

Register entry, as of 29 October 2026

Listed for sale

Record ID 5aa1696933ff

# 2019 Hyundai Tucson Value, SEL, Sport, Limited, Ultimate, Night

2.0 L, 4 cylinders · 4x2 · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**KM8 J33A4 6 K U 976127**

WMI 1-3

Hyundai Motor Co

DESCRIPTOR 4-8

Tucson · 2.0 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                                             |        |                    |
|------------|---------------------------------------------|--------|--------------------|
| Model year | 2019                                        | Engine | 2.0 L, 4 cylinders |
| Make       | Hyundai                                     | Fuel   | Gasoline           |
| Model      | Tucson                                      | Drive  | 4x2                |
| Trim       | Value, SEL, Sport, Limited, Ultimate, Night | Maker  | HYUNDAI MOTOR CO   |
| Body       | Sport Utility Vehicle                       | Plant  | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/hyundai/tucson/2019](https://cardog.app/tools/recalls/hyundai/tucson/2019)

## 6 recalls listed by Transport Canada for this model year

### Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

### Engine

2022244 8 May 2022

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. This is an expansion of R0180 (Transport Canada #2021-575). Any vehicle that received a software update under campaign R0180 does not require this update. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.



## Engine

2021575 17 Sep 2021

This recall was replaced by Transport Canada Recall No. 2022-244. Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. All vehicles previously included in TC # 2021-034 are now part of this new campaign. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

## Brakes

2020648 30 Dec 2020

Issue: On certain vehicles, a problem in the control module for the antilock brake system (ABS) could cause it to short circuit. Note: This is an expansion of recall 2020-431. This recall does not affect vehicles equipped with Smart Cruise Control(SCC). Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to revise the ABS fuse wiring and update the ABS control module, if necessary. Hyundai recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.

## Brakes

2020431 13 Sep 2020

This recall was replaced by Transport Canada Recall No. 2020-648. Issue: On certain vehicles, the control module for the antilock brake system (ABS) could corrode internally and cause a short circuit. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners of this problem by mail. The corrective actions for this recall are still being finalized. Hyundai recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.

## Engine

2019640 16 Dec 2019

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This affects Sonata and Santa Fe Sport equipped with a 2.4 L GDI or 2.0 L Turbo GDI engine, as well as Tucson equipped with a 2.4 L GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of an accident. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Vehicles previously repaired under Product Improvement Campaign R0153 (TC # 2019-130) do not require this software update. Owners can find additional information at <a href="http://www.hyundaiengineinfo.ca">www.hyundaiengineinfo.ca</a>.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.


Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.

[www.hyundaicanada.com/en/owners-section/recalls](http://www.hyundaicanada.com/en/owners-section/recalls)

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

## §3 VALUE [4]

This car asks \$12,711<sup>[5]</sup>, \$2,787 under the median of \$15,498<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$9,988             |
| Middle half | \$12,999 – \$16,498 |
| Median ask  | \$15,498            |
| This car    | \$12,711            |

Same configuration · 21 live listings · as of 29 Oct 2026



OTHER 2019 HYUNDAI TUCSON LISTINGS <sup>[5]</sup>

|                              |          |
|------------------------------|----------|
| Blenheim, ON · 97,416 km     | \$17,520 |
| Toronto, ON · 48,893 km      | \$20,720 |
| Tillsonburg, ON · 122,604 km | \$15,593 |
| Montmagny, QC · 161,461 km   | \$12,949 |
| Saint John, NB · 117,920 km  | \$14,857 |
| Québec, QC · 91,522 km       | \$16,977 |

## §4 EVENTS

|             |                                                                                         |
|-------------|-----------------------------------------------------------------------------------------|
| 2019        | Model year 2019 <sup>[1]</sup><br>Assembly plant Ulsan, South Korea                     |
| 16 Dec 2019 | Transport Canada recall 2019640 <sup>[2]</sup><br>Issued for the model year · Engine    |
| 13 Sep 2020 | Transport Canada recall 2020431 <sup>[2]</sup><br>Issued for the model year · Brakes    |
| 30 Dec 2020 | Transport Canada recall 2020648 <sup>[2]</sup><br>Issued for the model year · Brakes    |
| 17 Sep 2021 | Transport Canada recall 2021575 <sup>[2]</sup><br>Issued for the model year · Engine    |
| 8 May 2022  | Transport Canada recall 2022244 <sup>[2]</sup><br>Issued for the model year · Engine    |
| 23 Sep 2024 | Transport Canada recall 2024552 <sup>[2]</sup><br>Issued for the model year · Label     |
| 26 Oct 2026 | Listed for sale, Moncton, NB <sup>[5]</sup><br>Rallye Motors Chrysler · asking \$12,711 |
| 28 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$12,711                                  |

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

- |                                                                     |                                                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 21 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 29 Oct 2026                     |
| [3] NHTSA recall records (United States), listed for the model year |                                                                                  |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

