

Register entry, as of 28 October 2026

Listed for sale

Record ID bc90cb9bd656

# 2019 Hyundai Veloster Turbo R-Spec, Turbo and Turbo Ultimate

1.6 L, 4 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**KMH TH6AB 9 K U 012437**

WMI 1-3

Hyundai Motor Co

DESCRIPTOR 4-8

Veloster · 1.6 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                                        |        |                    |
|------------|----------------------------------------|--------|--------------------|
| Model year | 2019                                   | Engine | 1.6 L, 4 cylinders |
| Make       | Hyundai                                | Fuel   | Gasoline           |
| Model      | Veloster                               | Drive  | Not in the decode  |
| Trim       | Turbo R-Spec, Turbo and Turbo Ultimate | Maker  | HYUNDAI MOTOR CO   |
| Body       | Coupe                                  | Plant  | Ulsan, South Korea |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/hyundai/veloster/2019](https://cardog.app/tools/recalls/hyundai/veloster/2019)

## 4 recalls listed by Transport Canada for this model year

### Fuel system

2024403 11 Jul 2024

Issue: On certain vehicles, the high-pressure fuel pump could fail. If this happens, the engine may run rough and the check engine light may turn on. This could also cause a sudden loss of engine power while driving. Note: For the Elantra, Kona and Veloster models, this recall only affects the N performance versions. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to update the engine control module software. The high-pressure fuel pump will be replaced, if necessary.

### Engine

2021252 28 Apr 2021

Issue: On certain vehicles, the engine's piston oil rings may be defective. This can cause engine wear that can lead to increased oil consumption. Eventually, this can create abnormal engine noise and the oil pressure warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This only affects vehicles equipped with a 2.0 L Nu MPI engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the engine. The engine will be replaced, if necessary. Hyundai is also developing a Piston-ring Noise Sensing System (PNSS) software update to be installed when available; it will alert the driver of potential damage before an engine failure occurs.



## Engine

2019640 16 Dec 2019

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This affects Sonata and Santa Fe Sport equipped with a 2.4 L GDI or 2.0 L Turbo GDI engine, as well as Tucson equipped with a 2.4 L GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of an accident. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Vehicles previously repaired under Product Improvement Campaign R0153 (TC # 2019-130) do not require this software update. Owners can find additional information at <a href="http://www.hyundaiengineinfo.ca">www.hyundaiengineinfo.ca</a>.

## Structure

2019208 26 Apr 2019

Issue: On certain cars, the driver's door could open in a side impact crash. Safety Risk: A door that opens in a crash could create a risk of being ejected from the car and create an increased risk of injury. Corrective Actions: Hyundai will notify owners by mail and instruct them to take their vehicle to a dealer to replace the door latch assembly.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.

Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.

[www.hyundaicanada.com/en/owners-section/recalls](http://www.hyundaicanada.com/en/owners-section/recalls)

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

§3 VALUE <sup>[4]</sup>

This car asks \$14,698<sup>[5]</sup>, \$646 under the median of \$15,344<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$10,999            |
| Middle half | \$13,791 – \$16,244 |
| Median ask  | \$15,344            |
| This car    | \$14,698            |

Same configuration · 8 live listings · as of 28 Oct 2026

OTHER 2019 HYUNDAI VELOSTER LISTINGS <sup>[5]</sup>

|                                 |          |
|---------------------------------|----------|
| Thetford Mines, QC · 102,005 km | \$14,989 |
| Petawawa, ON · 57,433 km        | \$15,187 |
| Toronto, ON · 45,000 km         | \$18,770 |
| Kingston, ON · 145,838 km       | \$16,990 |
| Calgary, AB · 149,180 km        | \$14,391 |
| Brantford, ON · 92,232 km       | \$22,577 |

## §4 EVENTS

2019 Model year 2019<sup>[1]</sup>  
Assembly plant Ulsan, South Korea

26 Apr 2019 Transport Canada recall 2019208<sup>[2]</sup>  
Issued for the model year · Structure

16 Dec 2019 Transport Canada recall 2019640<sup>[2]</sup>  
Issued for the model year · Engine



|             |                                                                                            |
|-------------|--------------------------------------------------------------------------------------------|
| 28 Apr 2021 | Transport Canada recall 2021252 <sup>[2]</sup><br>Issued for the model year · Engine       |
| 11 Jul 2024 | Transport Canada recall 2024403 <sup>[2]</sup><br>Issued for the model year · Fuel system  |
| 26 Oct 2026 | Listed for sale, Prescott, ON <sup>[5]</sup><br>Riverside Buick GMC Ltd. · asking \$14,698 |
| 27 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$14,698                                     |

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

- |                                                                     |                                                                                 |
|---------------------------------------------------------------------|---------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 8 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                    |
| [3] NHTSA recall records (United States), listed for the model year |                                                                                 |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

