

# 2019 Volvo XC60 Inscription

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER <sup>[1]</sup>**LYV A22RL X K B 367744**

WMI 1-3

Daqing Volvo Car Manufac...

DESCRIPTOR 4-8

XC60 · 2.0 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

China

SERIAL 12-17

Build sequence

§1 IDENTITY <sup>[1]</sup>

|            |                       |        |                                       |
|------------|-----------------------|--------|---------------------------------------|
| Model year | 2019                  | Engine | 2.0 L, 4 cylinders                    |
| Make       | Volvo                 | Fuel   | Gasoline                              |
| Model      | XC60                  | Drive  | AWD                                   |
| Trim       | Inscription           | Maker  | DAQING VOLVO CAR MANUFACTURING CO LTD |
| Body       | Sport Utility Vehicle | Plant  | China                                 |

§2 OBLIGATIONS <sup>[2]</sup>[cardog.app/tools/recalls/volvo/xc60/2019](https://cardog.app/tools/recalls/volvo/xc60/2019)

## 6 recalls listed by Transport Canada for this model year

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |         |             |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-------------|
| Visual system                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 2022595 | 20 Oct 2022 |
| <p>Issue: On certain vehicles, a software problem could cause the top-view camera to display instead of the rearview camera image when you are reversing. Canadian regulations require the rearview image to display when reversing. Note: This recall only affects vehicles equipped with a 360-degree park assist camera. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volvo will notify owners in writing and send a wireless over-the-air update to each vehicle. If the update cannot be completed successfully, or for vehicles without over-the-air (OTA) update capability, Volvo will instruct you to schedule an appointment to have the update performed by a dealer.</p> |         |             |
| Electrical                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | 2021345 | 2 Jun 2021  |
| <p>Issue: On certain vehicles, the fuse for the low-pressure fuel pump may be too small. As a result, the fuse could blow and the engine could stall while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Action: Volvo will contact owners by mail and instruct you to take your vehicle to a dealer to replace the 15 A fuse for the low-pressure fuel pump with a 20 A fuse.</p>                                                                                                                                                                                                                                                                                                                                                                                                     |         |             |
| Visual system                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 2020390 | 25 Aug 2020 |
| <p>Issue: On certain vehicles, the nuts that attach the windshield wiper arms may not have been tightened properly. This could cause the wipers to slip and not clear the windshield properly. Safety Risk: Windshield wipers that do not work properly could affect a driver's visibility. This could increase the risk of a crash. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to tighten the nuts on the windshield wiper arms.</p>                                                                                                                                                                                                                                                                                                                                           |         |             |



**Brakes**

2020099 13 Mar 2020

Issue: On certain vehicles, the automatic emergency braking system (AEB) may not apply the brakes automatically when it detects a possible collision. In addition, the system may not warn of a potential crash with a non-moving vehicle or object. Note: The regular brake system and all other functions in the vehicle are not affected by this problem. Safety Risk: The AEB system may not provide driver warnings and apply the brakes automatically to help avoid a crash. Corrective Actions: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to update the vehicle software.

**Structure**

2019030 21 Jan 2019

Issue: On certain vehicles equipped with a power operated tailgate, the tailgate lifting arms could freeze and fail. This could create noise and cause the tailgate to stop working. It could also cause the tailgate lifting arms to separate. Safety Risk: If the tailgate arms separate, a spring may be projected rearward and create a risk of injury. Corrective Action: The company will notify owners by mail. Owners will be advised to take their vehicle to a dealer for replacement of the tailgate lifting arms.

**Accessories**

2018618 9 Nov 2018

On certain vehicles, the Telematics and Driver Support Systems may not function as designed due to a software error. In the event of a crash, this could mean that the Emergency Assist system would not alert Volvo and provide the GPS coordinates of the vehicle. This could create a risk of no response from emergency services. Correction: Dealers will update vehicle software.

Listed for the model year, not checked against your VIN. Volvo confirms which apply.


Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.

[www.volvocars.com/en-ca/l/recall-information/](http://www.volvocars.com/en-ca/l/recall-information/)

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

**§3 VALUE** <sup>[4]</sup>

This car asks \$23,595<sup>[5]</sup>, \$1,365 under the median of \$24,960<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$15,900            |
| Middle half | \$20,915 – \$28,006 |
| Median ask  | \$24,960            |
| This car    | \$23,595            |

Same model year · 22 live listings · as of 28 Oct 2026

**OTHER 2019 VOLVO XC60 LISTINGS** <sup>[5]</sup>

|                                |          |
|--------------------------------|----------|
| Saint-Laurent, QC · 146,795 km | \$17,995 |
| Surrey, BC · 50,000 km         | \$29,869 |
| Komoka, ON · 81,258 km         | \$29,995 |
| Lévis, QC · 131,600 km         | \$20,888 |
| Montreal, QC · 179,980 km      | \$15,900 |
| Quebec, QC · 107,000 km        | \$20,995 |

**§4 EVENTS**

2019      Model year 2019<sup>[1]</sup>  
             Assembly plant China



|             |                                                                                             |
|-------------|---------------------------------------------------------------------------------------------|
| 9 Nov 2018  | Transport Canada recall 2018618 <sup>[2]</sup><br>Issued for the model year · Accessories   |
| 21 Jan 2019 | Transport Canada recall 2019030 <sup>[2]</sup><br>Issued for the model year · Structure     |
| 13 Mar 2020 | Transport Canada recall 2020099 <sup>[2]</sup><br>Issued for the model year · Brakes        |
| 25 Aug 2020 | Transport Canada recall 2020390 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 2 Jun 2021  | Transport Canada recall 2021345 <sup>[2]</sup><br>Issued for the model year · Electrical    |
| 20 Oct 2022 | Transport Canada recall 2022595 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 25 Oct 2026 | Listed for sale, Milton, ON <sup>[5]</sup><br>Auto Moto of Ontario · asking \$23,595        |
| 28 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$23,595                                      |

## §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.

## SOURCES

- |                                                                     |                                                                               |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 22 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                  |
| [3] NHTSA recall records (United States), listed for the model year |                                                                               |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

