

2019 Land Rover Range Rover Supercharged LWB

5.0 L, 8 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SAL **GS5RE** **1** **K** **A** **548938**

WMI 1-3

Jaguar Land Rover Limited

DESCRIPTOR 4-8

Range Rover · 5.0 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Solihull

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	5.0 L, 8 cylinders
Make	Land Rover	Fuel	Gasoline
Model	Range Rover	Drive	AWD
Trim	Supercharged LWB	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Solihull, England

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover/2019

4 recalls listed by Transport Canada for this model year

Visual system

2024017 18 Jan 2024

For Ranger Rover Sport models, this recall was replaced by Transport Canada recall no. 2024-289. Issue: On certain vehicles, water could leak into the rearview camera and cause the rearview camera image not to display correctly. Note: This recall only affects vehicles equipped with a surround camera system. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to inspect the rearview camera and install a new seal. The dealer will replace the rearview camera, if necessary.

Engine

2023189 30 Mar 2023

Issue: On certain vehicles, the water pump drive belt could become damaged and detach. As a result, the engine could overheat and cause the coolant elbow to rupture. If this happens, coolant could leak onto the turbocharger heatshield. Note: This recall only affects plug-in hybrid (PHEV) models. Safety Risk: A coolant leak onto the turbocharger heatshield may lead to a fire in the engine bay. Corrective Action: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealership to replace the engine coolant elbow and turbocharger feed coolant pipe.



Lights and instruments

2021102 25 Feb 2021

Issue: On certain vehicles, when the Automatic High Beam (AHB) system is turned on, the AHB tell-tale indicator on the instrument panel may not turn on. This could lead you to drive without knowing that high beam lights can turn on automatically. Canadian regulations require a tell-tale indicator to turn on when the automatic high beams are activated. Safety Risk: A driver that does not know that the high beam lights are turned on could create glare for other drivers and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealer to update vehicle software.

Engine

2019029 17 Jan 2019

Issue: On certain vehicles, the engine crankshaft pulley bolt may have been manufactured improperly. This could cause it to crack and fail. If this happens, the crankshaft could break and cause a sudden engine failure. A driver may hear loud noises and see warning lights on the dash immediately before the engine fails. Safety Risk: An engine failure could increase the risk of a crash. Additionally, a loose pulley could separate from the engine and cause damage. If it separates from the vehicle, it could become a hazard for bystanders or other drivers. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to an authorized repair facility to have the crankshaft pulley bolt replaced with a new one.

Listed for the model year, not checked against your VIN. Land Rover confirms which apply.

Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.

www.landrover.ca/en/ownership/vin-recall.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$42,488^[5], the median^[4].



Lowest ask	\$32,430
Middle half	\$37,934 – \$47,495
Median ask	\$42,488
This car	\$42,488

Same model year · 19 live listings · as of 27 Oct 2026

OTHER 2019 LAND ROVER RANGE ROVER LISTINGS [5]

Toronto, ON · 89,085 km	\$47,995
Toronto, ON · 89,085 km	\$47,995
Ajax, ON · 100,311 km	\$39,987
Saskatoon, SK · 92,668 km	\$52,995
Richmond, BC · 80,964 km	\$45,995
Richmond, BC · 70,362 km	\$65,995

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Solihull, England
17 Jan 2019	Transport Canada recall 2019029 ^[2] Issued for the model year · Engine



25 Feb 2021	Transport Canada recall 2021102 ^[2] Issued for the model year · Lights and instruments
30 Mar 2023	Transport Canada recall 2023189 ^[2] Issued for the model year · Engine
18 Jan 2024	Transport Canada recall 2024017 ^[2] Issued for the model year · Visual system
24 Oct 2026	Listed for sale, Brampton, ON ^[5] Performance Honda · asking \$42,488
26 Oct 2026	Listing last updated ^[5] asking \$42,488

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 19 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

