

Register entry, as of 28 October 2026

Listed for sale

Record ID 1c5859f28271

2006 Land Rover Range Rover Sport HSE

4.4 L, 8 cylinders · Sport Utility Vehicle

VEHICLE IDENTIFICATION NUMBER [1]

SAL **SF254** **5** **6** **A** **923701**

WMI 1-3

Jaguar Land Rover Limited

DESCRIPTOR 4-8

Range Rover Sport · 4.4 L

CHECK 9

Computes

YEAR 10

2006

PLANT 11

Solihull

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2006	Engine	4.4 L, 8 cylinders
Make	Land Rover	Fuel	Not in the decode
Model	Range Rover Sport	Drive	Not in the decode
Trim	HSE	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Solihull, England

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover-sport/2006

5 recalls listed by Transport Canada for this model year

Airbag 2008193 4 Jun 2008

On certain vehicles, the wiring that connects the steering column rotary coupler (clockspring) to the driver's airbag module may fracture as a result of relative motion between the clockspring and the steering wheel hub. This may result in the deployment of only one stage of the dual stage airbag during a vehicle crash of sufficient severity, or cause the airbag to not deploy at all. Should the airbag module fail to deploy in the intended manner, it could increase the driver's risk of injury or death. Correction: Dealers will insert alignment spacers into specific areas of the steering column.

Brakes 2006105 4 May 2006

On certain vehicles equipped with 19 inch wheels, when the steering is on full left lock and the suspension is moving towards full compression, the left front brake hose, ABS wheel speed sensor lead, and, brake pad wear warning sensor lead, can catch on the wheel balance weight as the wheel rotates. This may lead to warnings of premature brake pad wear, warnings of ABS failure, or extended brake pedal travel and loss of one of the hydraulic service braking system circuits, which could result in extended stopping distances and a vehicle crash. Correction: Dealers will inspect the left front brake pipe assembly and replace if required. All clip-on wheel weights will be replaced with stick-on weights. Additionally, an owners handbook supplement will be produced stating the requirement to use stick-on wheel weights should future wheel balancing be required.

Electrical 2006083 19 Apr 2006

Certain vehicles do not comply with the requirements of CMVSS 114. When the ignition is switched off, after a period of time, it is possible to remove the ignition key when the transmission shift lever is not in Park. This could permit an unexpected vehicle roll away which could result in personal injury. Correction: Dealers will reprogram the Driveline Control Unit.



Powertrain

2005336 31 Oct 2005

Certain vehicles may have an incorrectly manufactured guide plate which could hinder the function of the transmission parking pawl. Consequently, PARK may not engage when the lever in the vehicle is moved to PARK and all indicators show PARK position is achieved. If the vehicle was parked on an incline of sufficient grade, and the parking brake was not engaged, the vehicle could roll away. Correction: Dealers will replace the parking pawl guide plate.

Seats and restraints

2005335 31 Oct 2005

Certain vehicles may have been manufactured with a seat belt mounting buckle whose tensile strength is below the required standard. In the event of a crash, where the left hand second row seat belt is being used, the buckle may not be fully retained. Correction: Land Rover has corrected all affected vehicles prior to distribution to dealers.

Listed for the model year, not checked against your VIN. Land Rover confirms which apply.


Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.

www.landrover.ca/en/ownership/vin-recall.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$2,495^[5], the median^[4].



Lowest ask	\$2,495
Middle half	\$2,495 – \$2,495
Median ask	\$2,495
This car	\$2,495

Same model year · 1 live listings · as of 28 Oct 2026

§4 EVENTS

2006

Model year 2006^[1]

Assembly plant Solihull, England

31 Oct 2005

Transport Canada recall 2005336^[2]

Issued for the model year · Powertrain

31 Oct 2005

Transport Canada recall 2005335^[2]

Issued for the model year · Seats and restraints

19 Apr 2006

Transport Canada recall 2006083^[2]

Issued for the model year · Electrical

4 May 2006

Transport Canada recall 2006105^[2]

Issued for the model year · Brakes

4 Jun 2008

Transport Canada recall 2008193^[2]

Issued for the model year · Airbag

25 Oct 2026

Listed for sale, London, ON^[5]

Tiger Auto Sales Ltd. · asking \$2,495



28 Oct 2026 Listing last updated^[5]
asking \$2,495

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

