

Register entry, as of 28 October 2026

Listed for sale

Record ID aa6b84d504ad

2011 Lotus Elise

4 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]**SCC** **LHCPC** **0** **B** **H** **A10797**

WMI 1-3

Lotus Cars Limited

DESCRIPTOR 4-8

Elise · 4 cylinders

CHECK 9

Computes

YEAR 10

2011

PLANT 11

United Kingdom

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2011	Engine	4 cylinders
Make	Lotus	Fuel	Gasoline
Model	Elise	Drive	Not in the decode
Trim	Not in the decode	Maker	LOTUS CARS LIMITED
Body	Convertible	Plant	United Kingdom

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/lotus/elise/2011

2 recalls listed by Transport Canada for this model year

Engine 2014191 27 May 2014

On certain vehicles, the engine oil cooler lines could fail, causing an oil leak. Oil may contact a hot engine or exhaust component, which could result in a fire. Oil may also be sprayed onto the tires and/or brakes, which could adversely affect vehicles stability. As well, engine oil spilt on the roadway could endanger other road users by making the roadway unexpectedly slippery. These issues could result in property damage and/or personal injury. Correction: Dealers will repair or replace the engine oil cooler lines. Note: This is an expansion of recalls 2011-390 and 2013-039 for vehicles not included in previous campaigns.

Lights and instruments 2011395 8 Nov 2011

Certain vehicles may have been inadvertently equipped with incorrect turn signal modules during vehicle assembly. This could cause the LED turn signal lamps to flash at an erratic frequency when the hazard warning switch is depressed. In addition, in the event that either a front or rear turn signal lamp fails to illuminate or does not flash at the correct frequency when operated, the remaining functioning signal lamps on that vehicle's side, as well as the instrument turn telltale, will not flash at an increased rate as intended. As a result, the driver will not be visually alerted to the fact that a turn signal lamp is not operating correctly. As such, the driver's intentions to turn may not be conveyed clearly to other road users, increasing the risk of a crash causing property damage and/or personal injury. Correction: Dealers will replace the turn signal modules.

Listed for the model year, not checked against your VIN. Lotus confirms which apply.
No online lookup from Lotus · call a Lotus dealer with your VIN.

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$129,950^[5], the median^[4].



Lowest ask	\$129,950
Middle half	\$129,950 – \$129,950
Median ask	\$129,950
This car	\$129,950

Same model year · 1 live listings · as of 28 Oct 2026

§4 EVENTS

2011	Model year 2011 ^[1] Assembly plant United Kingdom
8 Nov 2011	Transport Canada recall 2011395 ^[2] Issued for the model year · Lights and instruments
27 May 2014	Transport Canada recall 2014191 ^[2] Issued for the model year · Engine
11 Mar 2026	Listed for sale, Oakville, ON ^[5] Shift Motors · asking \$129,950
28 Oct 2026	Listing last updated ^[5] asking \$129,950

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 28 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

