

Register entry, as of 27 October 2026

Listed for sale

Record ID 793b4cfe1411

2023 Aston Martin DBX DBX707

4.0 L, 8 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SD7 VUJBW 9 P T V06131

WMI 1-3

Aston Martin Lagonda Limi...

DESCRIPTOR 4-8

DBX · 4.0 L

CHECK 9

Computes

YEAR 10

2023

PLANT 11

St Athan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	4.0 L, 8 cylinders
Make	Aston Martin	Fuel	Gasoline
Model	DBX	Drive	AWD
Trim	DBX707	Maker	ASTON MARTIN LAGONDA LIMITED
Body	Sport Utility Vehicle	Plant	St Athan, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/aston-martin/dbx/2023

4 recalls listed by Transport Canada for this model year

Suspension

2026156 31 Mar 2026

Issue: On certain vehicles, the pin(s) for the torque reaction link(s) may not have been manufactured correctly. As a result, the pin(s) could slide out of the rear lower suspension arm(s) and cause them to crack or break. If this happens, there could be a loss of vehicle control and/or damage to other suspension components and rear brakes. Safety Risk: A loss of vehicle control could increase the risk of a crash. Damaged brakes could cause extended stopping distances and increase the risk of a crash. Corrective Actions: Aston Martin will notify owners by mail and advise you to take your vehicle to a dealership to replace the rear torque reaction link bolts. The dealer will also inspect and replace any damaged parts, as necessary.

Engine

2024575 1 Oct 2024

Issue: On certain vehicles, the engine oil cooler hoses may not have been manufactured properly. As a result, the hoses could fail and leak oil. This could cause a loss of power to the wheels and/or an engine fire. Note: This recall is an expansion of Transport Canada recall no. 2024-218. For the DBX model, certain vehicles repaired under that recall also require this repair. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. An engine fire can create a risk of injury. Corrective Actions: Aston Martin will notify owners by mail and advise you to take your vehicle to a dealership to replace the engine oil cooler hoses.

Electrical

2024219 11 Apr 2024

Issue: On certain vehicles, the power cable(s) in the fuse box may not have been tightened properly. As a result, the cable(s) could become loose and overheat. If this happens, the engine could stall and the headlamps and/or the power steering assist could stop working. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Wiring that overheats could create the risk of a fire. A loss of power steering assist can cause a sudden increase in steering effort. Headlamps that stop working could reduce visibility and increase the risk of a crash. Corrective Actions: Aston Martin will notify owners by mail and advise you to take your vehicle to a dealership to replace the fasteners for the power cables. The dealer will also inspect and, if necessary, replace any damaged parts.



Engine

2024218 11 Apr 2024

Issue: On certain vehicles, the engine oil cooler hoses may not have been manufactured properly. As a result, the hoses could fail and leak oil. This could cause a loss of power to the wheels and/or an engine fire. Safety Risk: A sudden loss power to the wheels could increase the risk of a crash. An engine fire can create a risk of injury. Corrective Actions: Aston Martin will notify owners by mail and advise you to take your vehicle to a dealership to replace the engine oil cooler hoses.

Listed for the model year, not checked against your VIN. Aston Martin confirms which apply.
No online lookup from Aston Martin · call a Aston Martin dealer with your VIN.

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$208,888^[5], \$30,500 under the median of \$239,388^[4].



Lowest ask	\$208,888
Middle half	\$224,138 – \$254,639
Median ask	\$239,388
This car	\$208,888

Same model year · 2 live listings · as of 27 Oct 2026

OTHER 2023 ASTON MARTIN DBX LISTINGS [5]

Terrebonne, QC · 13,819 km \$269,889

§4 EVENTS

2023	Model year 2023 ^[1] Assembly plant St Athan, United Kingdom
11 Apr 2024	Transport Canada recall 2024219 ^[2] Issued for the model year · Electrical
11 Apr 2024	Transport Canada recall 2024218 ^[2] Issued for the model year · Engine
1 Oct 2024	Transport Canada recall 2024575 ^[2] Issued for the model year · Engine
31 Mar 2026	Transport Canada recall 2026156 ^[2] Issued for the model year · Suspension
14 Oct 2026	Listed for sale, Montréal, QC ^[5] Rolls-Royce Motor Cars Quebec · asking \$208,888
26 Oct 2026	Listing last updated ^[5] asking \$208,888



§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 2 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

