

Register entry, as of 28 October 2026

Listed for sale

Record ID 5dd8916a6a88

2001 Mercedes-Benz CL-Class CL600

6.0 L, 12 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDB PJ78J 1 1 A 009320

WMI 1-3

Mercedes-Benz Cars

DESCRIPTOR 4-8

CL-Class · 6.0 L

CHECK 9

Computes

YEAR 10

2001

PLANT 11

Germany

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2001	Engine	6.0 L, 12 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	CL-Class	Drive	Not in the decode
Trim	CL600	Maker	Mercedes-Benz Cars
Body	Coupe	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/cl-class/2001

5 recalls listed by Transport Canada for this model year

Other

2008290 15 Aug 2008

Certain vehicles equipped with Active Body Control (ABC) the sensors on the front struts may not operate within tolerances. As such, the sensor signal may not be accurately transmitted to the Electronic Control Unit (ECU). A variation in the transmitted values can result in one front strut adjusting to a value while the other does not adjust and presenting the driver with an uneven front suspension. This situation could have an effect on the vehicle's directional stability, possibly resulting in a vehicle crash with injuries or death. Correction: Dealers will inspect and replace affected AZ-sensors

Electrical

2006031 7 Feb 2006

Certain vehicles may experience instrument cluster backlighting malfunction. There are three distinct failure modes. (1) Vehicles built between 06/2000 and 11/2000 may contain a defective transformer that could cause an electrical short. (2) Vehicles built from 01/2002 to 04/2002 could have incorrect dielectric layers inside a capacitor that could lead to fluctuating current levels. (3) Vehicles built between 05/2004 and 09/2004 may have incorrect light emitting diodes (LEDs). Correction: Dealers will replace the instrument cluster module.

Electrical

2004154 6 May 2004

On certain vehicles, the size of the electric conductor on the blower motor fuse holder may be below appropriate tolerances. Consequently, the electric conductor of the blower motor fuse holder may dissipate more heat than the plastic fuse holder was designed to withstand, which would result in partial melting of the blower motor fuse holder and disabling of the blower motor. Correction: Dealers will replace the blower motor fuse holder.



Brakes

2004153 6 May 2004

On certain vehicles equipped with a 12-cylinder engine, corrosion may occur in the inner steel portions of the Active Body Control's high pressure distribution hose due to extensive exposure to humidity. This may result in ABC hydraulic fluid leakage near the catalytic converter which could cause a fire. Correction: Dealers will install a corrosion resistant ABC high-pressure distribution hose.

Other

2001064 14 Mar 2001

Certain vehicles are equipped with a heated windshield washer bottle which may be defective. The sheathing material on the electrical connection of the hose may overheat and cause surrounding plastic and insulation to melt. This could eventually result in a an engine compartment fire. Correction: Heated windshield washer bottle hose will be replaced.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$16,888^[5], the median^[4].



Lowest ask	\$16,888
Middle half	\$16,888 – \$16,888
Median ask	\$16,888
This car	\$16,888

Same model year · 1 live listings · as of 28 Oct 2026

§4 EVENTS

2001	Model year 2001 ^[1] Assembly plant Germany
14 Mar 2001	Transport Canada recall 2001064 ^[2] Issued for the model year · Other
6 May 2004	Transport Canada recall 2004154 ^[2] Issued for the model year · Electrical
6 May 2004	Transport Canada recall 2004153 ^[2] Issued for the model year · Brakes
7 Feb 2006	Transport Canada recall 2006031 ^[2] Issued for the model year · Electrical
15 Aug 2008	Transport Canada recall 2008290 ^[2] Issued for the model year · Other
20 Oct 2026	Listed for sale, Surrey, BC ^[5] Nexus Auto Group · asking \$16,888



28 Oct 2026 Listing last updated^[5]
asking \$16,888

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

