

Register entry, as of 28 October 2026

Listed for sale

Record ID 5175bc8ddcb9

2006 Mercedes-Benz CLK-Class CLK350

3.5 L, 6 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDB TK56G 5 6 T 072598

WMI 1-3

Mercedes-Benz Cars

DESCRIPTOR 4-8

CLK-Class · 3.5 L

CHECK 9

Computes

YEAR 10

2006

PLANT 11

Ostabruck

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2006	Engine	3.5 L, 6 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	CLK-Class	Drive	Not in the decode
Trim	CLK350	Maker	Mercedes-Benz Cars
Body	Convertible	Plant	Ostabruck, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/clk-class/2006

4 recalls listed by Transport Canada for this model year

Structure 2022740 22 Dec 2022

Issue: On certain vehicles, the sunroof glass may not be properly attached to the sliding roof frame. Over time, the glass can become loose and could separate from the vehicle. Note: Vehicles that were inspected under Transport Canada recalls 2019-668 and 2021-478 also require this inspection. Safety Risk: A sunroof that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the bonding of the sunroof glass. Dealers will replace the sliding roof, if necessary.

Structure 2021478 23 Jul 2021

Issue: This recall is for certain vehicles inspected under Mercedes-Benz recall 7891003 (Transport Canada recall 2019-668) that require a second inspection. On certain vehicles, the sunroof glass may not be properly attached to the sliding roof frame. Over time, the glass can become loose and could separate from the vehicle. Note: This recall affects 2006 and 2007 models originally equipped with a sunroof. Additionally, some 2001-2011 models may have had an affected sunroof installed during a repair. Safety Risk: A sunroof that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the bonding of the sunroof glass. Dealers will replace the sliding roof, if necessary.

Structure 2019668 23 Dec 2019

Issue: On certain vehicles, the sunroof glass may not be properly attached to the sliding roof frame. Over time, the glass can become loose and could separate from the vehicle. Note: This recall affects 2006 and 2007 models originally equipped with a sunroof. Additionally, some 2001-2011 models may have had an affected sunroof installed during a repair. Safety Risk: A sunroof that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the bonding of the sunroof glass. Dealers will replace the sliding roof, if necessary.



Other

2008242 9 Jul 2008

Certain vehicles may have been programmed with incorrect software calibration data during the manufacturing process. This could affect various functions such as: The electric fuel pump may not receive a signal which, in case of a crash, may prevent the fuel pump from disconnecting as designed; The maximum speed limiter may not be activated; The fuel gauge readings may be incorrect; A stuck fuel-level sensor may not be displayed in the instrument cluster; The speedometer may be out of tolerance which, as a result, may indicate inaccurate vehicle speed; The On-Board Diagnostic (OBD) system may reduce the emission level applicable to the vehicle, causing the Check Engine Light to illuminate incorrectly. Correction: Dealers will reprogram the electronic control module.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.

www.mercedes-benz.ca/en/recalls

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$7,499^[5], \$2,401 under the median of \$9,900^[4].



Lowest ask	\$7,499
Middle half	\$8,700 – \$10,450
Median ask	\$9,900
This car	\$7,499

Same model year · 3 live listings · as of 28 Oct 2026

§4 EVENTS

2006	Model year 2006 ^[1] Assembly plant Ostabruck, Germany
9 Jul 2008	Transport Canada recall 2008242 ^[2] Issued for the model year · Other
23 Dec 2019	Transport Canada recall 2019668 ^[2] Issued for the model year · Structure
23 Jul 2021	Transport Canada recall 2021478 ^[2] Issued for the model year · Structure
22 Dec 2022	Transport Canada recall 2022740 ^[2] Issued for the model year · Structure
25 Oct 2026	Listed for sale, Scarborough, ON ^[5] Why Buy New Motors · asking \$7,499
28 Oct 2026	Listing last updated ^[5] asking \$7,499



§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 3 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

