

Register entry, as of 29 October 2026

Listed for sale

Record ID bbe48b9bd400

2019 Mercedes-Benz SL-Class SL450

3.0 L, 6 cylinders · RWD · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDD JK6GA 0 K F 054498

WMI 1-3

Mercedes-Benz Cars

DESCRIPTOR 4-8

SL-Class · 3.0 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Germany

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.0 L, 6 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	SL-Class	Drive	RWD
Trim	SL450	Maker	Mercedes-Benz Cars
Body	Convertible	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/sl-class/2019

5 recalls listed by Transport Canada for this model year

Other

2022263 20 May 2022

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the SIM card for the communications module could disable itself. If this happens, the eCall system would not work properly when there is a crash or when the SOS button is pressed. Safety Risk: If the eCall system does not work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Electrical

2021064 12 Feb 2021

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the communications module may temporarily lose power during a crash. If this happens, the wrong vehicle location may be transmitted through the eCall system. This could cause emergency responders to be sent to the wrong location. Safety Risk: If the eCall system sends out the wrong location after a crash, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Accessories

2021041 1 Feb 2021

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to update the head unit software.



Suspension

2019540 28 Oct 2019

Issue: On certain vehicles, a faulty part could cause one of the mounts for rear axle carrier to detach. If this happens, the driver may notice a loud knocking sound from the rear of the vehicle. If the vehicle continues to be driven with this problem, over time the remaining mounting bolts may fail. This could cause the rear axle carrier to separate from the vehicle. Safety Risk: A rear axle carrier separation could affect vehicle control and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the mount for the rear axle carrier. If the left-front bolt connection is damaged, the vehicle will be bought back.

Airbag

2019385 7 Aug 2019

Issue: On certain vehicles, the passenger-front airbag may not meet manufacturer specifications. This could cause the airbag not to inflate properly in a crash. Safety Risk: An airbag that does not work properly could create an increased risk of injury in a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct them to take their vehicle to a dealer to replace the passenger-front airbag.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.

Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.

www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks \$58,888^[4], \$7,012 under the median of \$65,900^[3].



Lowest ask	\$58,888
Middle half	\$62,394 – \$81,948
Median ask	\$65,900
This car	\$58,888

Same model year · 3 live listings · as of 29 Oct 2026

OTHER 2019 MERCEDES-BENZ SL-CLASS LISTINGS [4]

Vaughan, ON · 41,119 km \$65,900

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Germany
7 Aug 2019	Transport Canada recall 2019385 ^[2] Issued for the model year · Airbag
28 Oct 2019	Transport Canada recall 2019540 ^[2] Issued for the model year · Suspension
1 Feb 2021	Transport Canada recall 2021041 ^[2] Issued for the model year · Accessories
12 Feb 2021	Transport Canada recall 2021064 ^[2] Issued for the model year · Electrical
20 May 2022	Transport Canada recall 2022263 ^[2] Issued for the model year · Other



15 Jul 2026 Listed for sale, St-Eustache, QC^[4]
Empire Auto · asking \$58,888

28 Oct 2026 Listing last updated^[4]
asking \$58,888

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- [1] Cardog identity register, decoded from the VIN
- [2] Transport Canada recall database, listed for the model year
- [3] Cardog market quote, same model year, 3 live listings, as of 29 Oct 2026
- [4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

