

Register entry, as of 29 October 2026

Listed for sale

Record ID 4432fda2b7cf

2015 Mercedes-Benz CLA-Class CLA250 4 MATIC

2.0 L, 4 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDD SJ4GB 1 F N 276323

WMI 1-3

Mercedes-Benz Cars

DESCRIPTOR 4-8

CLA-Class · 2.0 L

CHECK 9

Computes

YEAR 10

2015

PLANT 11

Kecskemet

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.0 L, 4 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	CLA-Class	Drive	AWD
Trim	CLA250 4 MATIC	Maker	Mercedes-Benz Cars
Body	Sedan	Plant	Kecskemet, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/cla-class/2015

9 recalls listed by Transport Canada for this model year

Structure

2023673 15 Dec 2023

Issue: On certain vehicles, the plastic panel located between the windshield and the panoramic sunroof may not have been attached correctly during a prior service repair. Over time, the panel could loosen and separate from the vehicle. Note: This is an expansion of Transport Canada recall 2021-170. Safety Risk: A panel that detaches from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the front roof panel.

Steering

2021507 11 Aug 2021

Issue: On certain vehicles, the power steering control unit may corrode. If this happens, moisture could enter the control unit and cause it to fail. This could cause a loss of power steering assist. Note: This is an expansion of Mercedes-Benz recall 4694202 (Transport Canada Recall No. 2020-617). This recall only affects vehicles that were originally sold or ever registered in areas of heavy road salt usage (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). Safety Risk: A loss of power steering assist would result in a sudden increase in steering effort, especially at low vehicle speeds. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the power steering control unit.

Structure

2021170 22 Mar 2021

Issue: On certain vehicles, the plastic panel located between the windshield and the panoramic sunroof may not have been attached correctly during a prior service repair. Over time, the panel could loosen and separate from the vehicle. Safety Risk: A panel that detaches from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front roof panel.



Steering

2020617 14 Dec 2020

Issue: On certain vehicles, the power steering control unit may corrode. If this happens, moisture could enter the control unit and cause it to fail. This could cause a loss of power steering assist. Note: This recall only affects vehicles that were originally sold or ever registered in areas of heavy road salt usage (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). Safety Risk: A loss of power steering assist would result in a sudden increase in steering effort, especially at low vehicle speeds. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the power steering control unit.

Airbag

2019632 13 Dec 2019

Issue: On certain vehicles, the occupant classification system (OCS) may not work properly. In some cases, this could cause the airbag system to turn off the passenger-front airbag, even if an adult is seated in the front passenger seat. Alternatively, the airbag may not be turned off when a child seat is installed in the front passenger seat. Safety Risk: An airbag that deploys in front of a child seat, or an airbag that doesn't properly deploy in front of a passenger could increase the risk of injury in a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front passenger seat cushion.

Airbag

2017490 10 Oct 2017

On certain vehicles, electrostatic discharge, when combined with a broken clock spring and insufficient grounding of the steering components, could lead to an inadvertent deployment of the driver's frontal airbag. Unintended airbag deployment, in a non-warranted (non-impact) situation, could startle the driver, which could result in a crash causing injury and/or property damage. In some instances, inadvertent deployment could cause minor injuries to vehicle occupants. Correction: Dealers will add sufficient grounding to the steering components. Note: A broken clock spring would result in a driver airbag warning message appearing in the instrument cluster, as well as a red airbag warning lamp illuminating.


3 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/cla-class/2015

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.

www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks \$19,494^[4], \$4,499 over the median of \$14,995^[3].



Lowest ask	\$8,950
Middle half	\$12,995 – \$14,999
Median ask	\$14,995
This car	\$19,494

Same configuration · 15 live listings · as of 29 Oct 2026

OTHER 2015 MERCEDES-BENZ CLA-CLASS LISTINGS [4]

Winnipeg, MB · 105,638 km	\$14,999
North York, ON · 161,447 km	\$9,800
North York, ON · 132,702 km	\$12,995
Toronto, ON · 162,938 km	\$12,995
Abbotsford, BC · 154,600 km	\$13,999
Mississauga, ON · 183,539 km	\$12,888



§4 EVENTS

2015	Model year 2015 ^[1] Assembly plant Kecskemet, Germany
13 Oct 2015	Transport Canada recall 2015463 ^[2] Issued for the model year · Engine
9 Feb 2017	Transport Canada recall 2017062 ^[2] Issued for the model year · Engine
15 Mar 2017	Transport Canada recall 2017145 ^[2] Issued for the model year · Airbag
10 Oct 2017	Transport Canada recall 2017490 ^[2] Issued for the model year · Airbag
13 Dec 2019	Transport Canada recall 2019632 ^[2] Issued for the model year · Airbag
14 Dec 2020	Transport Canada recall 2020617 ^[2] Issued for the model year · Steering
22 Mar 2021	Transport Canada recall 2021170 ^[2] Issued for the model year · Structure
11 Aug 2021	Transport Canada recall 2021507 ^[2] Issued for the model year · Steering
15 Dec 2023	Transport Canada recall 2023673 ^[2] Issued for the model year · Structure
24 Oct 2025	Listed for sale, Bécancour, QC ^[4] Gentilly Automobiles Ltd · asking \$19,494
28 Oct 2026	Listing last updated ^[4] asking \$19,494

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [3] Cardog market quote, same configuration, 15 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 29 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

