

Register entry, as of 29 October 2026

Listed for sale

Record ID a470f8849ddd

2011 Mercedes-Benz Sprinter

4x2 · Van · Diesel

VEHICLE IDENTIFICATION NUMBER ^[1]**WDZ** **BE8CC** **X** **B** **5** **545045**

WMI 1-3

Mercedes-Benz Usa, Llc (S...

DESCRIPTOR 4-8

Sprinter

CHECK 9

Computes

YEAR 10

2011

PLANT 11

Dusseldorf

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2011	Engine	Not in the decode
Make	Mercedes-Benz	Fuel	Diesel
Model	Sprinter	Drive	4x2
Trim	Not in the decode	Maker	MERCEDES-BENZ USA, LLC (SPRINTER)
Body	Van	Plant	Dusseldorf, Germany

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/mercedes-benz/sprinter/2011

8 recalls listed by Transport Canada for this model year

Airbag 2019455 4 Sep 2019

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the passenger-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Owners will be notified by mail and instructed to take their vehicle to a dealer to have the passenger-front airbag module replaced. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected. Additional note: This recall supersedes recall 2018-648.

Airbag 2019454 4 Sep 2019

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the driver-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Owners will be notified by mail and instructed to take their vehicle to a dealer to have the driver-front airbag module replaced. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected. Additional note: This recall supersedes recall 2016-159.



Airbag

2018648 26 Nov 2018

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag module. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected. Note: This recall is superseded by recall 2019455. Please see [recall 2019455](http://www.wapps.tc.gc.ca/Saf-Sec-Sur/7/VRDB-BDRV/search-recherche/detail.aspx?lang=eng&rn=2019455) for more information.

Airbag

2016159 13 Apr 2016

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will replace the front driver air bag module. Note: This recall is superseded by recall 2019454. Please see [recall 2019454](http://www.wapps.tc.gc.ca/Saf-Sec-Sur/7/VRDB-BDRV/search-recherche/detail.aspx?lang=eng&rn=2019454) for more information.

Seats and restraints

2011233 20 Jun 2011

On certain Sprinter 2500 vehicles, the bench-type seats (for rear occupants) may have been equipped with improperly manufactured ISOFIX anchorage brackets for child restraints. Failure of the child restraint anchorage to restrain the occupant as intended would increase the risk of personal injuries during a crash. Correction: Dealers will inspect and, if necessary, replace the seat bench assembly.

Suspension

2011232 20 Jun 2011

On certain Sprinter 3500 vehicles, the rear suspension springs may have been manufactured incorrectly and could fail. Rear suspension failure could result in a loss of vehicle control and a crash causing property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, replace the rear suspension springs.

2 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/sprinter/2011

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.

www.mercedes-benz.ca/en/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$34,999^[5], the median^[4].



Lowest ask	\$17,995
Middle half	\$26,497 – \$37,499
Median ask	\$34,999
This car	\$34,999

Same model year · 3 live listings · as of 29 Oct 2026

OTHER 2011 MERCEDES-BENZ SPRINTER LISTINGS ^[5]

Mississauga, ON · 97,171 km	\$39,999
London, ON · 120,801 km	\$17,995



§4 EVENTS

2011	Model year 2011 ^[1] Assembly plant Dusseldorf, Germany
16 Dec 2010	Transport Canada recall 2010449 ^[2] Issued for the model year · Visual system
13 Apr 2011	Transport Canada recall 2011156 ^[2] Issued for the model year · Seats and restraints
20 Jun 2011	Transport Canada recall 2011233 ^[2] Issued for the model year · Seats and restraints
20 Jun 2011	Transport Canada recall 2011232 ^[2] Issued for the model year · Suspension
13 Apr 2016	Transport Canada recall 2016159 ^[2] Issued for the model year · Airbag
26 Nov 2018	Transport Canada recall 2018648 ^[2] Issued for the model year · Airbag
4 Sep 2019	Transport Canada recall 2019455 ^[2] Issued for the model year · Airbag
4 Sep 2019	Transport Canada recall 2019454 ^[2] Issued for the model year · Airbag
10 Sep 2026	Listed for sale, Toronto, ON ^[5] COLISEUM AUTO SALES · asking \$34,999
28 Oct 2026	Listing last updated ^[5] asking \$34,999

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 3 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

