

2010 Volkswagen Tiguan 4-Motion

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WVG BV7AX 3 A W 509220

WMI 1-3

Volkswagen Ag

DESCRIPTOR 4-8

Tiguan · 2.0 L

CHECK 9

Computes

YEAR 10

2010

PLANT 11

Wolfsburg

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Tiguan	Drive	AWD
Trim	4-Motion	Maker	VOLKSWAGEN AG
Body	Sport Utility Vehicle	Plant	Wolfsburg, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/tiguan/2010

4 recalls listed by Transport Canada for this model year

Airbag

2016064 9 Feb 2016

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will replace the front driver airbag inflator.

Note: This campaign only affects the Audi A5 and Audi S5 Cabriolet models.

Seats and restraints

2015344 31 Jul 2015

On certain vehicles, the steering wheel clock spring could become contaminated with long hair or long fibers which may cause a displacement of the internal guide loops. When the guide loops are dragged out of position, they may apply tension to the internal flat cable and cause it to tear. Should the cable tear, the electrical connection to the driver's front airbag may be lost, causing the airbag monitoring indicator light to illuminate. Failure of the driver's airbag to deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will install a cover of a different design to help prevent clock spring contamination caused by hair or other fibers. In instances where the vehicle has an airbag light on (and diagnosis confirms the steering wheel clock spring requires replacement), dealers will install a new steering wheel clock spring.

Fuel system

2014307 22 Jul 2014

On certain vehicles, deposits may collect on fuel pump connections and reduce fuel pump performance. This could cause the engine to stall, resulting in a loss of motive power and increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will update vehicle software to increase fuel pump pressure in order to prevent deposits from forming.



Electrical

2013403 13 Nov 2013

On certain vehicles, a fuse can overheat and damage the fuse box, causing a partial loss of exterior vehicle lighting. This could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will install a fuse of an updated design.

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.

www.vw.ca/en/owners-and-drivers/recalls.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$2,495^[5], \$4,405 under the median of \$6,900^[4].



Lowest ask	\$2,495
Middle half	\$4,722 – \$8,490
Median ask	\$6,900
This car	\$2,495

Same model year · 7 live listings · as of 28 Oct 2026

OTHER 2010 VOLKSWAGEN TIGUAN LISTINGS [5]

Kelowna, BC · 236,356 km	\$9,500
London, ON · 172,389 km	\$3,495
Kelowna, BC · 236,356 km	\$9,500
North York, ON · 88,512 km	\$8,980
Airdrie, AB · 220,165 km	\$6,900
Ontario, ON · 176,363 km	\$7,999

§4 EVENTS

2010	Model year 2010 ^[1] Assembly plant Wolfsburg, Germany
13 Nov 2013	Transport Canada recall 2013403 ^[2] Issued for the model year · Electrical
22 Jul 2014	Transport Canada recall 2014307 ^[2] Issued for the model year · Fuel system
31 Jul 2015	Transport Canada recall 2015344 ^[2] Issued for the model year · Seats and restraints
9 Feb 2016	Transport Canada recall 2016064 ^[2] Issued for the model year · Airbag
25 Oct 2026	Listed for sale, London, ON ^[5] Tiger Auto Sales Ltd. · asking \$2,495



28 Oct 2026 Listing last updated^[5]
asking \$2,495

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 7 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

