

Register entry, as of 28 October 2026

Listed for sale

Record ID 97c618d41582

2010 Volvo XC70

3.2 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

YV4 982BZ 6 A 1 075592

WMI 1-3

Volvo Car Corporation

DESCRIPTOR 4-8

XC70 · 3.2 L

CHECK 9

Computes

YEAR 10

2010

PLANT 11

Torslanda

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	3.2 L, 6 cylinders
Make	Volvo	Fuel	Gasoline
Model	XC70	Drive	AWD
Trim	Not in the decode	Maker	VOLVO CAR CORPORATION
Body	Sport Utility Vehicle	Plant	Torslanda, Sweden

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volvo/xc70/2010

4 recalls listed by Transport Canada for this model year

Seats and restraints

2020298 30 Jun 2020

Issue: On certain vehicles, the flexible steel cable that attaches the seat belt to the outside of the front seats may weaken over time. As a result, the seat belt could detach. Safety Risk: A seat belt that detaches in a crash could create an increased risk of injury. Corrective Action: Volvo will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front-outboard seat belt anchors.

Accessories

2010396 8 Nov 2010

On certain vehicles, there is a possibility of overheating issues of batteries in the Garmin nüvi® 760 when certain batteries manufactured within a limited date code range are used in certain Garmin nüvi® 760 models with a specific printed circuit board (PCB) design. The interaction of these factors can, in some circumstances, increase the possibility of overheating, which may lead to a fire. Correction: Dealers will direct customers who have an affected unit to the Garmin Web site, which explains how to verify if their units are involved and includes procedures to follow for product exchange.

Airbag

2010350 13 Oct 2010

On certain vehicles, there may be an intermittent fault in the driver's airbag clockspring wiring connector for the Supplemental Restraint System (SRS). If this condition occurs, the SRS lamp will be permanently lit and the message "AIRBAG SYSTEM SERVICE REQUIRED" will be displayed in the drivers information module. If the condition occurs while driving, and if the driver ignores the warning and an accident occurs where the deployment of the driver's airbag is required, the airbag may not deploy as intended or may not deploy at all. Correction: Dealers will install a metal shim in the airbag clockspring wiring connector.



Fuel system

2009255 8 Sep 2009

On certain vehicles, the software within the Central Electronic Module (CEM) may not send a signal to the fuel Pump Electronic Module (PEM). This missing signal to the PEM inhibits the start of the fuel pump. The driver may be able to start the engine in spite of the fuel pump not being activated due to residual pressure in the fuel system. In some cases, the driver may be able to drive the vehicle a short distance at idle. However, the engine will eventually stall. Engine stalling would result in lost propulsion which, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash. Correction: Dealers will upgrade the CEM software.

Listed for the model year, not checked against your VIN. Volvo confirms which apply.

Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.

www.volvocars.com/en-ca/l/recall-information/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$8,995^[5], the median^[4].



Lowest ask	\$8,995
Middle half	\$8,995 – \$8,995
Median ask	\$8,995
This car	\$8,995

Same model year · 1 live listings · as of 28 Oct 2026

§4 EVENTS

2010	Model year 2010 ^[1] Assembly plant Torslanda, Sweden
8 Sep 2009	Transport Canada recall 2009255 ^[2] Issued for the model year · Fuel system
13 Oct 2010	Transport Canada recall 2010350 ^[2] Issued for the model year · Airbag
8 Nov 2010	Transport Canada recall 2010396 ^[2] Issued for the model year · Accessories
30 Jun 2020	Transport Canada recall 2020298 ^[2] Issued for the model year · Seats and restraints
29 Nov 2025	Listed for sale, Scarborough, ON ^[5] ALEXANDRIA AUTO · asking \$8,995
26 Oct 2026	Listing last updated ^[5] asking \$8,995



§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

