

Register entry, as of 27 October 2026

Listed for sale

Record ID dec05811cc87

2006 Volvo XC90 ULEV2

5 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

YV4 CZ592 0 6 1 296853

WMI 1-3

Volvo Car Corporation

DESCRIPTOR 4-8

XC90 · 5 cylinders

CHECK 9

Computes

YEAR 10

2006

PLANT 11

Torslanda

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2006	Engine	5 cylinders
Make	Volvo	Fuel	Gasoline
Model	XC90	Drive	AWD
Trim	ULEV2	Maker	VOLVO CAR CORPORATION
Body	Sport Utility Vehicle	Plant	Torslanda, Sweden

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volvo/xc90/2006

5 recalls listed by Transport Canada for this model year

Accessories

2010396 8 Nov 2010

On certain vehicles, there is a possibility of overheating issues of batteries in the Garmin nüvi® 760 when certain batteries manufactured within a limited date code range are used in certain Garmin nüvi® 760 models with a specific printed circuit board (PCB) design. The interaction of these factors can, in some circumstances, increase the possibility of overheating, which may lead to a fire. Correction: Dealers will direct customers who have an affected unit to the Garmin Web site, which explains how to verify if their units are involved and includes procedures to follow for product exchange.

Steering

2006108 8 May 2006

On certain vehicles, deformation at high loads may cause loss of clamping force of the outer tie rod and allow the nut to loosen. This may eventually lead to a fatigue fracture of the outer tie rod assembly. Tie rod separation could lead to a loss of steering control which could result in a vehicle crash. Correction: Dealers will replace outer tie rods with updated versions.

Visual system

2006093 26 Apr 2006

On certain vehicles the windshield wiper pivot splines may be damaged due to failure to remove snow from the windshield. This would result in a loss of wiper operation and resultant detriment to vision. Correction: Dealers will replace wiper arms and retaining nuts.



Seats and restraints

2006066 27 Mar 2006

Certain Volvo 850, S40, V40, V50, V70, XC70 and XC90 equipped with integrated child booster cushions were incorrectly labelled during vehicle assembly. The label indicates that the booster cushion can be used for children weighing between 15 and 36 kg (33 and 80 lb). CMVSS 213 states that the minimum weight for use must be 18 kg (40 lb). Should an underweight child be placed in the booster cushion and the vehicle is involved in a crash, the child may have a greater risk of injury. Correction: Volvo Canada will send a letter to owners explaining this problem and will supply updated weight limit decal to be applied to each side window.

Electrical

2005365 17 Nov 2005

On certain vehicles, the positive battery cable may wear against the starter solenoid. The resulting chafe damage could develop into an electrical short. This can be noticed in different ways. If the vehicle is parked, smoke may appear from under the hood and/or it may be impossible to start the car. If the short circuit happens during driving, not only will the engine stall, but the electrical power could also be lost, resulting in warning lamps being deactivated. Correction: Dealers will relocate the battery cable.

Listed for the model year, not checked against your VIN. Volvo confirms which apply.


Check your VIN with Volvo Canada or call a Volvo dealer with your VIN.

www.volvocars.com/en-ca/l/recall-information/

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$5,900^[5], \$1,700 over the median of \$4,200^[4].



Lowest ask	\$2,500
Middle half	\$3,350 – \$5,050
Median ask	\$4,200
This car	\$5,900

Same model year · 2 live listings · as of 27 Oct 2026

OTHER 2006 VOLVO XC90 LISTINGS [5]

Newmarket, ON · 252,190 km	\$2,500
Newmarket, ON · 252,190 km	\$4,500

§4 EVENTS

2006	Model year 2006 ^[1] Assembly plant Torslanda, Sweden
17 Nov 2005	Transport Canada recall 2005365 ^[2] Issued for the model year · Electrical
27 Mar 2006	Transport Canada recall 2006066 ^[2] Issued for the model year · Seats and restraints
26 Apr 2006	Transport Canada recall 2006093 ^[2] Issued for the model year · Visual system
8 May 2006	Transport Canada recall 2006108 ^[2] Issued for the model year · Steering



8 Nov 2010 Transport Canada recall 2010396^[2]
Issued for the model year · Accessories

11 Apr 2026 Listed for sale, Hamilton, ON^[5]
Auto Island · asking \$5,900

25 Oct 2026 Listing last updated^[5]
asking \$5,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 2 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

