Register entry, as of 28 October 2026 Listed for sale Record ID ecef6cb87ead

# 2013 Jeep Grand Cherokee Laredo

3.6 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1C4 | RJFAG | 9 | D | C | 535965 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Jeep · FCA US LLC | Grand Cherokee · 3.6 L | Verified | 2013 | Detroit | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2013 | Engine | 3.6 L, 6 cylinders |
| Make | Jeep | Fuel | Gasoline |
| Model | Grand Cherokee | Drive | 4WD |
| Trim | Laredo | Maker | FCA US LLC |
| Body | Sport Utility Vehicle | Plant | Detroit, Michigan, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/grand-cherokee/2013

**8** recalls listed by Transport Canada for this model year

### Fuel system

2019573 14 Nov 2019

Issue: On certain vehicles, the fuel pump relay could fail. A fuel pump relay failure can result in a no-start condition or cause a sudden loss of engine power while driving. Note: Vehicles that had a fuel pump relay replaced as part of a Transport Canada Recall No. 2014-386 (FCA Recall No. P54) or 2015-085 (R09) require a second repair under this recall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump relay, mounting bracket and related wiring.

### Brakes

2017450 18 Sep 2017

On certain vehicles, a brake booster shield may have been incorrectly installed as part of recall P14/2014-112. An incorrectly installed shield could be less effective in diverting water away from the brake booster, creating the possibility of corrosion allowing water to get inside. In a cold climate, water inside the brake booster could freeze limiting the braking ability of the vehicle, resulting in longer braking distances, increasing the risk of crash causing injury and/or damage to property. Correction: Dealers will inspect the installation of the brake booster shield and perform repairs as necessary.

### Electrical

2017341 10 Jul 2017

On certain vehicles equipped with electro-hydraulic power steering (“EHPS”), the alternator may fail suddenly. This could result in the engine stalling, causing a loss of motive power which could increase the risk of a crash as well as disable various vehicle safety systems, and could also cause a fire. Both issues could increase the risk of injury and/or damage to property. Correction: Dealers will inspect the part number on the alternator, and will replace the alternator as necessary. Note: Only specific engine and alternator combinations are affected by this campaign.

### Fuel system

2015085 26 Feb 2015

This recall was replaced by Transport Canada Recall No. 2019-573 (FCA Recall No. V62). On certain vehicles, a fuel pump relay within the Totally Integrated Power Module (TIPM-7) could fail, causing the engine to stall or to fail to start. Engine stalling would result in a loss of motive power, which, in conjunction with driver reactions and traffic conditions, could increase the risk of a crash resulting in injury and/or damage to property. Correction: Dealers will install a revised fuel pump relay external to the TIPM-7.

### Electrical

2014446 9 Oct 2014

On certain vehicles equipped with 3.6L engines and 160 amp output alternators, the alternator may fail suddenly. This could result in the engine stalling, causing a loss of motive power which could increase the risk of a crash as well as disable various vehicle safety systems, and could also cause a fire. Both issues could increase the risk of injury and/or damage to property. Correction: Dealers will replace the alternator.

### Electrical

2014275 3 Jul 2014

On certain vehicles equipped with illuminated sun visor vanity mirrors, service repairs requiring removal of the sun visors and/or headliner may cause an electrical short circuit, which could increase the risk of a fire causing injury and/or damage to property. Correction: Dealers will inspect wiring for damage and repair as necessary, re-route wiring and install a sun visor spacer.

2 more on the model-year record, cardog.app/tools/recalls/jeep/grand-cherokee/2013

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $10,990[5], $1,995 over the median of $8,995[4].

| | |
|---|---|
| Lowest ask | $2,988 |
| Middle half | $7,194 – $11,744 |
| Median ask | $8,995 |
| This car | $10,990 |

Same configuration · 10 live listings · as of 28 Oct 2026

### OTHER 2013 JEEP GRAND CHEROKEE LISTINGS [5]

| | |
|---|---|
| Mirabel, QC · 222,764 km | $7,777 |
| Terrebonne, QC · 222,764 km | $7,777 |
| Burlington, ON · 342,369 km | $2,988 |
| Mcmasterville, QC · 219,957 km | $6,495 |
| Gatineau, QC · 160,320 km | $12,980 |
| Quebec, QC · 77,500 km | $11,995 |

## §4 EVENTS

2013 **Model year 2013**[1]
Assembly plant Detroit, Michigan, United States

| | |
|---|---|
| 5 Mar 2014 | Transport Canada recall 2014070[2]<br>Issued for the model year · Brakes |
| 2 Apr 2014 | Transport Canada recall 2014112[2]<br>Issued for the model year · Brakes |
| 3 Jul 2014 | Transport Canada recall 2014275[2]<br>Issued for the model year · Electrical |
| 9 Oct 2014 | Transport Canada recall 2014446[2]<br>Issued for the model year · Electrical |
| 26 Feb 2015 | Transport Canada recall 2015085[2]<br>Issued for the model year · Fuel system |
| 10 Jul 2017 | Transport Canada recall 2017341[2]<br>Issued for the model year · Electrical |
| 18 Sep 2017 | Transport Canada recall 2017450[2]<br>Issued for the model year · Brakes |
| 14 Nov 2019 | Transport Canada recall 2019573[2]<br>Issued for the model year · Fuel system |
| 26 Oct 2026 | Listed for sale, Calgary, AB[5]<br>Wheaton Honda West · asking $10,990 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $10,990 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 10 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.