Register entry, as of 28 October 2026 Listed for sale Record ID 65989d7d4b23

2021 Jeep Gladiator Rubicon

3.0 L, 6 cylinders · 4WD · Pickup · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

1C6	JJTBM	4	M	L	503271
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Jeep · FCA US LLC	Gladiator · 3.0 L	Verified	2021	Toledo	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	3.0 L, 6 cylinders
Make	Jeep	Fuel	Diesel
Model	Gladiator	Drive	4WD
Trim	Rubicon	Maker	FCA US LLC
Body	Pickup	Plant	Toledo, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/gladiator/2021

7 recalls listed by Transport Canada for this model year

Steering

2026271 4 Jun 2026

Issue: On certain vehicles, the connection for the electric hydraulic power steering pump (EHPSP) could become loose. If this happens, the EHPSP connection could overheat and melt. Safety Risk: Wiring that overheats and melts can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: To reduce the safety risk, FCA recommends that you should park your vehicle outside and away from other vehicles or buildings until the recall repairs are completed. FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, repair or replace the affected part(s).

Fuel system

2023218 13 Apr 2023

Issue: On certain vehicles equipped with a 3.0 L diesel engine, the high-pressure fuel pump could fail. If this happens, you may notice a change in engine performance, a fuel leak, or a malfunction indicator lamp and/or service electronic throttle control tell-tale may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the high-pressure fuel pump. Additional fuel system parts may be replaced, if necessary.

Powertrain

2023089 23 Feb 2023

Issue: Under certain conditions, the clutch pressure plate could overheat and break. If this happens, the pressure plate may also crack or break the transmission case. This could cause debris to fall from the vehicle. Note: This recall only affects certain vehicles equipped with a 3.6 L engine and a manual transmission. Vehicles repaired under FCA Canada recalls Y01, Y03 and Y07 (Transport Canada recall 2021-035) also require this repair. Safety Risk: Debris from an overheated and fractured pressure plate could contact nearby parts and increase the risk of a fire. Parts that fall from the vehicle could create a road hazard for others and increase the risk of injury. Corrective Actions: FCA Canada will notify owners by mail and advise you to tale your vehicle to a dealership to replace the clutch assembly. The dealer will also inspect and, if necessary, update the instrument panel cluster and powertrain control module software.

Engine

2022584 14 Oct 2022

Issue: On certain vehicles equipped with a 3.0 L diesel engine, the high-pressure fuel pump could fail. If this happens, you may notice a change in engine performance, a fuel leak, or a malfunction indicator lamp and/or service electronic throttle control tell-tale may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the high-pressure fuel pump. Additional fuel system parts may be replaced, if necessary.

Seats and restraints

2022583 14 Oct 2022

Issue: On certain vehicles, there may be a problem with the driver and front passenger seat belt pretensioners. As a result, the seat belt pretensioners may not work properly in a crash. Safety Risk: A seat belt pretensioner that does not work properly could increase the risk of injury in a crash. Corrective Actions: FCA Canada will contact owners by mail and instruct you to bring your vehicle to a dealership to replace the driver and front passenger seat belt pretensioners.

Visual system

2022476 25 Aug 2022

Issue: On certain vehicles equipped with a 3.0 L diesel engine, a software problem could cause the radio to reset. If you shift to reverse while the computer is resetting, the rearview camera image will not appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that is slow to appear could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to update the radio software.

1 more on the model-year record, cardog.app/tools/recalls/jeep/gladiator/2021

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $69,999[5], $31,024 over the median of $38,975[4].



Lowest ask	$27,209
Middle half	$34,999 – $41,995
Median ask	$38,975
This car	$69,999

Same model year · 65 live listings · as of 28 Oct 2026

OTHER 2021 JEEP GLADIATOR LISTINGS [5]

Kingston, ON · 109,594 km	$41,995
Mercier, QC · 67,000 km	$34,999
Vancouver, BC · 109,570 km	$63,575
Sherbrooke, QC · 81,303 km	$40,987
Waterloo, ON · 142,700 km	$34,695
Airdrie, AB · 108,996 km	$44,995

§4 EVENTS

2021	Model year 2021[1] Assembly plant Toledo, Ohio, United States
28 Jan 2021	Transport Canada recall 2021035[2] Issued for the model year · Powertrain
25 Aug 2022	Transport Canada recall 2022476[2] Issued for the model year · Visual system
14 Oct 2022	Transport Canada recall 2022584[2] Issued for the model year · Engine
14 Oct 2022	Transport Canada recall 2022583[2] Issued for the model year · Seats and restraints
23 Feb 2023	Transport Canada recall 2023089[2] Issued for the model year · Powertrain
13 Apr 2023	Transport Canada recall 2023218[2] Issued for the model year · Fuel system
4 Jun 2026	Transport Canada recall 2026271[2] Issued for the model year · Steering
27 Oct 2026	Listed for sale, Stony Plain, AB[5] Competition Chevrolet · asking $69,999

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 65 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.