Register entry, as of 29 October 2026 Listed for sale Record ID 2e58ee151b38

2015 Ram 1500 Sport

5.7 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1C6	RR7MT	4	F	S	696795
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Ram · FCA US LLC	1500 · 5.7 L	Verified	2015	Warren	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	5.7 L, 8 cylinders
Make	Ram	Fuel	Gasoline
Model	1500	Drive	4WD
Trim	Sport	Maker	FCA US LLC
Body	Pickup	Plant	Warren, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/1500/2015

18 recalls listed by Transport Canada for this model year

Engine

2023338 8 Jun 2023

Issue: On certain vehicles equipped with a 3.0 L diesel engine, a problem with the engine tone wheel could cause a loss of signal to crankshaft position sensor. If this happens, the engine could stall and you may not be able to restart it. Note: Vehicles included in FCA recall W58 (Transport Canada recall 2020-371) are not part of this recall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module. This update will help maintain engine power if the crankshaft position signal is lost.

Fuel system

2022303 9 Jun 2022

Issue: On certain vehicles equipped with a 3.0 L diesel engine, the high-pressure fuel pump could fail. If this happens, you may notice a change in engine performance, a fuel leak, or a malfunction indicator lamp and/or service electronic throttle control tell-tale may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the high-pressure fuel pump. Additional fuel system parts may be replaced, if necessary.

Airbag

2021511 12 Aug 2021

Issue: On certain trucks, the side curtain airbag inflators could be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could rupture unexpectedly. If this happens, small pieces of metal could be propelled toward vehicle occupants or cause damage to the airbag and prevent it from inflating properly. Safety Risk: A side curtain airbag inflator that ruptures could create a risk of injury. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to inspect and replace the side curtain airbags, as necessary.

Engine
2020371 13 Aug 2020

Issue: On certain vehicles equipped with a 3.0 L diesel engine, a problem with the engine tone wheel could cause a loss of signal to crankshaft position sensor. If this happens, the engine could stall and you may not be able to restart it. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to update the powertrain control module. This update will help maintain engine power if the crankshaft position signal is lost.

Engine
2019535 25 Oct 2019

Issue: On certain trucks equipped with a 3.0-L EcoDiesel engine, the exhaust gas recirculation (EGR) cooler could crack internally and leak. If this happens, a driver may notice a low coolant level or a heater that does not work properly. Safety Risk: A cracked EGR cooler could create the risk of an engine fire. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to replace the EGR cooler. Dealers will also inspect intake manifold and replace it as necessary.

Structure
2019441 30 Aug 2019

Issue: On certain trucks equipped with a power locking tailgate, the tailgate may open while driving. If this occurs, cargo that is not secured could fall out of the truck bed and onto the road. Note: This is an expansion of recall U74 (Transport Canada recall 2018-398). Safety Risk: Cargo that falls from the truck bed could create a road hazard for others. Corrective Actions: The company will notify owners by mail and instruct them to take their truck to a dealer to modify the tailgate locking mechanism. Note: This recall supersedes recall 2019-221

12 more on the model-year record, cardog.app/tools/recalls/ram/1500/2015

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 18 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $24,960[5], $8,963 over the median of $15,997[4].



Lowest ask	$6,999
Middle half	$12,995 – $19,582
Median ask	$15,997
This car	$24,960

Same model year · 82 live listings · as of 29 Oct 2026

OTHER 2015 RAM 1500 LISTINGS [5]

Edmonton, AB · 262,116 km	$13,799
Winnipeg, MB · 262,116 km	$11,999
Regina, SK · 262,116 km	$11,999
Winnipeg, MB · 262,116 km	$11,999
Nipawin, SK · 162,288 km	$24,999
Woodstock, ON · 143,706 km	$17,950

§4 EVENTS

2015 **Model year 2015**[1]
Assembly plant Warren, Michigan, United States

22 Jul 2015	Transport Canada recall 2015326[2] Issued for the model year · Airbag
13 Aug 2015	Transport Canada recall 2015367[2] Issued for the model year · Electrical
16 Oct 2015	Transport Canada recall 2015477[2] Issued for the model year · Powertrain
23 Mar 2016	Transport Canada recall 2016129[2] Issued for the model year · Steering
12 May 2016	Transport Canada recall 2016214[2] Issued for the model year · Accessories
10 May 2017	Transport Canada recall 2017250[2] Issued for the model year · Airbag
21 Dec 2017	Transport Canada recall 2017659[2] Issued for the model year · Powertrain
22 Dec 2017	Transport Canada recall 2017663[2] Issued for the model year · Accessories
17 May 2018	Transport Canada recall 2018269[2] Issued for the model year · Engine
31 Jul 2018	Transport Canada recall 2018398[2] Issued for the model year · Structure
10 May 2019	Transport Canada recall 2019221[2] Issued for the model year · Structure
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
30 Aug 2019	Transport Canada recall 2019441[2] Issued for the model year · Structure
25 Oct 2019	Transport Canada recall 2019535[2] Issued for the model year · Engine
13 Aug 2020	Transport Canada recall 2020371[2] Issued for the model year · Engine
12 Aug 2021	Transport Canada recall 2021511[2] Issued for the model year · Airbag
9 Jun 2022	Transport Canada recall 2022303[2] Issued for the model year · Fuel system
8 Jun 2023	Transport Canada recall 2023338[2] Issued for the model year · Engine
25 Oct 2026	Listed for sale, Huntsvillle, ON[5] Edmonds GM · asking $24,960

28 Oct 2026	Listing last updated[5] asking $24,960

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 82 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.