Register entry, as of 26 October 2026 Listed for sale Record ID 573b9b78a574

# 2018 Ram 1500 Longhorn

3.0 L, 6 cylinders · 4WD · Pickup · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

| 1C6 | RR7PM | 5 | J | S | 256937 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Ram · FCA US LLC | 1500 · 3.0 L | Verified | 2018 | Warren | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2018 | Engine | 3.0 L, 6 cylinders |
| Make | Ram | Fuel | Diesel |
| Model | 1500 | Drive | 4WD |
| Trim | Longhorn | Maker | FCA US LLC |
| Body | Pickup | Plant | Warren, Michigan, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/1500/2018

**16** recalls listed by Transport Canada for this model year

### Airbag — 2025468 — 11 Sep 2025

Issue: On certain trucks, the side curtain airbag inflators may be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could rupture unexpectedly and metal fragments could be propelled toward vehicle occupants. Note: This is an expansion of Transport Canada recall 2025-013. Safety Risk: An airbag inflator that ruptures can create a risk of injury. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to replace the affected side curtain airbag(s).

### Airbag — 2025013 — 16 Jan 2025

Issue: On certain trucks, the side curtain airbag inflators may be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could rupture unexpectedly and metal fragments could be propelled toward vehicle occupants. Note: This recall also affects certain 2016 model year RAM 3500 chassis cab incomplete vehicles. Safety Risk: An airbag inflator that ruptures can create a risk of injury. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to replace the affected side curtain airbag(s).

### Engine — 2023338 — 8 Jun 2023

Issue: On certain vehicles equipped with a 3.0 L diesel engine, a problem with the engine tone wheel could cause a loss of signal to crankshaft position sensor. If this happens, the engine could stall and you may not be able to restart it. Note: Vehicles included in FCA recall W58 (Transport Canada recall 2020-371) are not part of this recall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module. This update will help maintain engine power if the crankshaft position signal is lost.

### Fuel system

2022303 9 Jun 2022

Issue: On certain vehicles equipped with a 3.0 L diesel engine, the high-pressure fuel pump could fail. If this happens, you may notice a change in engine performance, a fuel leak, or a malfunction indicator lamp and/or service electronic throttle control tell-tale may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the high-pressure fuel pump. Additional fuel system parts may be replaced, if necessary.

### Engine

2020371 13 Aug 2020

Issue: On certain vehicles equipped with a 3.0 L diesel engine, a problem with the engine tone wheel could cause a loss of signal to crankshaft position sensor. If this happens, the engine could stall and you may not be able to restart it. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to update the powertrain control module. This update will help maintain engine power if the crankshaft position signal is lost.

### Engine

2019535 25 Oct 2019

Issue: On certain trucks equipped with a 3.0-L EcoDiesel engine, the exhaust gas recirculation (EGR) cooler could crack internally and leak. If this happens, a driver may notice a low coolant level or a heater that does not work properly. Safety Risk: A cracked EGR cooler could create the risk of an engine fire. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to replace the EGR cooler. Dealers will also inspect intake manifold and replace it as necessary.

10 more on the model-year record, cardog.app/tools/recalls/ram/1500/2018

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 15 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $26,995[5], $5,007 over the median of $21,988[4].

| | |
|---|---|
| Lowest ask | $19,888 |
| Middle half | $20,999 – $26,995 |
| Median ask | $21,988 |
| This car | $26,995 |

Same configuration · 9 live listings · as of 26 Oct 2026

### OTHER 2018 RAM 1500 LISTINGS [5]

| | |
|---|---|
| Leduc, AB · 154,501 km | $30,803 |
| Stettler, AB · 94,140 km | $39,998 |
| Picton, ON · 137,646 km | $32,995 |
| Nanaimo, BC · 101,259 km | $23,495 |
| Concord, ON · 243,501 km | $7,910 |
| Concord, ON · 147,299 km | $17,610 |

## §4 EVENTS

| | |
|---|---|
| 2018 | Model year 2018[1]<br>Assembly plant Warren, Michigan, United States |
| 8 Feb 2018 | Transport Canada recall 2018081[2]<br>Issued for the model year · Powertrain |
| 17 May 2018 | Transport Canada recall 2018269[2]<br>Issued for the model year · Engine |
| 15 Jun 2018 | Transport Canada recall 2018324[2]<br>Issued for the model year · Other |
| 9 Aug 2018 | Transport Canada recall 2018422[2]<br>Issued for the model year · Powertrain |
| 23 Aug 2018 | Transport Canada recall 2018447[2]<br>Issued for the model year · Powertrain |
| 26 Apr 2019 | Transport Canada recall 2019206[2]<br>Issued for the model year · Powertrain |
| 10 May 2019 | Transport Canada recall 2019221[2]<br>Issued for the model year · Structure |
| 25 Jul 2019 | Transport Canada recall 2019365[2]<br>Issued for the model year · Lights and instruments |
| 21 Aug 2019 | Transport Canada recall 2019420[2]<br>Issued for the model year · Other |
| 30 Aug 2019 | Transport Canada recall 2019441[2]<br>Issued for the model year · Structure |
| 25 Oct 2019 | Transport Canada recall 2019535[2]<br>Issued for the model year · Engine |
| 13 Aug 2020 | Transport Canada recall 2020371[2]<br>Issued for the model year · Engine |
| 9 Jun 2022 | Transport Canada recall 2022303[2]<br>Issued for the model year · Fuel system |
| 8 Jun 2023 | Transport Canada recall 2023338[2]<br>Issued for the model year · Engine |
| 16 Jan 2025 | Transport Canada recall 2025013[2]<br>Issued for the model year · Airbag |
| 11 Sep 2025 | Transport Canada recall 2025468[2]<br>Issued for the model year · Airbag |
| 26 Oct 2026 | Listed for sale, Vancouver, BC[5]<br>Dueck Downtown · asking $26,995 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 9 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.