Register entry, as of 27 October 2026 Listed for sale Record ID 62c983dbe612

2017 Ford Taurus SEL

3.5 L, 6 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1FA	HP2E8	4	H	G	127321
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ford Motor Company	Taurus · 3.5 L	Verified	2017	Chicago	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.5 L, 6 cylinders
Make	Ford	Fuel	Gasoline
Model	Taurus	Drive	FWD
Trim	SEL	Maker	FORD MOTOR COMPANY
Body	Sedan	Plant	Chicago, Illinois, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/taurus/2017

4 recalls listed by Transport Canada for this model year

Structure — 2025483 — 12 Sep 2025

Issue: On certain vehicles, the exterior B-pillar trims on the driver and front passenger doors may not be properly attached. As a result, the trim(s) could loosen and separate from the vehicle. Safety Risk: Trim that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and repair or replace the exterior B-pillar trims, as necessary.

Suspension — 2020051 — 11 Feb 2020

Issue: On certain vehicles, the rear suspension toe link(s) could break. This could cause a sudden loss of vehicle stability. Note: Vehicles previously repaired under Ford Campaign 19R01 or 19S18 do not require repair under this recall. For the Taurus model, only the SHO Performance Package model is included in this recall. Safety Risk: A loss of vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a Ford or Lincoln dealer to install improved rear suspension toe links.

Suspension — 2019281 — 11 Jun 2019

Issue: On certain vehicles, a buildup of dirt and mud could cause the rear suspension toe links to break. This could result in a sudden loss of vehicle stability. Note: This problem affects vehicles operated in Alberta, Saskatchewan and Manitoba. The unique soil properties in this region could make a toe link more likely to break. Safety Risk: A loss of stability could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to install improved rear suspension toe links.

Steering

2017415 30 Aug 2017

On certain vehicles, the steering gear heat shield fasteners may have an incorrect coating that could cause the heat shield to corrode and detach. This could expose the steering gear system to higher temperatures and could cause the steering gear to overheat, which could result in a reduction of steering assist until the gear cools. If the steering gear electrical connectors were to melt, it would result in a sudden loss of steering assist. A loss of power steering assist could unexpectedly increase steering effort, which would increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the fasteners and replace as required. Note: In the event of a loss of power assist, the message "SERVICE POWER STEERING NOW" would be displayed in the instrument cluster.

Listed for the model year, not checked against your VIN. Ford confirms which apply.
Check your VIN with Ford Canada or call a Ford dealer with your VIN.
www.ford.ca/support/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $12,968[5], $3,000 under the median of $15,968[4].

Lowest ask	$12,968
Middle half	$14,468 – $17,467
Median ask	$15,968
This car	$12,968

Same model year · 2 live listings · as of 27 Oct 2026

OTHER 2017 FORD TAURUS LISTINGS [5]

Calgary, AB · 119,675 km	$18,967

§4 EVENTS

2017	Model year 2017[1] Assembly plant Chicago, Illinois, United States
30 Aug 2017	Transport Canada recall 2017415[2] Issued for the model year · Steering
11 Jun 2019	Transport Canada recall 2019281[2] Issued for the model year · Suspension
11 Feb 2020	Transport Canada recall 2020051[2] Issued for the model year · Suspension
12 Sep 2025	Transport Canada recall 2025483[2] Issued for the model year · Structure
25 Oct 2026	Listed for sale, Ajax, ON[5] Boyer Chevrolet Buick GMC Ajax Ltd · asking $12,968
26 Oct 2026	Listing last updated[5] asking $12,968

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 2 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.