Register entry, as of 27 October 2026 Listed for sale Record ID 8d6ece68612c

2022 Ford Bronco Raptor

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1FM	EE5JR	6	N	L	A51201
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ford Motor Company	Bronco · 3.0 L	Verified	2022	Wayne	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	3.0 L, 6 cylinders
Make	Ford	Fuel	Gasoline
Model	Bronco	Drive	AWD
Trim	Raptor	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Wayne, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/bronco/2022

19 recalls listed by Transport Canada for this model year

Electrical

2026356 20 Jul 2026

Issue: On certain vehicles, the engine wiring harness may not have enough protection and could become damaged by contact with surrounding components. As a result, the wiring harness could short circuit. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to install additional protection on the engine wiring harness. The dealer will also repair or replace the engine wiring harness, as necessary.

Accessories

2026310 24 Jun 2026

Issue: On certain vehicles, the fender flare(s) may not be properly attached. As a result, the fender flare(s) could loosen and separate from the vehicle. Note: This recall only affects Bronco Raptor models. Safety Risk: A fender flare that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and repair or replace the fender flares, as necessary.

Structure

2026229 12 May 2026

Issue: On certain vehicles, the hard top roof panels may not have been manufactured properly. As a result, sections of the exterior panels could separate and detach from the vehicle while driving. Note: This recall only affects certain vehicles equipped with a molded-in-colour hard top. Safety Risk: A section of roof that detaches from the vehicle could create a hazard for others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the hard top.

Powertrain

2026188 15 Apr 2026

Issue: On certain vehicles, the transmission may not have been reassembled properly after service. As a result, the transmission output shaft splines and/or the transfer case input splines could wear and fail. If this happens, there could be a loss of power to the wheels, or the vehicle could move when it's parked and the parking brake isn't used. Safety Risk: A loss of power to the wheels could increase the risk of a crash. A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the transmission and transfer case.

Visual system

2026093 3 Mar 2026

Issue: Under certain conditions, the infotainment system could overheat. As a result, the rearview camera image may not display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the accessory protocol image module (APIM) software.

Electrical

2026005 9 Jan 2026

Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Note: This recall replaces Transport Canada recall no. 2025-554. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater. Alternatively, owners can choose to have the dealership permanently disable the engine block heater.

13 more on the model-year record, cardog.app/tools/recalls/ford/bronco/2022

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 23 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $88,995[5], $49,295 over the median of $39,700[4].



Lowest ask	$23,995
Middle half	$35,554 – $43,995
Median ask	$39,700
This car	$88,995

Same model year · 118 live listings · as of 27 Oct 2026

OTHER 2022 FORD BRONCO LISTINGS [5]

Toronto, ON · 28,725 km	$36,488
Lethbridge, AB · 62,818 km	$36,557
Sudbury, ON · 64,729 km	$40,995
Sudbury, ON · 77,041 km	$41,995
Smiths Falls, ON · 45,357 km	$48,995
Orangeville, ON · 49,600 km	$49,450

§4 EVENTS

2022	Model year 2022[1] Assembly plant Wayne, Michigan, United States
10 Jun 2022	Transport Canada recall 2022309[2] Issued for the model year · Structure
24 Jun 2022	Transport Canada recall 2022335[2] Issued for the model year · Structure
4 Nov 2022	Transport Canada recall 2022636[2] Issued for the model year · Visual system
13 Mar 2023	Transport Canada recall 2023129[2] Issued for the model year · Visual system
19 May 2023	Transport Canada recall 2023294[2] Issued for the model year · Seats and restraints
29 May 2023	Transport Canada recall 2023308[2] Issued for the model year · Label
17 Jan 2025	Transport Canada recall 2025020[2] Issued for the model year · Suspension
24 Apr 2025	Transport Canada recall 2025223[2] Issued for the model year · Visual system
9 May 2025	Transport Canada recall 2025260[2] Issued for the model year · Visual system
9 May 2025	Transport Canada recall 2025255[2] Issued for the model year · Visual system
8 Jul 2025	Transport Canada recall 2025366[2] Issued for the model year · Fuel system
10 Oct 2025	Transport Canada recall 2025554[2] Issued for the model year · Electrical
24 Oct 2025	Transport Canada recall 2025585[2] Issued for the model year · Seats and restraints
9 Jan 2026	Transport Canada recall 2026005[2] Issued for the model year · Electrical
3 Mar 2026	Transport Canada recall 2026093[2] Issued for the model year · Visual system
15 Apr 2026	Transport Canada recall 2026188[2] Issued for the model year · Powertrain
12 May 2026	Transport Canada recall 2026229[2] Issued for the model year · Structure

24 Jun 2026	Transport Canada recall 2026310[2] Issued for the model year · Accessories
20 Jul 2026	Transport Canada recall 2026356[2] Issued for the model year · Electrical
29 Jul 2026	Listed for sale, North Vancouver, BC[5] North Shore Acura · asking $88,995
25 Oct 2026	Listing last updated[5] asking $88,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 118 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.