Register entry, as of 27 October 2026 Listed for sale Record ID 6c7d6b4b1ae4

# 2022 Ford Expedition Platinum

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Flexible Fuel Vehicle (FFV)

VEHICLE IDENTIFICATION NUMBER [1]

| 1FM | JU1MT | 1 | N | E | A05359 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Ford Motor Company | Expedition · 3.5 L | Verified | 2022 | Jefferson County | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | 3.5 L, 6 cylinders |
| Make | Ford | Fuel | Flexible Fuel Vehicle (FFV) |
| Model | Expedition | Drive | 4WD |
| Trim | Platinum | Maker | FORD MOTOR COMPANY |
| Body | Sport Utility Vehicle | Plant | Jefferson County, Kentucky, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/expedition/2022

**12** recalls listed by Transport Canada for this model year

### Other

2026279 9 Jun 2026

Issue: On certain vehicles, the chrome plating on the center console could bubble and peel. If this happens, sharp edges can be created. Safety Risk: Exposed sharp edges can increase the risk of injury. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the center console.

### Seats and restraints

2026257 27 May 2026

Issue: On certain vehicles, there could be a problem with the driver and/or front passenger seatbelt pretensioner(s). As a result, the airbag warning light could turn on, and the seatbelt pretensioners could deploy without a crash. Note: This recall replaces Transport Canada recall nos. 2024-084 and 2025-164. Vehicles that were repaired under those recalls also require this inspection or repair. Safety Risk: Seat belt pretensioners that don't work properly could create an increased risk of injury. Additionally, seat belt pretensioners that deploy without a crash could startle the driver and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the driver and front passenger seatbelt retractors.

### Visual system

2026161 1 Apr 2026

Issue: On certain trucks, the windshield wiper arms may not have been manufactured correctly. As a result, the wiper arm(s) could break or become detached and may not wipe the windshield properly. Safety Risk: Windshield wipers that do not work properly could affect a driver's visibility. Windshield wiper(s) that detach from the vehicle could create a road hazard for others. Both issues could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail. The corrective actions for this recall are under development.

### Lights and instruments

2026079 20 Feb 2026

Issue: On certain vehicles, a software problem with the integrated trailer module (ITRM) may cause the trailer lights not to work when towing. This problem could also cause the trailer brakes not to work on certain vehicles. Note: This problem would cause a "Trailer brake module fault" message to be displayed and turn signal telltale to flash rapidly. This recall also affects certain Super Duty incomplete vehicles. Safety Risk: Trailer lights that don't work could make the vehicle less visible and cause following drivers not to recognize that the vehicle is braking or intends to turn or change lanes. These issues could increase the risk of a crash. Additionally, a loss of trailer brakes could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the ITRM software. Alternatively, you may schedule an appointment to have the update performed at a Ford dealership.

### Structure

2025587 24 Oct 2025

Issue: On certain vehicles, the moonroof wind deflector may not have been attached properly. As a result, the deflector could detach from the vehicle. Note: This recall also affects certain Super Duty incomplete vehicles. Safety Risk: A moonroof wind deflector that detaches from the vehicle could create a hazard for others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, repair the moonroof wind deflector.

### Fuel system

2025366 8 Jul 2025

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module software. For Super Duty models, the dealer will replace the fuel pump.

6 more on the model-year record, cardog.app/tools/recalls/ford/expedition/2022

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $58,788[5], $5,710 over the median of $53,078[4].

| | |
|---|---|
| Lowest ask | $37,995 |
| Middle half | $47,230 – $56,991 |
| Median ask | $53,078 |
| This car | $58,788 |

Same model year · 20 live listings · as of 27 Oct 2026

### OTHER 2022 FORD EXPEDITION LISTINGS [5]

| | |
|---|---|
| Airdrie, AB · 68,001 km | $56,990 |
| Espanola, ON · 126,034 km | $47,474 |
| Wawa, ON · 118,004 km | $42,566 |
| Lloydminster, AB · 127,691 km | $52,890 |
| North Bay, ON · 126,034 km | $47,474 |
| Sault Ste Marie, ON · 118,004 km | $41,995 |

## §4 EVENTS

| | |
|---|---|
| 2022 | Model year 2022[1]<br>Assembly plant Jefferson County, Kentucky, United States |
| 29 Mar 2022 | Transport Canada recall 2022146[2]<br>Issued for the model year · Brakes |
| 30 May 2022 | Transport Canada recall 2022279[2]<br>Issued for the model year · Brakes |
| 9 Jun 2023 | Transport Canada recall 2023341[2]<br>Issued for the model year · Seats and restraints |
| 2 Mar 2025 | Transport Canada recall 2025106[2]<br>Issued for the model year · Brakes |
| 9 May 2025 | Transport Canada recall 2025260[2]<br>Issued for the model year · Visual system |
| 9 May 2025 | Transport Canada recall 2025259[2]<br>Issued for the model year · Brakes |
| 8 Jul 2025 | Transport Canada recall 2025366[2]<br>Issued for the model year · Fuel system |
| 24 Oct 2025 | Transport Canada recall 2025587[2]<br>Issued for the model year · Structure |
| 20 Feb 2026 | Transport Canada recall 2026079[2]<br>Issued for the model year · Lights and instruments |
| 1 Apr 2026 | Transport Canada recall 2026161[2]<br>Issued for the model year · Visual system |
| 27 May 2026 | Transport Canada recall 2026257[2]<br>Issued for the model year · Seats and restraints |
| 9 Jun 2026 | Transport Canada recall 2026279[2]<br>Issued for the model year · Other |
| 26 Oct 2026 | Listed for sale, North Bay, ON[5]<br>TOP PICKS AUTO SALES · asking $58,788 |

## §5 DOCUMENTS

Window sticker — We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 20 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.