Register entry, as of 28 October 2026 Listed for sale Record ID 57f9a78cab6e

2013 Chevrolet Malibu 2LT

2.5 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G1	1E5SA	3	D	F	190817
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Malibu · 2.5 L	Verified	2013	Kansas City	Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	2.5 L, 4 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Malibu	Drive	Not in the decode
Trim	2LT	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Kansas City, Kansas, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/malibu/2013

9 recalls listed by Transport Canada for this model year

Suspension

2021510 12 Aug 2021

Issue: On certain vehicles, the protective coating on the rear suspension toe links may chip away. If this happens, the metal can rust and the toe link could break. A broken toe link can affect vehicle stability and could cause a loss of directional control. Note: This recall is an expansion of Transport Canada recall 2020-615. This recall only affects vehicles that were originally sold or ever registered in areas of heavy road salt usage (Manitoba, Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). Safety Risk: A loss of vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear suspension toe links and adjuster fasteners.

Suspension

2020615 10 Dec 2020

Issue: On certain vehicles, the protective coating on the rear suspension toe links may chip away. If this happens, the metal can rust and the toe link could break. A broken toe link can affect vehicle stability and could cause a loss of directional control. Note: This recall only affects vehicles that were originally sold or ever registered in areas of heavy road salt usage (Manitoba, Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). Safety Risk: A loss of vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear suspension toe links and adjuster fasteners.

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

Structure

2015118 18 Mar 2015

Certain vehicles equipped with power-operated sunroof systems may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 118 - Power-Operated Window, Partition and Roof Panel Systems. The roof panels could close automatically when the non-recessed portion of the “Slide” or “Tilt” switches are pressed and the roof panel is open, which is contrary to the standard. The switch could be more susceptible to an inadvertent actuation, which could result in unintended auto-closure of the roof panel, increasing the risk of injury. Correction: Dealers will update the Body Control Module (BCM), which will remove the "one touch" (momentary actuation) feature for certain switch positions.

Lights and instruments

2014310 23 Jul 2014

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard 108 - Lighting System and Retroreflective Devices. If one of the two front turn signal bulbs burn out in either front turn signal lamp, no indication would be provided to the driver, which is contrary to the requirements of the standard. Correction: Dealers will update vehicle software.

Electrical

2013401 13 Nov 2013

On certain vehicles equipped with 8-way power adjustable seats, the seat wiring may chafe against the seat frame and cause a short. This could result in unintended seat movement, inoperative seat adjustment, sparking under the seat, smoke and/or fire. These issues could increase the risk of injury and/or damage to property. Correction: Dealers will inspect and repair wiring as necessary.

3 more on the model-year record, cardog.app/tools/recalls/chevrolet/malibu/2013

> Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
> Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
> www.chevrolet.ca/en/ownercenter/recalls

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $1,995[5], $4,004 under the median of $5,999[4].



Lowest ask	$1,995
Middle half	$5,247 – $9,478
Median ask	$5,999
This car	$1,995

Same model year · 7 live listings · as of 28 Oct 2026

OTHER 2013 CHEVROLET MALIBU LISTINGS [5]

Cranbrook, BC · 140,247 km	$5,999
Cranbrook, BC · 140,247 km	$5,999
Laval, QC · 172,000 km	$4,499
St Catharines, ON · 193,494 km	$9,960
London, ON · 158,446 km	$8,995

Dayton, NS · 180,500 km $5,995

§4 EVENTS

2013	Model year 2013[1] Assembly plant Kansas City, Kansas, United States
23 Jan 2013	Transport Canada recall 2013023[2] Issued for the model year · Suspension
6 Feb 2013	Transport Canada recall 2013043[2] Issued for the model year · Lights and instruments
6 May 2013	Transport Canada recall 2013149[2] Issued for the model year · Electrical
13 Nov 2013	Transport Canada recall 2013401[2] Issued for the model year · Electrical
23 Jul 2014	Transport Canada recall 2014310[2] Issued for the model year · Lights and instruments
18 Mar 2015	Transport Canada recall 2015118[2] Issued for the model year · Structure
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
10 Dec 2020	Transport Canada recall 2020615[2] Issued for the model year · Suspension
12 Aug 2021	Transport Canada recall 2021510[2] Issued for the model year · Suspension
25 Oct 2026	Listed for sale, London, ON[5] Tiger Auto Sales Ltd. · asking $1,995
28 Oct 2026	Listing last updated[5] asking $1,995

§5 DOCUMENTS

Window sticker This VIN reads as model year 1983 or 2013, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 7 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.