Register entry, as of 24 November 2026 Listed for sale Record ID a437d439e239

2008 Buick Lucerne CXL

3.8 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1G4	HD572	4	8	U	173029
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Buick · GENERAL MOTORS…	Lucerne · 3.8 L	Verified	2008	Detroit Hamtramck	Build sequence

§1 IDENTITY [1]

Model year	2008	Engine	3.8 L, 6 cylinders
Make	Buick	Fuel	Gasoline
Model	Lucerne	Drive	Not in the decode
Trim	CXL	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Detroit Hamtramck, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/lucerne/2008

3 recalls listed by Transport Canada for this model year

Electrical — 2014246 — 23 Jun 2014

On certain vehicles, a defect in the ignition switch could allow the switch to move out of the "run" position if the key ring is carrying added weight or the vehicle goes off-road or is subjected to some other jarring event. If this were to occur, engine power, power steering and power braking would be affected, increasing the risk of a crash causing injury and/or damage to property. The timing of the key movement out of the “run” position, relative to the activation of the sensing algorithm of the crash event, may also result in the airbags not deploying in a subsequent collision, increasing the risk of injury. Correction: For each key, dealers will install two key rings and modify the key ring opening shape. Note: Until the correction is performed, all items should be removed from the key ring.

Accessories — 2010189 — 7 Jun 2010

On certain vehicles equipped with a Heated Washer Fluid System (HWFS), a short circuit on the printed circuit board for the washer fluid heater may overheat the control-circuit ground wire. A repair was implemented in a recall in 2008, however, there have been new reports of thermal incidents on heated washer fluid system modules after this improvement was installed. This situation may cause some minor distortion, but also could lead to melting of the plastic around the heated washer fluid system, or cause a fire. Correction: Dealers will permanently disable and remove the heated washer fluid module. An updated page will be provided and inserted in the Owner Manual to document the removal of the feature.

Other — 2008313 — 29 Aug 2008


On certain vehicles equipped with a heated washer fluid system, a short circuit on the printed circuit board for the washer fluid heater may overheat the control-circuit ground wire. This situation may cause other electrical features to malfunction which could cause smoke and in some cases a fire. Correction: Dealer will install a wire harness with an in-line fuse.

> Listed for the model year, not checked against your VIN. Buick confirms which apply. Check your VIN with Buick Canada or call a Buick dealer with your VIN.
> www.buick.ca/en/ownercenter/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $2,750[5], the median[4].



Lowest ask	$2,750
Middle half	$2,750 – $2,750
Median ask	$2,750
This car	$2,750

Same model year · 1 live listings · as of 23 Nov 2026

§4 EVENTS

2008	Model year 2008[1] Assembly plant Detroit Hamtramck, Michigan, United States
29 Aug 2008	Transport Canada recall 2008313[2] Issued for the model year · Other
7 Jun 2010	Transport Canada recall 2010189[2] Issued for the model year · Accessories
23 Jun 2014	Transport Canada recall 2014246[2] Issued for the model year · Electrical
12 Nov 2026	Listed for sale, London, ON[5] Finch Chrysler · asking $2,750
22 Nov 2026	Listing last updated[5] asking $2,750

§5 DOCUMENTS

Window sticker	This VIN reads as model year 2008, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 1 live listings, as of 23 Nov 2026
[5] Live public dealer listings on Cardog, as of 24 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.