Register entry, as of 29 October 2026 Listed for sale Record ID c937335b3bbc

2020 Volkswagen Atlas Cross Sport 4Motion SEL

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1V2	MC2CA	7	L	C	207382
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen Group Of Ame…	Atlas Cross Sport · 2.0 L	Verified	2020	Chattanooga	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Atlas Cross Sport	Drive	AWD
Trim	4Motion SEL	Maker	VOLKSWAGEN GROUP OF AMERICA, INC.
Body	Sport Utility Vehicle	Plant	Chattanooga, Tennessee, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/atlas-cross-sport/2020

6 recalls listed by Transport Canada for this model year

Airbag

2024354 19 Jun 2024

Issue: On certain vehicles, the passenger occupant detection system (PODS) may malfunction. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause an error message to display on the instrument panel and a warning chime to sound. The airbag indicator light would also display "passenger airbag off". Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the PODS sensor mat and seat harness. Volkswagen advises that you shouldn't use the front passenger seat if a PODS error message displays on the instrument panel or if the airbag indicator light displays "passenger airbag off" with an occupant in the seat.

Airbag

2022110 11 Mar 2022

Issue: On certain vehicles, the wiring contacts for the front doors may become damaged. If this happens, there could be a delay before the side airbags inflate in a side-impact crash. This problem could also cause the parking brake to engage while driving at low speed, cause the windows to roll down on their own, or give warning of a faulty door sensor. Safety Risk: Delayed inflation of the side airbags could create an increased the risk of injury in a crash. Corrective Actions: Volkswagen will notify owners by mail. The corrective actions for this recall are under development.

Heater and defroster

2021705 17 Nov 2021

Issue: On certain vehicles, the drain tube for the air conditioning system may be blocked. As a result, water may leak inside the vehicle and into the airbag control module. If this happens, the airbag control module may not work properly and could cause the airbags to inflate without a crash. Safety Risk: An airbag that inflates suddenly without a crash could create a risk of injury. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the air conditioning system drain tube. If the tube is blocked, the dealer will repair it and replace the airbag control module.

Steering

2021032 27 Jan 2021

Issue: On certain vehicles, the front steering knuckles may not have been manufactured correctly. As a result, the steering knuckle could break suddenly while driving. If this happens, there would be a loss of steering control. Safety Risk: A loss of steering control could create a risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the front knuckles and replace them, if necessary.

Tires

2020546 13 Nov 2020

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could lead to a sudden loss of air pressure and could cause a tire failure. Note: This recall only affects vehicles equipped with certain Continental tires, with specific date codes and mold numbers. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the tires and replace the ones that have the DOT number and production mold number combinations identified by Continental.

Seats and restraints

2020392 26 Aug 2020

Issue: On certain vehicles, parts of the front seat frame and backrest adjuster may not have been properly welded. As a result, the backrest adjustment could break in a rear-end crash and allow to seat to move. Safety Risk: A seatback that fails could cause an increased risk of injury in a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the driver and passenger front seats. The seatback frames will be replaced, as necessary.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

Median ask $23,150[4] for same configuration.

Lowest ask	$19,988
Middle half	$22,347 – $24,990
Median ask	$23,150
This car	US$28,999

Same configuration · 12 live listings · as of 29 Oct 2026

OTHER 2020 VOLKSWAGEN ATLAS CROSS SPORT LISTINGS [5]

Brantford, ON · 158,339 km	$22,700
Burlington, ON · 65,950 km	$20,999
Hamilton, ON · 158,339 km	$22,700
Welland, ON · 158,339 km	$22,700
Sudbury, ON · 106,281 km	$27,995
Okotoks, AB · 81,000 km	$30,789

§4 EVENTS

2020	Model year 2020[1] Assembly plant Chattanooga, Tennessee, United States
26 Aug 2020	Transport Canada recall 2020392[2] Issued for the model year · Seats and restraints
13 Nov 2020	Transport Canada recall 2020546[2] Issued for the model year · Tires
27 Jan 2021	Transport Canada recall 2021032[2] Issued for the model year · Steering
17 Nov 2021	Transport Canada recall 2021705[2] Issued for the model year · Heater and defroster
11 Mar 2022	Transport Canada recall 2022110[2] Issued for the model year · Airbag
19 Jun 2024	Transport Canada recall 2024354[2] Issued for the model year · Airbag
9 Oct 2026	Listed for sale, Red Deer, AB[5] Red Deer Motors · asking US$28,999
29 Oct 2026	Listing last updated[5] asking US$28,999

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 12 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.