Register entry, as of 29 October 2026 Listed for sale Record ID 9012313b3f6e

# 2013 Volkswagen Passat Highline

2.0 L, 4 cylinders · Sedan · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

| 1VW | CN7A3 | X | D | C | 096981 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Volkswagen Group Of Ame… | Passat · 2.0 L | Verified | 2013 | Chattanooga | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2013 | Engine | 2.0 L, 4 cylinders |
| Make | Volkswagen | Fuel | Diesel |
| Model | Passat | Drive | Not in the decode |
| Trim | Highline | Maker | VOLKSWAGEN GROUP OF AMERICA, INC. |
| Body | Sedan | Plant | Chattanooga, Tennessee, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/passat/2013

**11** recalls listed by Transport Canada for this model year

### Airbag

2024649 30 Oct 2024

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the driver-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-front airbag. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

### Label

2020353 4 Aug 2020

Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.

### Lights and instruments

2019242 23 May 2019

Issue: Certain vehicles were built with headlights that may allow horizontal adjustment. This is not allowed under Canadian regulations. Safety Risk: Headlights that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the headlights. A blocking cap will be installed on the horizontal adjusters as necessary.

### Other

2018266 17 May 2018

On certain early production vehicles, modifications may have been made prior to sale that could make the vehicles non-compliant with regulatory requirements. Correction: Volkswagen will repurchase the affected vehicles and remove them from the market.

### Airbag

2018111 6 Mar 2018

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the driver frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the driver frontal airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected. Additional Note: This recall supersedes the Volkswagen brand vehicles subject to recall 2016-064 (Volkswagen Recall 69M9). Volkswagen vehicles completed under the previous 2016-064 recall require repair under this recall, as the previous recall remedy was an interim repair. Interim repair parts must be replaced with final repair parts.

### Powertrain

2017256 10 May 2017

On certain vehicles, an underbody heat shield may not be long enough to protect the right drive half-shaft grease boot from heat. Over time, this could lead to a grease leak from the boot. If leaking grease comes into contact with heated surfaces of the exhaust system and/or diesel particulate filter (DPF), it could lead to a fire potentially causing injury and/or damage to property. Correction: Dealers will install a revised heat shield and certain vehicles will have the upper boost hose replaced.

5 more on the model-year record, cardog.app/tools/recalls/volkswagen/passat/2013

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $8,995[5], $5 under the median of $9,000[4].

| | |
|---|---|
| Lowest ask | $3,600 |
| Middle half | $7,243 – $11,448 |
| Median ask | $9,000 |
| This car | $8,995 |

Same model year · 18 live listings · as of 29 Oct 2026

#### OTHER 2013 VOLKSWAGEN PASSAT LISTINGS [5]

| | |
|---|---|
| Thorndale, ON · 202,120 km | $5,995 |
| Toronto, ON · 231,580 km | $6,950 |
| Scarborough, ON · 163,600 km | $8,999 |
| Toronto, ON · 127,150 km | $7,988 |
| Scarborough, ON · 409,882 km | $1,500 |
| London, ON · 141,995 km | $11,995 |

## §4 EVENTS

| | |
|---|---|
| 2013 | Model year 2013[1]<br>Assembly plant Chattanooga, Tennessee, United States |
| 5 Mar 2014 | Transport Canada recall 2014068[2]<br>Issued for the model year · Accessories |
| 17 Mar 2014 | Transport Canada recall 2014080[2]<br>Issued for the model year · Lights and instruments |
| 31 Jul 2015 | Transport Canada recall 2015344[2]<br>Issued for the model year · Seats and restraints |
| 9 Feb 2016 | Transport Canada recall 2016064[2]<br>Issued for the model year · Airbag |
| 23 Mar 2016 | Transport Canada recall 2016132[2]<br>Issued for the model year · Electrical |
| 10 May 2017 | Transport Canada recall 2017256[2]<br>Issued for the model year · Powertrain |
| 6 Mar 2018 | Transport Canada recall 2018111[2]<br>Issued for the model year · Airbag |
| 17 May 2018 | Transport Canada recall 2018266[2]<br>Issued for the model year · Other |
| 23 May 2019 | Transport Canada recall 2019242[2]<br>Issued for the model year · Lights and instruments |
| 4 Aug 2020 | Transport Canada recall 2020353[2]<br>Issued for the model year · Label |
| 30 Oct 2024 | Transport Canada recall 2024649[2]<br>Issued for the model year · Airbag |
| 27 Nov 2025 | Listed for sale, Scarborough, ON[5]<br>ALEXANDRIA AUTO · asking $8,995 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $8,995 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 18 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.