Register entry, as of 26 October 2026 Listed for sale Record ID 9d114e6411bc

2010 Mazda Mazda6 Base grade

2.5 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1YV	HZ8BH	7	A	5	M11128
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mazda · AUTO ALLIANCE I…	Mazda6 · 2.5 L	Verified	2010	Flat Rock	Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	2.5 L, 4 cylinders
Make	Mazda	Fuel	Gasoline
Model	Mazda6	Drive	Not in the decode
Trim	Base grade	Maker	AUTO ALLIANCE INTERNATIONAL, USA
Body	Sedan	Plant	Flat Rock, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mazda/mazda6/2010

6 recalls listed by Transport Canada for this model year

Airbag

2018597 30 Oct 2018

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected. Additional Note: This is an expansion of recall 2018-040.

Structure

2018504 14 Sep 2018

On certain vehicles registered and operated in areas of heavy road salt usage during winter months (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador), the front cross member may rust due to a manufacturing defect. This could affect vehicle handling and cause reduced steering control, potentially increasing the risk of a crash causing injury and/or property damage. Correction: Dealers will install a drain hose, inspect the cross member and, depending on its condition, replace it or install a reinforcement and apply a wax coating.

Airbag

2016395 10 Aug 2016

On certain vehicles, a defect in the supplemental restraint system (SRS) controller could result in airbags and seatbelt pretensioners failing to deploy in a crash where deployment is warranted. Failure of the SRS components to deploy in a crash could increase the risk of injury. Correction: Dealers will replace the SRS control unit. Note: This condition would cause the illumination of the SRS warning light.

Fuel system

2014075 11 Mar 2014

On certain vehicles equipped with the 2.5L engine, a particular type of spider may weave a web in the evaporative canister vent line which may cause a restriction in the line. If this occurs, the fuel tank pressure may become excessively negative when the emission control system works to purge the vapors from the canister. As the canister is purged repeatedly during normal operation, the stress on the fuel tank may eventually result in a crack causing a fuel leak. Fuel leakage, in the presence of an ignition source, could result in a fire causing injury and/or property damage. Correction: Dealers will inspect the canister vent line and, if a web is found, the fuel tank and check valve on the canister vent line will be replaced. The Powertrain Control Module (PCM) will be reprogrammed with modified software having a function to avoid excessive negative pressure of the fuel tank.

Structure

2013322 23 Sep 2013

On certain vehicles, door latch screws could loosen over time, causing the door(s) to fail to latch when closed and illuminating the door ajar warning light. If the vehicle is driven in this condition, the door(s) could open while the vehicle is in motion, increasing the risk of an accident causing injury and/or property damage. Correction: Dealers will inspect and re-tighten or replace the latch screws.

Fuel system

2011090 28 Feb 2011

On certain vehicles equipped with the 2.5L engine, a particular type of spider may weave a web in the evaporative canister vent line which may cause a restriction in the line. If this occurs, the fuel tank pressure may become excessively negative when the emission control system works to purge the vapors from the canister. As the canister is purged repeatedly during normal operation, the stress on the fuel tank may eventually result in a crack causing a fuel leak. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will clean the canister vent line and install a spring to prohibit spider intrusion. The Powertrain Control Module (PCM) will be reprogrammed with modified software having a function to avoid excessive negative pressure of the fuel tank. When any damage of the fuel tank and/or presence of a web in the canister vent line are found, the fuel tank and the check valve on the canister vent line will be replaced.

> Listed for the model year, not checked against your VIN. Mazda confirms which apply.
> Check your VIN with Mazda Canada or call a Mazda dealer with your VIN.
> www.mazdarecalls.ca/

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $8,950[5], $1,476 over the median of $7,474[4].

Lowest ask	$4,950
Middle half	$5,962 – $8,986
Median ask	$7,474
This car	$8,950

Same model year · 6 live listings · as of 26 Oct 2026

OTHER 2010 MAZDA MAZDA6 LISTINGS [5]

Simcoe, ON · 172,420 km	$5,998
Coquitlam, BC · 177,994 km	$9,722
Toronto, ON · 313,103 km	$5,950
Mississauga, ON · 182,208 km	$4,950

§4 EVENTS

2010	Model year 2010[1] Assembly plant Flat Rock, Michigan, United States
28 Feb 2011	Transport Canada recall 2011090[2] Issued for the model year · Fuel system
23 Sep 2013	Transport Canada recall 2013322[2] Issued for the model year · Structure
11 Mar 2014	Transport Canada recall 2014075[2] Issued for the model year · Fuel system
10 Aug 2016	Transport Canada recall 2016395[2] Issued for the model year · Airbag
14 Sep 2018	Transport Canada recall 2018504[2] Issued for the model year · Structure
30 Oct 2018	Transport Canada recall 2018597[2] Issued for the model year · Airbag
26 Oct 2026	Listed for sale, Surrey, BC[5] Midway Mazda · asking $8,950

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 6 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.