Register entry, as of 29 October 2026 Listed for sale Record ID ae045f6dbefa

2010 Chevrolet Camaro 2SS

6.2 L, 8 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2G1	FK1EJ	0	A	9	147690
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Camaro · 6.2 L	Verified	2010	Oshawa	Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	6.2 L, 8 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Camaro	Drive	Not in the decode
Trim	2SS	Maker	GENERAL MOTORS LLC
Body	Coupe	Plant	Oshawa, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/camaro/2010

3 recalls listed by Transport Canada for this model year

Electrical

2019463 19 Sep 2019

Issue: This recall is for replacement flip key assemblies sold as replacement parts. Please see Transport Canada Recall No. 2014-243 for additional details. There is a risk that some drivers may bump the ignition key with their knee and unintentionally move the key out of the "run" position. If this happens, engine power, power braking and power steering would be affected. This can cause a sudden increase steering and brake pedal effort. This could also cause the airbags not to deploy in a crash. Safety Risk: Airbags that do not deploy properly could create an increased risk of injury in a crash. An increase brake pedal effort could cause extended stopping distances and increase the risk of a crash. Sudden changes in steering effort could also increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the key(s). If a flip key is found, it will be replaced with a flat blade key as in Transport Canada Recall No. 2014-243.

Electrical

2014243 20 Jun 2014

On certain vehicles, there is a risk that some drivers may bump the ignition key with their knee and unintentionally move the key from out of the "run" position. If this were to occur, engine power, power braking and power steering would be affected, which would unexpectedly increase steering and brake pedal effort, potentially increasing stopping distances and the risk of a crash causing injury and/or damage to property. The timing of the key movement out of the "run" position, relative to the activation of the sensing algorithm of the crash event, may also result in the airbags not deploying in a subsequent collision, increasing the risk of injury. Correction: Dealers are to remove the key blade from the original flip key/transmitter assemblies provided with the vehicle, and provide two new keys and two key rings for every original key. Important note: Until the correction is performed, drivers should adjust their seat and steering column to allow clearance between their knee and the ignition key.

Electrical

2009131 7 May 2009

On certain vehicles equipped with a V8 engine, the positive battery cable may contact the starter motor housing, which could cause chafe damage to the cable insulation. If the insulation wears through to the cable it could create an electrical short, which can result in a no start condition, cause the engine to stall without the ability to restart, or cause an engine compartment fire. Engine stalling would result in lost propulsion which, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash. Correction: Dealers will reroute the positive battery cable to ensure adequate clearance.

> Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
> Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
> www.chevrolet.ca/en/ownercenter/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $26,698[5], the median[4].



Lowest ask	$15,950
Middle half	$19,995 – $33,900
Median ask	$26,698
This car	$26,698

Same model year · 9 live listings · as of 29 Oct 2026

OTHER 2010 CHEVROLET CAMARO LISTINGS [5]

Edmonton, AB · 5,293 km	$39,915
Regina, SK · 5,293 km	$39,915
Winnipeg, MB · 5,293 km	$39,915
Winnipeg, MB · 5,293 km	$39,915
Medicine Hat, AB · 56,076 km	$29,900
Ancaster, ON · 38,000 km	$42,995

§4 EVENTS

2010	Model year 2010[1] Assembly plant Oshawa, Ontario, Canada
7 May 2009	Transport Canada recall 2009131[2] Issued for the model year · Electrical
20 Jun 2014	Transport Canada recall 2014243[2] Issued for the model year · Electrical
19 Sep 2019	Transport Canada recall 2019463[2] Issued for the model year · Electrical
26 Oct 2026	Listed for sale, Prescott, ON[5] Riverside Buick GMC Ltd. · asking $26,698

28 Oct 2026	Listing last updated[5] asking $26,698

§5 DOCUMENTS

Window sticker	This VIN reads as model year 1980 or 2010, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 9 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.