Register entry, as of 25 November 2026 Listed for sale Record ID 38ec60548b2c

2009 Buick Allure CX

3.8 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2G4	WF582	0	9	1	192528
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Buick · GENERAL MOTORS…	Allure · 3.8 L	Verified	2009	Oshawa #2	Build sequence

§1 IDENTITY [1]

Model year	2009	Engine	3.8 L, 6 cylinders
Make	Buick	Fuel	Gasoline
Model	Allure	Drive	Not in the decode
Trim	CX	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Oshawa #2, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/allure/2009

3 recalls listed by Transport Canada for this model year

Lights and instruments — 2015365 — 12 Aug 2015

On certain vehicles, the headlamp driver module (HDM) may not operate properly in high underhood temperatures. If the HDM is not operating correctly, the low-beam headlamps and daytime running lamps could fail to illuminate. Loss of daytime running lamps and low-beam headlamps could result in decreased driver's vision, as well as rendering the vehicle less visible to other motorists, which could result in a crash causing injury and/or property damage. Correction: Dealers will replace the headlamp relay (HDM) located in the underhood bussed electrical centre (UBEC). Note: this condition does not affect the high-beam headlamps, marker lamps, turn signals, or fog lamps. Note: This recall supersedes recall 2014-535.

Lights and instruments — 2014535 — 26 Nov 2014

On certain vehicles, the headlamp driver module (HDM) may not operate properly in high underhood temperatures. If the HDM is not operating correctly, the low-beam headlamps and daytime running lamps could fail to illuminate. Loss of daytime running lamps and low-beam headlamps could result in decreased driver's vision, as well as rendering the vehicle less visible to other motorists, which could result in a crash causing injury and/or property damage. Correction: Dealers will replace the headlamp driver module (HDM) with a new design HDM. Note: this condition does not affect the high-beam headlamps, marker lamps, turn signals, or fog lamps. Note: This recall is superseded by recall 2015365.

Electrical — 2014246 — 23 Jun 2014

On certain vehicles, a defect in the ignition switch could allow the switch to move out of the "run" position if the key ring is carrying added weight or the vehicle goes off-road or is subjected to some other jarring event. If this were to occur, engine power, power steering and power braking would be affected, increasing the risk of a crash causing injury and/or damage to property. The timing of the key movement out of the “run” position, relative to the activation of the sensing algorithm of the crash event, may also result in the airbags not deploying in a subsequent collision, increasing the risk of injury. Correction: For each key, dealers will install two key rings and modify the key ring opening shape. Note: Until the correction is performed, all items should be removed from the key ring.

> Listed for the model year, not checked against your VIN. Buick confirms which apply.
> Check your VIN with Buick Canada or call a Buick dealer with your VIN.
> www.buick.ca/en/ownercenter/recalls

§3 VALUE [3]

This car asks $4,522[4], the median[3].



Lowest ask	$4,522
Middle half	$4,522 – $4,522
Median ask	$4,522
This car	$4,522

Same model year · 1 live listings · as of 25 Nov 2026

§4 EVENTS

2009	Model year 2009[1] Assembly plant Oshawa #2, Ontario, Canada
23 Jun 2014	Transport Canada recall 2014246[2] Issued for the model year · Electrical
26 Nov 2014	Transport Canada recall 2014535[2] Issued for the model year · Lights and instruments
12 Aug 2015	Transport Canada recall 2015365[2] Issued for the model year · Lights and instruments
18 Nov 2026	Listed for sale, Mississauga, ON[4] 401 Dixie Volkswagen · asking $4,522
25 Nov 2026	Listing last updated[4] asking $4,522

§5 DOCUMENTS

Window sticker	This VIN reads as model year 2009, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 1 live listings, as of 25 Nov 2026
[4] Live public dealer listings on Cardog, as of 25 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.