Register entry, as of 28 November 2026 Listed for sale Record ID c89790016c1b

2022 Honda Civic Sport

2.0 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2HG	FE2F5	2	N	H	123149
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Honda Of Canada Mfg., A…	Civic · 2.0 L	Verified	2022	Alliston	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	2.0 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	Civic	Drive	4x2
Trim	Sport	Maker	HONDA OF CANADA MFG., A DIVISION OF HONDA CANADA INC.
Body	Sedan	Plant	Alliston, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/civic/2022

5 recalls listed by Transport Canada for this model year

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Wheels

2025599 30 Oct 2025

Issue: This recall is for certain aluminum wheels that were installed before delivery or sold as a dealer accessory. On certain vehicles, the wheels may not have been manufactured properly. As a result, the wheel nut(s) could loosen and cause the wheel(s) to detach. Safety Risk: A wheel separation could cause a loss of control and increase the risk of a crash. Additionally, a wheel that separates could create a road hazard for others. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the hub(s), wheel(s) and wheel nut(s).

Steering

2024588 3 Oct 2024

Issue: On certain vehicles, the steering gearbox may not have been manufactured properly. As a result, there could be a sudden change in steering feel and an increase in steering effort. Safety Risk: A sudden change in steering effort could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to add grease to the steering gearbox and replace the electronic power steering spring.

Airbag

2024059 1 Feb 2024

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Steering

2023562 19 Oct 2023

Issue: On certain vehicles, the incorrect steering gear box assembly may have been installed during a repair. As a result, the tires could become damaged by contact with the chassis and fail. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the steering gear box assembly. The dealer will also inspect the tires for damage and replace them, as necessary.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $19,998[5], $3,864 under the median of $23,862[4].



Lowest ask	$17,999
Middle half	$21,903 – $25,381
Median ask	$23,862
This car	$19,998

Same configuration · 90 live listings · as of 28 Nov 2026

OTHER 2022 HONDA CIVIC LISTINGS [5]

Langley, BC · 62,529 km	$22,127
Mississauga, ON · 111,416 km	$22,995
Ajax, ON · 108,884 km	$22,499
Antigonish, NS · 64,879 km	$23,122
Chilliwack, BC · 119,620 km	$24,900
Winnipeg, MB · 50,304 km	$23,988

§4 EVENTS

2022	Model year 2022[1] Assembly plant Alliston, Ontario, Canada
19 Oct 2023	Transport Canada recall 2023562[2] Issued for the model year · Steering
1 Feb 2024	Transport Canada recall 2024059[2] Issued for the model year · Airbag

3 Oct 2024	Transport Canada recall 2024588[2] Issued for the model year · Steering
30 Oct 2025	Transport Canada recall 2025599[2] Issued for the model year · Wheels
21 May 2026	Transport Canada recall 2026251[2] Issued for the model year · Seats and restraints
27 Nov 2026	Listed for sale, New Westminster, BC[5] Westminster Toyota · asking $19,998

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 90 live listings, as of 28 Nov 2026
[5] Live public dealer listings on Cardog, as of 28 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.