Register entry, as of 29 October 2026 Listed for sale Record ID 3d2f4b6c4300

# 2024 Toyota RAV4 XLE

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 2T3 | RWRFV | 5 | R | W | 202273 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Toyota Motor Manufacturi… | RAV4 · 2.5 L | Verified | 2024 | Woodstock | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2024 | Engine | 2.5 L, 4 cylinders |
| Make | Toyota | Fuel | Gasoline |
| Model | RAV4 | Drive | 4WD |
| Trim | XLE | Maker | TOYOTA MOTOR MANUFACTURING CANADA |
| Body | Sport Utility Vehicle | Plant | Woodstock, Ontario, Canada |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/rav4/2024

**3** recalls listed by Transport Canada for this model year

### Visual system

2025594 30 Oct 2025

Issue: Under certain conditions, a software problem could cause the rearview camera image to freeze or not to display. If this happens, the rearview image may not display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall only affects certain vehicles equipped with a panoramic view monitor system. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: The company will notify owners in writing and advise you to take your vehicle to a dealership to update the parking assist ECU software.

### Visual system

2025469 11 Sep 2025

Issue: On certain vehicles, a software problem could cause the combination meter in the instrument panel not to display when the vehicle is started. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, warning lights and malfunction tell-tales. Note: This recall only affects vehicles equipped with a 12.3-inch display. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to update the combination meter software. Alternatively, certain eligible vehicles will be sent a wireless over-the-air software update, which you can install yourself. For certain vehicles, the dealer will also inspect and, if necessary, replace the combination meter.

### Brakes

2024737 5 Dec 2024

Issue: On a small number of vehicles, the bolts that secure the front brake caliper mounting bracket(s) and the wheel hub(s) to the steering knuckle(s) may not have been tightened properly. As a result, the caliper(s) could move and cause the brake hose(s) to become damaged. If this happens, brake fluid could leak and cause reduced braking. Additionally, the hub bolts could loosen and cause the front wheel(s) to separate from the vehicle. Safety Risks: Reduced braking can cause extended stopping distances and increase the risk of a crash. A wheel separation could cause a loss of control and increase the risk of a crash. A wheel that separates could also create a hazard for others. Corrective Actions: The company will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the front brake caliper bracket and wheel hub bolts. The dealer will replace any damaged components, as necessary.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $40,000[5], $5 over the median of $39,995[4].




| | |
|---|---|
| Lowest ask | $31,995 |
| Middle half | $38,890 – $43,000 |
| Median ask | $39,995 |
| This car | $40,000 |

Same configuration · 53 live listings · as of 29 Oct 2026

### OTHER 2024 TOYOTA RAV4 LISTINGS [5]

| | |
|---|---|
| Gatineau, QC · 69,786 km | $34,988 |
| Vaughan, ON · 42,967 km | $34,998 |
| Dieppe, NB · 61,593 km | $35,991 |
| Laval, QC · 42,697 km | $39,595 |
| Gatineau, QC · 25,810 km | $37,995 |
| Richmond Hill, ON · 0 km | $37,704 |

## §4 EVENTS

| | |
|---|---|
| 2024 | Model year 2024[1]<br>Assembly plant Woodstock, Ontario, Canada |
| 5 Dec 2024 | Transport Canada recall 2024737[2]<br>Issued for the model year · Brakes |
| 11 Sep 2025 | Transport Canada recall 2025469[2]<br>Issued for the model year · Visual system |
| 30 Oct 2025 | Transport Canada recall 2025594[2]<br>Issued for the model year · Visual system |

| | |
|---|---|
| 26 Oct 2026 | Listed for sale, Windsor, ON[5]<br>Lexus of Windsor · asking $40,000 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $40,000 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 53 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.