Register entry, as of 28 October 2026 Listed for sale Record ID e39d2459f6b4

2022 GMC Sierra Elevation

2.7 L, 4 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3GT	PUCEK	X	N	G	661892
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
GMC · GENERAL MOTORS…	Sierra · 2.7 L	Verified	2022	Silao	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	2.7 L, 4 cylinders
Make	GMC	Fuel	Gasoline
Model	Sierra	Drive	4WD
Trim	Elevation	Maker	GENERAL MOTORS LLC
Body	Pickup	Plant	Silao, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/gmc/sierra/2022

9 recalls listed by Transport Canada for this model year

Engine

2025225 24 Apr 2025

Issue: On certain vehicles, the connecting rods and/or crankshaft components may not have been manufactured properly. As a result, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This recall only affects certain vehicles equipped with a 6.2 L V8 gas engine. Safety Risk: An engine failure could cause a sudden loss of power to the wheels and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to inspect and, if necessary, repair or replace the engine. For vehicles that pass the engine inspection, the dealer will replace the oil with a higher viscosity oil, install a new oil fill cap, replace the oil filter, and add an insert to the owner's manual.

Structure

2025052 6 Feb 2025

Issue: On certain trucks, the front grille deflector may not have been manufactured properly. As a result, the deflector could detach from the vehicle. Note: This recall only affects certain trucks equipped with a chrome front grille deflector. Safety Risk: A front grille deflector that detaches from the vehicle could create a hazard for others and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail. The corrective actions for this recall are under development.

Powertrain

2024637 24 Oct 2024

Issue: Over time, the transmission control valve could wear and lose pressure. If this happens, the transmission could shift harshly and could cause the rear wheels to lock up. Note: This recall only affects vehicles equipped with a diesel engine. Safety Risk: Rear wheels that lock suddenly could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to update the transmission control module software to detect excess wear in advance of a wheel lock up. If detected, a service engine light would turn on, a message would display in the instrument panel and the vehicle would be limited to fifth gear.

Structure

2024061 1 Feb 2024

Issue: On certain trucks, water could leak into the exterior tailgate switch. As a result, the tailgate could unlatch and open unexpectedly while parked. If this happens, cargo that is not secured could fall out of the truck bed and onto the road when the vehicle is moving. Note: This recall only affects trucks equipped with a power-locking tailgate. Safety Risk: Cargo that falls from the truck bed could create a road hazard for others and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your truck to a dealership to replace the exterior tailgate switch. To reduce the safety risk, General Motors recommends that you should inspect the tailgate to ensure it's closed and latched before driving.

Lights and instruments

2024060 1 Feb 2024

Issue: On certain vehicles, a software problem could cause the lower beam headlamps not to turn on as it becomes dark outside if the multi-function switch is in the "OFF" or "PARKING LAMP" position. This could also cause the daytime running lamps (DRLs) to turn off when the vehicle is moving. As a result, the vehicles may not meet certain requirements of Canadian regulations. Safety Risk: Headlamps and/or DRLs that don't turn on could reduce visibility, make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to update the body control module (BCM)software.

Lights and instruments

2023472 24 Aug 2023

Issue: On certain vehicles, the automatic headlamps may not turn on soon enough as it becomes dark outside. Canadian regulations require automatic headlamps to turn on when the ambient light level drops below a certain point (1000 lux). Safety Risk: Headlamps that don't turn on as it becomes dark outside could reduce visibility and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the body control module (BCM) software. Alternatively, you may schedule an appointment to have the update performed at a GM dealership.

3 more on the model-year record, cardog.app/tools/recalls/gmc/sierra/2022

> Listed for the model year, not checked against your VIN. GMC confirms which apply.
> Check your VIN with GMC Canada or call a GMC dealer with your VIN.
> www.gmccanada.ca/en/ownercenter/recalls

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $44,821[5], $4,939 over the median of $39,882[4].

Lowest ask	$25,995
Middle half	$36,094 – $43,233
Median ask	$39,882
This car	$44,821

Same configuration · 18 live listings · as of 28 Oct 2026

OTHER 2022 GMC SIERRA LISTINGS [5]

Kindersley, SK · 105,965 km	$52,890
Deer Lake, NL · 128,651 km	$57,454
St-Léonard, QC · 109,405 km	$43,995
St-Jérôme, QC · 109,405 km	$43,995
Repentigny (Québec), QC · 109,405 km	$43,995
Yarmouth, NS · 68,255 km	$47,995

§4 EVENTS

2022	Model year 2022[1] Assembly plant Silao, Mexico
31 Mar 2022	Transport Canada recall 2022160[2] Issued for the model year · Accessories
30 Jun 2022	Transport Canada recall 2022348[2] Issued for the model year · Lights and instruments
8 Dec 2022	Transport Canada recall 2022700[2] Issued for the model year · Lights and instruments
24 Aug 2023	Transport Canada recall 2023472[2] Issued for the model year · Lights and instruments
1 Feb 2024	Transport Canada recall 2024061[2] Issued for the model year · Structure
1 Feb 2024	Transport Canada recall 2024060[2] Issued for the model year · Lights and instruments
24 Oct 2024	Transport Canada recall 2024637[2] Issued for the model year · Powertrain
6 Feb 2025	Transport Canada recall 2025052[2] Issued for the model year · Structure
24 Apr 2025	Transport Canada recall 2025225[2] Issued for the model year · Engine
25 Oct 2026	Listed for sale, Huntsvillle, ON[5] Edmonds GM · asking $44,821
27 Oct 2026	Listing last updated[5] asking $44,821

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 18 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.