Register entry, as of 27 October 2026 Listed for sale Record ID 44ade3e5fca5

2010 Cadillac SRX Base

3.0 L, 6 cylinders · FWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3GY	FNGEY	5	A	S	655214
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Cadillac · GENERAL MOTO…	SRX · 3.0 L	Verified	2010	Ramos Arizpe	Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	3.0 L, 6 cylinders
Make	Cadillac	Fuel	Gasoline
Model	SRX	Drive	FWD
Trim	Base	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Ramos Arizpe, Coahuila, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/cadillac/srx/2010

6 recalls listed by Transport Canada for this model year

Suspension — 2021394 — 24 Jun 2021

Issue: On certain vehicles, the adjustable rear toe link may not have been properly tightened during a previous service repair. As a result, the toe link could loosen and eventually separate. This could cause a sudden loss of vehicle stability. Note: You may notice the following warning symptoms if a rear toe link is loose: - sway or wander while driving; - loud metallic or other unusual noise from the rear suspension; - the steering wheel may be off-center; - the Stabilitrak malfunction indicator lamp (MIL) may stay on or flash while driving; - Uneven wear between the rear tires. If you detect these symptoms, you should stop driving and have the vehicle towed to the nearest dealership. Safety Risk: A loss of stability could increase the risk of a crash. Corrective Action: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to replace the adjustable rear toe links with a newly designed part.

Suspension — 2014406 — 18 Sep 2014

On certain vehicles, the rear suspension toe link jam nuts may not have been tightened to specification. If the vehicle is operated in this condition, the toe link nuts could loosen and eventually separate, allowing the rear wheel to turn inboard or outboard. If this were to happen, sudden changes in vehicle handling could occur, which could result in a crash causing injury and/or property damage. Correction: Dealers will inspect and ensure the rear suspension toe link nuts are tightened to specification. If required, the rear suspension toe link will be replaced.

Seats and restraints — 2014311 — 23 Jul 2014

On certain vehicles equipped with power height adjustable front seats, a bolt securing the adjuster mechanism may loosen and fall out. This would cause the seat to drop to the lowest vertical adjustment position, which could affect the driver's ability to safety operate vehicle controls as well as cause reduced driver visibility. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the bolt.

Powertrain

2011437 21 Dec 2011

On certain vehicles, the transmission shift cable may have been improperly installed during vehicle assembly. If the cable separates from the transmission, the driver would be unable to shift in or out of gear. As such, the shift lever could be moved into the PARK position while the transmission is still in the last used gear before detachment. If the driver leaves the vehicle without engaging the parking brake, the vehicle could roll away. A rollaway vehicle could strike another vehicle, stationary object, or a bystander, causing property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, correct the transmission shift cable installation.

Steering

2010325 30 Sep 2010

On certain vehicles, processing of the crimp during manufacture of the power steering pressure line may have damaged the line. If the line was damaged, a power steering fluid leak may develop. If there is a sufficient amount of fluid loss, the driver will hear noise from the power steering pump and increased effort may be required for steering. If power steering fluid flows onto hot engine parts, an engine compartment fire could occur which may result in property damage or personal injury. Correction: Dealers will replace the power steering line on vehicles equipped with a 2.8L engine (LAU). Dealers will also inspect, and if necessary replace the power steering line on vehicles equipped with a 3.0L engine (LF1).

Engine

2010170 28 May 2010

On certain vehicles equipped with a 2.8L V6 engine, if low octane (regular) fuel is used in the vehicle instead of the required high octane (premium) fuel, as stated in the owner manual and on the fuel filler door, the combination of regular fuel usage and aggressive driving maneuvers may induce pre-ignition. If pre-ignition occurs, the driver will hear a pinging or knocking sound from the engine, and if the vehicle continues to be driven after the onset of this noise a connecting rod or piston may break, resulting in engine failure which would disable the vehicle, increasing the risk of a crash causing property damage, personal injury or death. Correction: Dealers will reprogram the engine control module.

> Listed for the model year, not checked against your VIN. Cadillac confirms which apply.
> Check your VIN with Cadillac Canada or call a Cadillac dealer with your VIN.
> www.cadillaccanada.ca/en/ownercenter/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $6,995[5], the median[4].

Lowest ask	$3,394
Middle half	$4,995 – $7,980
Median ask	$6,995
This car	$6,995

Same model year · 5 live listings · as of 27 Oct 2026

OTHER 2010 CADILLAC SRX LISTINGS [5]

Gananoque, ON · 75,873 km	$8,000
Vaudreuil-Dorion, QC · 228,471 km	$4,995
North York, ON · 130,000 km	$7,980
Sudbury, ON · 203,163 km	$3,394

§4 EVENTS

2010 **Model year 2010**[1]
Assembly plant Ramos Arizpe, Coahuila, Mexico

28 May 2010	Transport Canada recall 2010170[2] Issued for the model year · Engine
30 Sep 2010	Transport Canada recall 2010325[2] Issued for the model year · Steering
21 Dec 2011	Transport Canada recall 2011437[2] Issued for the model year · Powertrain
23 Jul 2014	Transport Canada recall 2014311[2] Issued for the model year · Seats and restraints
18 Sep 2014	Transport Canada recall 2014406[2] Issued for the model year · Suspension
24 Jun 2021	Transport Canada recall 2021394[2] Issued for the model year · Suspension
25 Oct 2026	Listed for sale, St. Catharines, ON[5] Eastway Auto Service Ltd · asking $6,995
26 Oct 2026	Listing last updated[5] asking $6,995

§5 DOCUMENTS

Window sticker This VIN reads as model year 1980 or 2010, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 5 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.