Register entry, as of 28 October 2026 Listed for sale Record ID 4ffbb8353832

2013 Lincoln MKZ

3.7 L, 6 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3LN	6L2JK	7	D	R	821028
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Lincoln · FORD MOTOR CO…	MKZ · 3.7 L	Verified	2013	Hermosillo	Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	3.7 L, 6 cylinders
Make	Lincoln	Fuel	Gasoline
Model	MKZ	Drive	AWD
Trim	Not in the decode	Maker	FORD MOTOR COMPANY, MEXICO
Body	Sedan	Plant	Hermosillo, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lincoln/mkz/2013

11 recalls listed by Transport Canada for this model year

Brakes

2023132 14 Mar 2023

Issue: On certain vehicles, the front brake hoses could fail and cause a progressive brake fluid leak. If this happens, the driver may experience a change in brake pedal feel and travel. This can cause reduced braking. Note: A brake fluid leak would cause the brake warning light to turn on. This recall doesn't affect models with a Hybrid engine. Vehicles repaired under Ford warranty extension program 22N02 already have updated brake hoses, and don't require this repair. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and instruct you to take your vehicle to a dealership to replace the front brake hoses.

Steering

2019431 27 Aug 2019

Issue: On certain vehicles, the bolts that attach the electric power steering assist motor to the steering gear may corrode and break. This could cause a loss of power steering assist. This recall applies to vehicles originally sold or currently registered in areas of heavy road salt usage (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). Safety Risk: A loss of power steering assist may result in a sudden increase in steering effort, especially at low vehicle speeds. This could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a Ford or Lincoln dealer to replace the bolts and apply a wax sealer. If one or more of the bolts are broken or missing, a new steering gear will be installed.

Structure

2017183 29 Mar 2017

On certain vehicles, the door latches may have a broken pawl spring tab. This could result in the door not latching correctly. As a result, doors which appear to be latched could unlatch while driving. This could increase the risk of injury to a vehicle occupant seated next to the door, or result in damage to property. Correction: Dealers will replace all four door latches with a more robust part. Note: This is an expansion of recall 2015-175.

Seats and restraints

2016601 1 Dec 2016

On certain vehicles, deployment of the driver or front passenger seatbelt pretensioner in a crash may generate internal pretensioner temperatures that can degrade the tensile strength of the outboard seat belt anchor cable. This could result in the seat belt not adequately restraining the seat occupant in a crash, increasing the risk of injury and/or damage to property. Correction: Dealers will apply a coating to protect the pretensioner's cables.

Steering

2015177 28 Apr 2015

On certain vehicles registered and operated in areas where road salt is used on the roadways during winter months for extended time periods (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island and Newfoundland-Labrador), corrosion may occur at the steering gear motor attachment bolts. Steering gear motor detachment from the gear housing could result in sudden loss of steering power assist. This would cause the Electronic Stability Control and Traction Control malfunction indicator lamps to illuminate. A vehicle experiencing a loss of steering power assist would revert to a manual steering mode which would require greater driver effort, especially at low vehicle speeds. A loss of steering power assist could ultimately result in a crash causing property damage and/or personal injury. Correction: Dealers will apply sealer and replace the steering gear motor attachment bolts as required. If one or more of the steering gear motor attachment bolds are broken or missing, a new steering gear will be installed in the vehicle.

Structure

2015175 24 Apr 2015

On certain vehicles, the door latches may have a broken pawl spring tab. This could result in the door not latching correctly. As a result, doors which appear to be latched could unlatch while driving. This could increase the risk of injury to a vehicle occupant seated next to the door, or result in damage to property. Correction: Dealers will replace all four door latches with a more robust part.

5 more on the model-year record, cardog.app/tools/recalls/lincoln/mkz/2013

> Listed for the model year, not checked against your VIN. Lincoln confirms which apply.
> Check your VIN with Lincoln Canada or call a Lincoln dealer with your VIN.
> www.lincolncanada.com/support/recalls/

United States: 13 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $7,999[5], $1,489 under the median of $9,488[4].

Lowest ask	$7,999
Middle half	$8,744 – $10,232
Median ask	$9,488
This car	$7,999

Same model year · 2 live listings · as of 28 Oct 2026

OTHER 2013 LINCOLN MKZ LISTINGS [5]

Calgary, AB · 190,956 km	$10,977
North Vancouver District, BC · 165,280 km	$7,173

§4 EVENTS

2013 Model year 2013[1]
Assembly plant Hermosillo, Mexico

29 May 2013	Transport Canada recall 2013187[2] Issued for the model year · Electrical
29 May 2013	Transport Canada recall 2013186[2] Issued for the model year · Fuel system
27 Nov 2013	Transport Canada recall 2013425[2] Issued for the model year · Powertrain
2 Apr 2014	Transport Canada recall 2014109[2] Issued for the model year · Seats and restraints
30 Sep 2014	Transport Canada recall 2014427[2] Issued for the model year · Seats and restraints
24 Apr 2015	Transport Canada recall 2015175[2] Issued for the model year · Structure
28 Apr 2015	Transport Canada recall 2015177[2] Issued for the model year · Steering
1 Dec 2016	Transport Canada recall 2016601[2] Issued for the model year · Seats and restraints
29 Mar 2017	Transport Canada recall 2017183[2] Issued for the model year · Structure
27 Aug 2019	Transport Canada recall 2019431[2] Issued for the model year · Steering
14 Mar 2023	Transport Canada recall 2023132[2] Issued for the model year · Brakes
25 Oct 2025	Listed for sale, Edmonton, AB[5] Parkdale Motors · asking $7,999
28 Oct 2026	Listing last updated[5] asking $7,999

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 2 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.