Register entry, as of 29 October 2026 Listed for sale Record ID 1c8ace868cf5

2016 Toyota Yaris

1.5 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3MY	DLBYV	6	G	Y	110685
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota · MAZDA MOTOR…	Yaris · 1.5 L	Verified	2016	Guanajuato	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	1.5 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	Yaris	Drive	Not in the decode
Trim	Not in the decode	Maker	MAZDA MOTOR MANUFACTURING DE MEXICO S.A. DE C.V.
Body	Sedan	Plant	Guanajuato, Salamanca, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/yaris/2016

4 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Airbag

2019197 23 Apr 2019

Issue: Over time, the wiring to the side airbag sensors in the front doors could corrode. This could cause the front seat-mounted side airbags and curtain shield airbags not to work properly. Note: This problem would cause the airbag warning light (SRS warning) to turn on. Safety Risk: Airbags that do not work properly in a crash could create an increased risk of injury. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to replace the front door wire harness assemblies, as necessary.

Electrical

2017363 20 Jul 2017

On certain vehicles, the electrical power cords of some dealer installed block heaters may have been improperly manufactured, causing the wires to contact each other, resulting in a short circuit. A short circuit could lead to a fire which would increase the risk of injury and/or damage to property. Correction: For vehicles where the subject block heater was approved for installation, the dealer will replace the block heater assembly with a new one of an improved design. For vehicles where the subject block heater was not approved for installation, dealers will remove the block heater assembly. In the interim, until the remedy can be performed, dealers will cut the plug end from the block heater cord to disable the block heater's operation.

Label

2017117 7 Mar 2017

Certain vehicles may have an incorrect compliance label that does not meet the requirements of the Motor Vehicle Safety Regulations. The vehicle's compliance label was misprinted with an incorrect manufacturing date of "12/99". Correction: Dealers will replace the compliance label with a corrected one.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $11,995[5], $2,203 under the median of $14,198[4].



Lowest ask	$9,999
Middle half	$12,370 – $14,992
Median ask	$14,198
This car	$11,995

Same model year · 12 live listings · as of 29 Oct 2026

OTHER 2016 TOYOTA YARIS LISTINGS [5]

Kelowna, BC · 86,650 km	$15,995
Val-David, QC · 76,998 km	$14,997
Granby, QC · 142,719 km	$13,229
St Catharines, ON · 176,245 km	$12,495
Chilliwack, BC · 127,832 km	$18,900
Ottawa, ON · 89,000 km	$14,990

§4 EVENTS

2016	Model year 2016[1] Assembly plant Guanajuato, Salamanca, Mexico
7 Mar 2017	Transport Canada recall 2017117[2] Issued for the model year · Label
20 Jul 2017	Transport Canada recall 2017363[2] Issued for the model year · Electrical

23 Apr 2019	Transport Canada recall 2019197[2] Issued for the model year · Airbag
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
29 Oct 2026	Listed for sale, Montréal, QC[5] Toyota Gabriel Centre-Ville · asking $11,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 12 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.