Register entry, as of 29 October 2026 Listed for sale Record ID c923b7ceedb2

# 2017 Nissan Sentra

1.8 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3N1 | AB7AP | 8 | H | L | 672005 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Nissan Mexicana, S.A. De C... | Sentra · 1.8 L | Verified | 2017 | Aguascalientes | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2017 | Engine | 1.8 L, 4 cylinders |
| Make | Nissan | Fuel | Gasoline |
| Model | Sentra | Drive | 4x2 |
| Trim | Not in the decode | Maker | NISSAN MEXICANA, S.A. DE C.V. |
| Body | Sedan | Plant | Aguascalientes, Aguascalientes, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/sentra/2017

**4** recalls listed by Transport Canada for this model year

### Brakes

2021114 4 Mar 2021

Issue: On certain vehicles, the stop lamp switch could fail. If this happens, the brake lights may not turn on when the brakes are applied and it may not be possible to start the engine. Safety Risk: Brake lights that do not work properly could result in road users being confused of the driver's intentions, and increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your vehicle to a dealer to replace the stop lamp switch. The dealer will also install a grommet to protect the switch.

### Electrical

2018440 22 Aug 2018

On certain vehicles equipped with a mechanical key ignition system, a spring in the ignition switch could wear and break. This may allow the ignition key to inadvertently move from the ON position to the accessory (ACC) position while driving, causing the engine to shut off and the airbag system to lose power. The resulting loss of motive power, and change in steering and brake forces could increase the risk of a crash causing injury and/or damage to property. Additionally, in the event of a crash, this may also cause the airbags not to function. Correction: Dealers will inspect the lot number of the ignition switch, and replace it with a new one if it is affected. Note: Until the correction is performed, owners are advised to remove all objects from the ignition key ring, such as additional keys, key chains, etc.

### Airbag

2017385 4 Aug 2017

On certain vehicles, the passenger's frontal airbag may not deploy correctly due to an issue in manufacturing. As a result of long-term storage, there could be insufficient compression strength of the coolant within the inflator housing of the passenger's frontal airbag, which may cause the airbag to fail to deploy properly in the event of a crash (where deployment is warranted), which could increase the risk of injury to the front passenger occupant. Correction: Dealers will replace the passenger's frontal airbag inflator. Note: This is an expansion of recall 2017-215.

### Airbag

2017215 18 Apr 2017

On certain vehicles, the passenger's frontal airbag may not deploy correctly due to an issue in manufacturing. As a result of long-term storage, there could be insufficient compression strength of the coolant within the inflator housing of the passenger's frontal airbag, which may cause the airbag to fail to deploy properly in the event of a crash (where deployment is warranted), which could increase the risk of injury to the front passenger occupant. Correction: Dealers will replace the passenger's frontal airbag inflator.

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $9,499[5], the median[4].

| | |
|---|---|
| Lowest ask | $5,895 |
| Middle half | $8,120 – $10,916 |
| Median ask | $9,499 |
| This car | $9,499 |

Same configuration · 30 live listings · as of 29 Oct 2026

OTHER 2017 NISSAN SENTRA LISTINGS [5]

| | |
|---|---|
| Surrey, BC · 129,650 km | $10,000 |
| Longueuil, QC · 144,161 km | $12,966 |
| Saskatoon, SK · 102,485 km | $10,735 |
| Brossard, QC · 104,482 km | $8,995 |
| Nipawin, SK · 102,485 km | $10,735 |
| Saskatoon, SK · 102,485 km | $10,735 |

## §4 EVENTS

| | |
|---|---|
| 2017 | Model year 2017[1]<br>Assembly plant Aguascalientes, Aguascalientes, Mexico |
| 18 Apr 2017 | Transport Canada recall 2017215[2]<br>Issued for the model year · Airbag |
| 4 Aug 2017 | Transport Canada recall 2017385[2]<br>Issued for the model year · Airbag |
| 22 Aug 2018 | Transport Canada recall 2018440[2]<br>Issued for the model year · Electrical |
| 4 Mar 2021 | Transport Canada recall 2021114[2]<br>Issued for the model year · Brakes |

| | |
|---|---|
| 13 Oct 2026 | Listed for sale, Pickering, ON[5]<br>Hakim Auto Sales · asking $9,499 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $9,499 |

## §5 DOCUMENTS

Window sticker — We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 30 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.