Register entry, as of 29 October 2026 Listed for sale Record ID d5e7694b2ca0

# 2022 Volkswagen Tiguan 4Motion SE

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3VV | 2B7AX | 5 | N | M | 063513 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Volkswagen De Mexico Sa… | Tiguan · 2.0 L | Verified | 2022 | Puebla | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | 2.0 L, 4 cylinders |
| Make | Volkswagen | Fuel | Gasoline |
| Model | Tiguan | Drive | AWD |
| Trim | 4Motion SE | Maker | VOLKSWAGEN DE MEXICO SA DE CV |
| Body | Sport Utility Vehicle | Plant | Puebla, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/tiguan/2022

**4** recalls listed by Transport Canada for this model year

### Visual system

2022382 20 Jul 2022

Issue: Under certain conditions, the rearview camera image may not appear on the center screen. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to update the infotainment software.

### Structure

2022170 6 Apr 2022

Issue: This recall is for accessory rear hatch spoilers that were installed on a new vehicle or sold as an accessory part at a Volkswagen dealership. On certain vehicles, the rear spoiler might not be properly attached to the hatch. As a result, the spoiler could detach from the vehicle while driving. Safety Risk: A spoiler that detaches from the vehicle could create a hazard for other drivers and nearby people. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to replace the rear hatch spoiler.

### Suspension

2022132 23 Mar 2022

Issue: On certain vehicles, the rear suspension knuckles could crack and/or break. A rear knuckle that breaks while driving could cause a sudden loss of vehicle stability. Safety Risk: A loss of vehicle stability could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to inspect and, if necessary, replace one or both rear suspension knuckles.

### Brakes

2021672 3 Nov 2021

Issue: On certain vehicles, the brake pipe nut at the right-front wheel well may not have been properly tightened. As a result, the nut could loosen and create a brake fluid leak. If this happens, there could be a partial loss of braking and the brake warning lamp may turn on. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to inspect, and if necessary, tighten the right-front brake pipe nut.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $26,998[5], $3,435 over the median of $23,563[4].

| | |
|---|---|
| Lowest ask | $16,950 |
| Middle half | $21,940 – $25,751 |
| Median ask | $23,563 |
| This car | $26,998 |

Same configuration · 59 live listings · as of 29 Oct 2026

### OTHER 2022 VOLKSWAGEN TIGUAN LISTINGS [5]

| | |
|---|---|
| Truro, NS · 122,519 km | $23,995 |
| Mirabel, QC · 120,904 km | $20,992 |
| Mirabel, QC · 33,537 km | $24,844 |
| Greenwood, NS · 83,600 km | $19,998 |
| St-Eustache, QC · 95,200 km | $30,492 |
| Richmond, BC · 47,725 km | $27,995 |

## §4 EVENTS

| | |
|---|---|
| 2022 | Model year 2022[1]<br>Assembly plant Puebla, Mexico |
| 3 Nov 2021 | Transport Canada recall 2021672[2]<br>Issued for the model year · Brakes |
| 23 Mar 2022 | Transport Canada recall 2022132[2]<br>Issued for the model year · Suspension |
| 6 Apr 2022 | Transport Canada recall 2022170[2]<br>Issued for the model year · Structure |
| 20 Jul 2022 | Transport Canada recall 2022382[2]<br>Issued for the model year · Visual system |

| | |
|---|---|
| 26 Oct 2026 | Listed for sale, Gatineau, QC[5]<br>Hull Chrysler · asking $26,998 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $26,998 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 59 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.