Register entry, as of 17 November 2026 Listed for sale Record ID 8d83ae3be8f0

# 2015 Volkswagen Golf

1.8 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3VW | 117AU | 8 | F | M | 065886 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Volkswagen De Mexico Sa… | Golf · 1.8 L | Verified | 2015 | Puebla | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2015 | Engine | 1.8 L, 4 cylinders |
| Make | Volkswagen | Fuel | Gasoline |
| Model | Golf | Drive | Not in the decode |
| Trim | Not in the decode | Maker | VOLKSWAGEN DE MEXICO SA DE CV |
| Body | Hatchback | Plant | Puebla, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/golf/2015

**13** recalls listed by Transport Canada for this model year

### Fuel system

2024095 14 Feb 2024

Issue: On certain vehicles, a seal for the suction jet pump inside the fuel tank could fail. As a result, fuel may flow directly into the evaporative emission control system (EVAP). If this happens, fuel could leak from the charcoal canister. Note: This problem could cause a fuel odor, the fuel nozzle to stop early and/or fuel to spill when refueling. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the suction jet pump.

### Fabrics

2021326 26 May 2021

Issue: On certain models, the chrome layer could peel off of the trim located around the gear shift cover. If this happens, sharp edges can be created. Safety Risk: Exposed sharp edges can create the risk of a cut. Corrective Actions: Volkswagen will contact owners by mail and instruct you to take your vehicle to a dealer to replace the gear shift cover trim frame.

### Label

2020353 4 Aug 2020

Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.

### Powertrain 2019423 22 Aug 2019

Issue: On certain vehicles, a build-up of silicate on the shift lever switch could cause the transmission to detect that it is in the Park position when it isn't. This could allow the ignition key to be removed when the transmission is not in the Park position. If the parking brake is not applied, this could allow the car to roll away. Safety Risk: If the transmission position is not displayed correctly, a user may not know that the vehicle is not in the PARK position. If the parking brake is not applied, this could create a risk of a vehicle roll-away and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have a new shift lever micro switch and control unit installed.

### Suspension 2019116 6 Mar 2019

Issue: On certain vehicles, the rear suspension coil springs may not have been properly manufactured and could break over time. This could cause damage to a rear tire, resulting in rapid air loss and/or tire failure. Safety Risk: A rear tire failure could affect vehicle control. Additionally, a broken coil spring could also create a road hazard for other motorists. Both of these conditions may increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have both of the rear axle coil springs replaced. If a broken coil spring is found, the rear tires should be inspected for damage and replaced as required.

### Powertrain 2018371 11 Jul 2018

On certain vehicles, the park position switch may malfunction due to a problem with the electrical contacts. This could allow for removal of the ignition key without the shift lever being in the Park (P) position. If the parking brake is not applied, this could result in unintended vehicle movement, which could increase the risk of crash causing injury and/or damage to property. Correction: Dealers will install an additional park position switch and circuit board.

7 more on the model-year record, cardog.app/tools/recalls/volkswagen/golf/2015

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply. Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $10,998[5], $3 over the median of $10,995[4].




| | |
|---|---|
| Lowest ask | $4,995 |
| Middle half | $8,980 – $12,999 |
| Median ask | $10,995 |
| This car | $10,998 |

Same model year · 25 live listings · as of 17 Nov 2026

### OTHER 2015 VOLKSWAGEN GOLF LISTINGS [5]

| | |
|---|---|
| Kitchener, ON · 82,018 km | $12,999 |
| Saint-Bruno-de-Montarville, QC · 111,111 km | $10,998 |
| Calgary, AB · 88,313 km | $20,550 |
| Vaughan, ON · 171,000 km | $7,998 |
| St. Catharines, ON · 162,050 km | $9,499 |
| Vancouver, BC · 116,463 km | $15,890 |

## §4 EVENTS

| | |
|---|---|
| 2015 | **Model year 2015**[1]<br>Assembly plant Puebla, Mexico |
| 9 Jul 2014 | **Transport Canada recall 2014288**[2]<br>Issued for the model year · Suspension |
| 16 Jul 2014 | **Transport Canada recall 2014295**[2]<br>Issued for the model year · Powertrain |
| 17 Dec 2014 | **Transport Canada recall 2014575**[2]<br>Issued for the model year · Fuel system |
| 16 Apr 2015 | **Transport Canada recall 2015161**[2]<br>Issued for the model year · Fuel system |
| 5 Oct 2015 | **Transport Canada recall 2015445**[2]<br>Issued for the model year · Airbag |
| 23 Oct 2015 | **Transport Canada recall 2015504**[2]<br>Issued for the model year · Engine |
| 2 Sep 2016 | **Transport Canada recall 2016430**[2]<br>Issued for the model year · Fuel system |
| 11 Jul 2018 | **Transport Canada recall 2018371**[2]<br>Issued for the model year · Powertrain |
| 6 Mar 2019 | **Transport Canada recall 2019116**[2]<br>Issued for the model year · Suspension |
| 22 Aug 2019 | **Transport Canada recall 2019423**[2]<br>Issued for the model year · Powertrain |
| 4 Aug 2020 | **Transport Canada recall 2020353**[2]<br>Issued for the model year · Label |
| 26 May 2021 | **Transport Canada recall 2021326**[2]<br>Issued for the model year · Fabrics |
| 14 Feb 2024 | **Transport Canada recall 2024095**[2]<br>Issued for the model year · Fuel system |
| 7 Nov 2026 | **Listed for sale, Coquitlam, BC**[5]<br>Kia West · asking $10,998 |
| 14 Nov 2026 | **Listing last updated**[5]<br>asking $10,998 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 25 live listings, as of 17 Nov 2026
[5] Live public dealer listings on Cardog, as of 17 Nov 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.