Register entry, as of 29 October 2026 Listed for sale Record ID cddc66779d8b

2011 Volkswagen Jetta SEL

2.5 L, 5 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VW	GX7AJ	4	B	M	379365
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen De Mexico Sa…	Jetta · 2.5 L	Verified	2011	Puebla	Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	2.5 L, 5 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Jetta	Drive	Not in the decode
Trim	SEL	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Sedan	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/jetta/2011

7 recalls listed by Transport Canada for this model year

Label

2020353 4 Aug 2020

Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.

Powertrain

2019423 22 Aug 2019

Issue: On certain vehicles, a build-up of silicate on the shift lever switch could cause the transmission to detect that it is in the Park position when it isn't. This could allow the ignition key to be removed when the transmission is not in the Park position. If the parking brake is not applied, this could allow the car to roll away. Safety Risk: If the transmission position is not displayed correctly, a user may not know that the vehicle is not in the PARK position. If the parking brake is not applied, this could create a risk of a vehicle roll-away and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have a new shift lever micro switch and control unit installed.

Seats and restraints

2015344 31 Jul 2015

On certain vehicles, the steering wheel clock spring could become contaminated with long hair or long fibers which may cause a displacement of the internal guide loops. When the guide loops are dragged out of position, they may apply tension to the internal flat cable and cause it to tear. Should the cable tear, the electrical connection to the driver's front airbag may be lost, causing the airbag monitoring indicator light to illuminate. Failure of the driver's airbag to deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will install a cover of a different design to help prevent clock spring contamination caused by hair or other fibers. In instances where the vehicle has an airbag light on (and diagnosis confirms the steering wheel clock spring requires replacement), dealers will install a new steering wheel clock spring.

Suspension

2014464 20 Oct 2014

On certain vehicles, if the rear axle trailing arms are damaged in a rear or side-rear impact crash and a repair facility does not correctly diagnose or replace damaged rear axle components, rear trailing arm durability could be reduced, which could result in a sudden fracture of the trailing arm. This could lead to a loss of vehicle control, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will install a sheet metal inlay on both rear axle trailing arms. The inlay is designed to help prevent the sudden loss of vehicle control should a rear axle trailing arm fracture occur if undiagnosed/unrepaired damage exists from a previous rear or side-rear impact/crash.

Fuel system

2011355 3 Oct 2011

On certain vehicles equipped with a 2.0L TDI diesel engine, the fuel injection lines could crack. Diesel fuel leakage may ignite on a hot engine surface and cause a fire, which could result in property damage and/or personal injury. Correction: Dealers will install vibration dampers on all four fuel injection lines. Additionally, on some vehicles (depending on the date of manufacture) the #2 fuel injection line will be replaced.

Accessories

2011331 8 Sep 2011

On certain vehicles, stainless steel exhaust tips (part number 1K0 071 910 U), sold as over-the-counter accessories, can extend beyond the original length of the factory-installed exhaust pipes. Contact with warm exhaust tips could result in burn injuries. Correction: Dealers will inspect and, if necessary, replace the exhaust tips with updated versions.

1 more on the model-year record, cardog.app/tools/recalls/volkswagen/jetta/2011

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $5,490[5], $490 over the median of $5,000[4].

Lowest ask	$2,800
Middle half	$3,499 – $5,900
Median ask	$5,000
This car	$5,490

Same model year · 9 live listings · as of 29 Oct 2026

OTHER 2011 VOLKSWAGEN JETTA LISTINGS [5]

London, ON · 114,270 km	$2,995
Mississauga, ON · 340,503 km	$3,499
Barrie, ON · 112,389 km	$7,995
Halton Hills, ON · 172,000 km	$5,000
Brantford, ON · 213,690 km	$4,490
Abbotsford, BC · 206,000 km	$7,025

§4 EVENTS

2011 **Model year 2011**[1]
Assembly plant Puebla, Mexico

25 Mar 2011	Transport Canada recall 2011132[2] Issued for the model year · Electrical
8 Sep 2011	Transport Canada recall 2011331[2] Issued for the model year · Accessories
3 Oct 2011	Transport Canada recall 2011355[2] Issued for the model year · Fuel system
20 Oct 2014	Transport Canada recall 2014464[2] Issued for the model year · Suspension
31 Jul 2015	Transport Canada recall 2015344[2] Issued for the model year · Seats and restraints
22 Aug 2019	Transport Canada recall 2019423[2] Issued for the model year · Powertrain
4 Aug 2020	Transport Canada recall 2020353[2] Issued for the model year · Label
29 Jul 2026	Listed for sale, Notre-Dame-Des-Prairies, QC[5] Joliette Ford Lincoln · asking $5,490
29 Oct 2026	Listing last updated[5] asking $5,490

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 9 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.