Register entry, as of 28 October 2026 Listed for sale Record ID edda240d6621

2015 Volkswagen Beetle 1.8T, TDI

1.8 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VW	J07AT	0	F	M	648673
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen De Mexico Sa…	Beetle · 1.8 L	Verified	2015	Puebla	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	1.8 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Beetle	Drive	Not in the decode
Trim	1.8T, TDI	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Hatchback	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/beetle/2015

6 recalls listed by Transport Canada for this model year

Heater and defroster

2024648 30 Oct 2024

Issue: Volkswagen Group Canada is conducting a parts recovery campaign targeting 2012-2016 Volkswagen vehicles equipped with a TDI (diesel) engine built between May 25, 2011 and June 1, 2016. The auxiliary heater elements are being recovered to aid in Volkswagen's analysis in support of Transport Canada defect investigation file no. 3280-15-10. Note: This action is not being conducted under the requirements of the Motor Vehicle Safety Act. For the 2016 model year Jetta, only the Jetta Hybrid model is involved in this parts recovery program. Safety Risk: No safety defect has been identified with these auxiliary heater elements. Corrective Actions: Volkswagen will notify owners by mail and advise them to take their vehicle to a dealership to replace the auxiliary heater element at no charge.

Seats and restraints

2022735 14 Dec 2022

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the driver-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Owners will be notified by mail and instructed to take their vehicle to a dealer to replace the driver-front airbag . Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

Label

2020353 4 Aug 2020

Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.

Powertrain

2019423 22 Aug 2019

Issue: On certain vehicles, a build-up of silicate on the shift lever switch could cause the transmission to detect that it is in the Park position when it isn't. This could allow the ignition key to be removed when the transmission is not in the Park position. If the parking brake is not applied, this could allow the car to roll away. Safety Risk: If the transmission position is not displayed correctly, a user may not know that the vehicle is not in the PARK position. If the parking brake is not applied, this could create a risk of a vehicle roll-away and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have a new shift lever micro switch and control unit installed.

Engine

2015504 23 Oct 2015

On certain vehicles, the camshaft lobe which actuates the vacuum pump may fail, causing the pump to fail to deliver further vacuum supply to the brake booster, potentially increasing stopping distances. This would also result in a reduction in available engine power. These issues could increase the risk of a crash causing injury and/or damage to property. Note: This issue would result in the Engine Malfunction Indicator Light (MIL) illuminating. Correction: Dealers will update the engine control module (ECM) software.

Fuel system

2014575 17 Dec 2014

On certain vehicles, a sealing cap at the fuel rail may fail to seal, allowing fuel to leak into the engine compartment during engine operation. Leaking fuel, in the presence of an ignition source, could lead to a fire causing injury and/or damage to property. Correction: Dealers will inspect, and if necessary, replace the fuel rail.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $14,995[5], $2,095 over the median of $12,900[4].



Lowest ask	$6,999
Middle half	$10,495 – $13,742
Median ask	$12,900
This car	$14,995

Same model year · 11 live listings · as of 28 Oct 2026

OTHER 2015 VOLKSWAGEN BEETLE LISTINGS [5]

Montréal, QC · 162,501 km	$9,999
Quebec, QC · 131,309 km	$10,991
North York, ON · 104,614 km	$17,479
Guelph, ON · 186,779 km	$7,500
Surrey, BC · 170,350 km	$12,900
Halton Hills, ON · 226,000 km	$6,999

§4 EVENTS

2015 Model year 2015[1]
Assembly plant Puebla, Mexico

17 Dec 2014	Transport Canada recall 2014575[2] Issued for the model year · Fuel system
23 Oct 2015	Transport Canada recall 2015504[2] Issued for the model year · Engine
22 Aug 2019	Transport Canada recall 2019423[2] Issued for the model year · Powertrain
4 Aug 2020	Transport Canada recall 2020353[2] Issued for the model year · Label
14 Dec 2022	Transport Canada recall 2022735[2] Issued for the model year · Seats and restraints
30 Oct 2024	Transport Canada recall 2024648[2] Issued for the model year · Heater and defroster
26 Oct 2026	Listed for sale, Penticton, BC[5] Bannister Kia Penticton · asking $14,995
28 Oct 2026	Listing last updated[5] asking $14,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 11 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.