Register entry, as of 27 November 2026 Listed for sale Record ID d0363395ce4c

2014 Volkswagen Beetle

2.0 L, 4 cylinders · Hatchback · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

3VW	JL7AT	5	E	M	644477
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen De Mexico Sa…	Beetle · 2.0 L	Verified	2014	Puebla	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Diesel
Model	Beetle	Drive	Not in the decode
Trim	Not in the decode	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Hatchback	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/beetle/2014

8 recalls listed by Transport Canada for this model year

Heater and defroster

2024648 30 Oct 2024

Issue: Volkswagen Group Canada is conducting a parts recovery campaign targeting 2012-2016 Volkswagen vehicles equipped with a TDI (diesel) engine built between May 25, 2011 and June 1, 2016. The auxiliary heater elements are being recovered to aid in Volkswagen's analysis in support of Transport Canada defect investigation file no. 3280-15-10. Note: This action is not being conducted under the requirements of the Motor Vehicle Safety Act. For the 2016 model year Jetta, only the Jetta Hybrid model is involved in this parts recovery program. Safety Risk: No safety defect has been identified with these auxiliary heater elements. Corrective Actions: Volkswagen will notify owners by mail and advise them to take their vehicle to a dealership to replace the auxiliary heater element at no charge.

Airbag

2021017 21 Jan 2021

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the driver-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Owners will be notified by mail and instructed to take their vehicle to a dealer to replace the driver-front airbag . Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

Label

2020353 4 Aug 2020

Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.

Powertrain

2019423 22 Aug 2019

Issue: On certain vehicles, a build-up of silicate on the shift lever switch could cause the transmission to detect that it is in the Park position when it isn't. This could allow the ignition key to be removed when the transmission is not in the Park position. If the parking brake is not applied, this could allow the car to roll away. Safety Risk: If the transmission position is not displayed correctly, a user may not know that the vehicle is not in the PARK position. If the parking brake is not applied, this could create a risk of a vehicle roll-away and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have a new shift lever micro switch and control unit installed.

Fuel system

2014575 17 Dec 2014

On certain vehicles, a sealing cap at the fuel rail may fail to seal, allowing fuel to leak into the engine compartment during engine operation. Leaking fuel, in the presence of an ignition source, could lead to a fire causing injury and/or damage to property. Correction: Dealers will inspect, and if necessary, replace the fuel rail.

Structure

2014465 20 Oct 2014

On certain vehicles, the panoramic sunroof glass and steel frame may have been manufactured out of tolerance. This issue may result in the sunroof fracturing if the vehicle were to experience a sudden jolt, especially in cold temperatures. Sunroof glass panel breakage, while the vehicle is in motion, could cause driver distraction, which could result in a crash causing injury and/or property damage. Additionally, broken glass inside the vehicle poses a risk of injury to vehicle occupants. Correction: Dealers will replace the panoramic sunroof glass assembly.

2 more on the model-year record, cardog.app/tools/recalls/volkswagen/beetle/2014

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply. Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $10,991[5], the median[4].



Lowest ask	$7,800
Middle half	$8,710 – $12,346
Median ask	$10,991
This car	$10,991

Same model year · 7 live listings · as of 27 Nov 2026

OTHER 2014 VOLKSWAGEN BEETLE LISTINGS [5]

Orangeville, ON · 172,676 km	$9,421
Guelph, ON · 139,716 km	$7,800
Ottawa, ON · 66,494 km	$12,995
Calgary, AB · 219,776 km	$12,697
Beauharnois, QC · 178,678 km	$11,994
Halton Hills, ON · 191,985 km	$7,999

§4 EVENTS

2014	Model year 2014[1] Assembly plant Puebla, Mexico
12 Nov 2013	Transport Canada recall 2013398[2] Issued for the model year · Lights and instruments
16 Apr 2014	Transport Canada recall 2014136[2] Issued for the model year · Powertrain
20 Oct 2014	Transport Canada recall 2014465[2] Issued for the model year · Structure
17 Dec 2014	Transport Canada recall 2014575[2] Issued for the model year · Fuel system
22 Aug 2019	Transport Canada recall 2019423[2] Issued for the model year · Powertrain
4 Aug 2020	Transport Canada recall 2020353[2] Issued for the model year · Label
21 Jan 2021	Transport Canada recall 2021017[2] Issued for the model year · Airbag
30 Oct 2024	Transport Canada recall 2024648[2] Issued for the model year · Heater and defroster
11 Nov 2026	Listed for sale, Truro, NS[5] Century Honda · asking $10,991
27 Nov 2026	Listing last updated[5] asking $10,991

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 7 live listings, as of 27 Nov 2026
[5] Live public dealer listings on Cardog, as of 27 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.