Register entry, as of 29 October 2026 Listed for sale Record ID 7c67c2a5be9c

2015 Mitsubishi RVR ES/SE (Canada)

2.0 L · 4x2 · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4A4	AH3AU	8	F	E	604268
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mitsubishi Motors North A…	RVR · 2.0 L	Verified	2015	Bloomington-Normal	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.0 L
Make	Mitsubishi	Fuel	Gasoline
Model	RVR	Drive	4x2
Trim	ES/SE (Canada)	Maker	MITSUBISHI MOTORS NORTH AMERICA
Body	Sport Utility Vehicle	Plant	Bloomington-Normal, Illinois, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mitsubishi/rvr/2015

9 recalls listed by Transport Canada for this model year

Label

2024554 19 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words and abbreviations listed on the label for "TIRES", "RIMS", "WITH", "FR" and "RR" and appear in English only, when they should be listed as "TIRES/PNEUS", "RIMS/JANTES", "WITH/AVEC", "FR/AVT" and "RR/ARR". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Mitsubishi has corrected the compliance label for all new vehicles.

Structure

2020216 15 May 2020

Issue: On certain vehicles, road salt can corrode the front cross-member (subframe). As a result, a lower control arm could eventually detach from the cross-member. This could cause a loss of vehicle control. Safety Risk: A loss of control can create the risk of a crash. Corrective Actions: Mitsubishi will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the front cross-member (subframe). If no significant corrosion is found, the dealer will spray a sealing and anti-corrosion coating both inside and on the cross-member. If significant corrosion is found, the dealer will replace the cross-member.

Visual system

2018083 12 Feb 2018

On certain vehicles, water may drain from the windshield cowl area onto the front wiper link ball joint. Over time, this could result in corrosion and/or wear to the joint, which could result in the separation of the wiper link ball. If separation were to occur, the windshield wipers could become inoperative, which could limit the driver's visibility under certain operating conditions which may increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the wiper link rod with a countermeasure one, and will inspect the wiper motor crank arm and replace as necessary.

Brakes

2018053 26 Jan 2018

On certain vehicles, insufficient rust prevention to the parking brake shaft and insufficient sealing performance of the rear brake caliper boot could allow water to penetrate inside these components causing corrosion. As a result, the parking brake shaft may become stuck causing brake dragging and/or decreased parking brake performance. Additionally, the automatic adjuster for the brake pad clearance of the rear brake caliper with the built-in parking brake may not work correctly. These conditions could lead to a vehicle rollaway, which would increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect and repair the rear brakes as necessary.

Engine

2017475 29 Sep 2017

On certain vehicles, defective electrical relays may have been installed in the power distribution center. This could cause various electrical circuits to fail, potentially resulting in engine stalling, reduced engine power, or loss of engine cooling fan function potentially resulting in engine overheating. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace affected relay(s) with updated parts.

Visual system

2016530 27 Oct 2016

On certain vehicles, water may drain from the windshield cowl area and potentially collect in the area of the wiper motor breathing hole. If the wiper motor is not operating, water could potentially enter the wiper motor through the breathing hole. If this occurs, over time, it could result in corrosion and/or an electrical conduction failure, both of which could result in the wiper motor not operating. If the wiper motor were to stop operating, the windshield wipers would become inoperative, which could limit the driver's visibility under certain operating conditions which may increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the wiper motor with an upgraded wiper motor that will prevent water intrusion.

3 more on the model-year record, cardog.app/tools/recalls/mitsubishi/rvr/2015

> Listed for the model year, not checked against your VIN. Mitsubishi confirms which apply.
> Check your VIN with Mitsubishi Canada or call a Mitsubishi dealer with your VIN.
> www.mitsubishi-motors.ca/en/owners/maintenance-service/mitsubishi-recalls

§3 VALUE [3]

This car asks $9,990[4], $746 under the median of $10,736[3].

Lowest ask	$6,995
Middle half	$9,336 – $10,994
Median ask	$10,736
This car	$9,990

Same model year · 6 live listings · as of 29 Oct 2026

OTHER 2015 MITSUBISHI RVR LISTINGS [4]

Longueuil, QC · 161,275 km	$8,955
Baie-Comeau, QC · 106,121 km	$10,480
St-Félicien, QC · 106,121 km	$10,480
Saint-Félicien, QC · 106,000 km	$10,480
Cowichan Valley, BC · 133,105 km	$10,999
Montréal, QC · 131,000 km	$6,995

§4 EVENTS

2015	Model year 2015[1] Assembly plant Bloomington-Normal, Illinois, United States
20 Nov 2014	Transport Canada recall 2014525[2] Issued for the model year · Seats and restraints
17 Sep 2015	Transport Canada recall 2015410[2] Issued for the model year · Label
22 Jul 2016	Transport Canada recall 2016371[2] Issued for the model year · Other
27 Oct 2016	Transport Canada recall 2016530[2] Issued for the model year · Visual system
29 Sep 2017	Transport Canada recall 2017475[2] Issued for the model year · Engine
26 Jan 2018	Transport Canada recall 2018053[2] Issued for the model year · Brakes
12 Feb 2018	Transport Canada recall 2018083[2] Issued for the model year · Visual system
15 May 2020	Transport Canada recall 2020216[2] Issued for the model year · Structure
19 Sep 2024	Transport Canada recall 2024554[2] Issued for the model year · Label
25 Oct 2026	Listed for sale, Vaudreuil-Dorion, QC[4] Prilo Occasion · asking $9,990
29 Oct 2026	Listing last updated[4] asking $9,990

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 6 live listings, as of 29 Oct 2026

[4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.