Register entry, as of 25 November 2026 Listed for sale Record ID f77baa2fdb9c

2008 Mercedes-Benz GL-Class GL450 4 MATIC

4.6 L, 8 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4JG	BF71E	3	8	A	382066
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz Of North A…	GL-Class · 4.6 L	Verified	2008	Vance	Build sequence

§1 IDENTITY [1]

Model year	2008	Engine	4.6 L, 8 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	GL-Class	Drive	AWD
Trim	GL450 4 MATIC	Maker	MERCEDES-BENZ OF NORTH AMERICA, INC.
Body	Sport Utility Vehicle	Plant	Vance, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/gl-class/2008

4 recalls listed by Transport Canada for this model year

Brakes

2022237 6 May 2022

Issue: On certain vehicles, corrosion could cause the brake booster to fail. If this happens, there may be an increase in brake pedal effort and increase the distance needed to stop the vehicle. In rare cases of severe corrosion, the brake booster could separate completely and cause a loss of brakes. Safety Risk: A loss of brakes can increase the risk of a crash. Corrective Actions: Mercedes-Benz advises you to stop driving your vehicle immediately. The company will notify owners by mail and instruct you to contact a local Mercedes-Benz dealership to arrange for towing and an inspection. The dealer will remove the rubber brake booster sleeve and determine whether the vehicle is safe to drive or if it can't be driven and a parts replacement is necessary. Also, depending on the results of the inspection, you may need to return within two years for a re-inspection.

Steering

2008448 18 Dec 2008

On certain vehicles, a driving pin located inside the power steering rack may have been manufactured incorrectly. Should the driving pin fail it would cause an unexpected loss of steering power assist, which may result in a vehicle crash. Correction: Dealers will replace the power steering gear assembly.

Other 2008242 9 Jul 2008

Certain vehicles may have been programmed with incorrect software calibration data during the manufacturing process. This could affect various functions such as: The electric fuel pump may not receive a signal which, in case of a crash, may prevent the fuel pump from disconnecting as designed; The maximum speed limiter may not be activated; The fuel gauge readings may be incorrect; A stuck fuel-level sensor may not be displayed in the instrument cluster; The speedometer may be out of tolerance which, as a result, may indicate inaccurate vehicle speed; The On-Board Diagnostic (OBD) system may reduce the emission level applicable to the vehicle, causing the Check Engine Light to illuminate incorrectly. Correction: Dealers will reprogram the electronic control module.


Other 2008191 2 Jun 2008

On certain vehicles, trailer hitches, whether installed during vehicle assembly, or sold as an over-the-counter accessory and installed by the dealer, may contain inadequate welds and, as a result, could eventually fail. This could allow the towed unit to separate from the towing vehicle, causing property damage, personal injury or death. Correction: Dealers will repair weld the hitch assembly.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply. Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $9,600[4], $1,698 under the median of $11,298[3].



Lowest ask	$8,950
Middle half	$9,438 – $13,371
Median ask	$11,298
This car	$9,600

Same model year · 4 live listings · as of 25 Nov 2026

OTHER 2008 MERCEDES-BENZ GL-CLASS LISTINGS [4]

Edmonton, AB · 123,393 km	$14,500
Richmond, BC · 142,771 km	$12,995
Hamilton, ON · 237,000 km	$8,950

§4 EVENTS

2008	Model year 2008[1] Assembly plant Vance, Alabama, United States
2 Jun 2008	Transport Canada recall 2008191[2] Issued for the model year · Other
9 Jul 2008	Transport Canada recall 2008242[2] Issued for the model year · Other
18 Dec 2008	Transport Canada recall 2008448[2] Issued for the model year · Steering
6 May 2022	Transport Canada recall 2022237[2] Issued for the model year · Brakes

21 Apr 2026	Listed for sale, Windsor, ON[4] Auto Nation Car Sales · asking $9,600
25 Nov 2026	Listing last updated[4] asking $9,600

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 4 live listings, as of 25 Nov 2026

[4] Live public dealer listings on Cardog, as of 25 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.