Register entry, as of 27 October 2026 Listed for sale Record ID 1c37e544a868

# 2020 Subaru Impreza Premium+ES

2.0 L, 4 cylinders · AWD · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 4S3 | GTAV6 | 2 | L | 3 | 711050 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Subaru Of America, Inc | Impreza · 2.0 L | Verified | 2020 | United States | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2020 | Engine | 2.0 L, 4 cylinders |
| Make | Subaru | Fuel | Gasoline |
| Model | Impreza | Drive | AWD |
| Trim | Premium+ES | Maker | SUBARU OF AMERICA, INC |
| Body | Hatchback | Plant | United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/impreza/2020

3 recalls listed by Transport Canada for this model year

### Lights and instruments

2022394 21 Jul 2022

Issue: Over time, the backup lamp switch could corrode and fail. If this happens, the backup lamps will not turn on when the transmission is shifted into reverse and the shift position will not display. Additionally, for vehicles equipped with a rearview camera, the camera image will not appear on the display in the instrument cluster. Safety Risk: Backup lamps that do not work properly could cause a person not to recognize that the vehicle is backing. A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. These issues could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealership to inspect, and if necessary, replace the backup lamp switch.

### Tires

2021209 7 Apr 2021

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could cause a tire failure and lead to sudden loss of air pressure. Note: This recall only affects certain 16 inch Continental tires, with specific date codes and mould numbers. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Subaru will notify the owners by mail and instruct them to take the vehicle to a dealer to inspect all four tires. If one tire is affected, all four tires will be replaced.

### Tires

2020521 2 Nov 2020

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could cause a tire failure and lead to sudden loss of air pressure. Note: This recall only affects vehicles equipped with certain Continental tires, with a date code of 2420 and mold number 416290. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to inspect all four tires. If one tire is affected, all four tires will be replaced

> Listed for the model year, not checked against your VIN. Subaru confirms which apply.
> Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
> www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $16,880[5], the median[4].

| | |
|---|---|
| Lowest ask | $12,995 |
| Middle half | $15,579 – $18,524 |
| Median ask | $16,880 |
| This car | $16,880 |

Same model year · 23 live listings · as of 27 Oct 2026

### OTHER 2020 SUBARU IMPREZA LISTINGS [5]

| | |
|---|---|
| Orleans, ON · 110,888 km | $18,882 |
| Charlottetown, PE · 83,417 km | $16,995 |
| Sherbrooke, QC · 145,000 km | $14,988 |
| Thunder Bay, ON · 49,263 km | $22,999 |
| Terrebonne, QC · 155,584 km | $13,499 |
| Guelph, ON · 201,500 km | $12,995 |

## §4 EVENTS

| | |
|---|---|
| 2020 | Model year 2020[1]<br>Assembly plant United States |
| 2 Nov 2020 | Transport Canada recall 2020521[2]<br>Issued for the model year · Tires |
| 7 Apr 2021 | Transport Canada recall 2021209[2]<br>Issued for the model year · Tires |
| 21 Jul 2022 | Transport Canada recall 2022394[2]<br>Issued for the model year · Lights and instruments |
| 21 Oct 2026 | Listed for sale, Montréal, QC[5]<br>Volvo Autos Saint Léonard · asking $16,880 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $16,880 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 23 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.