Register entry, as of 27 October 2026 Listed for sale Record ID 067a32df02b1

# 2020 Subaru Outback Onyx Edition

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 4S4 | BTHJD | 8 | L | 3 | 156365 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Subaru Of America, Inc | Outback · 2.4 L | Verified | 2020 | Lafayette | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2020 | Engine | 2.4 L, 4 cylinders |
| Make | Subaru | Fuel | Gasoline |
| Model | Outback | Drive | 4WD |
| Trim | Onyx Edition | Maker | SUBARU OF AMERICA, INC |
| Body | Sport Utility Vehicle | Plant | Lafayette, Indiana, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/outback/2020

**6** recalls listed by Transport Canada for this model year

### Label

2024546 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.

### Airbag

2024190 22 Mar 2024

Issue: On certain vehicles, an electrical component in the sensors for the occupant detection system (ODS) may not have been manufactured properly and could crack. Over time, moisture could enter the crack and cause a short circuit. If this happens, the passenger-front airbag may not deploy in a crash, even when a passenger is seated. Note: This problem would cause the SRS warning light to turn on in the instrument panel and the passenger airbag indicator light would display "OFF". Safety Risk: An airbag that does not work properly could increase the risk of injury to a passenger in a crash. Corrective Actions: Subaru will notify owners by mail and advise you to take your vehicle to a dealership to replace the ODS sensors in the front passenger seat. To reduce the safety risk, Subaru advises that you shouldn't use the front passenger seat if the SRS (airbag) warning light is on and the passenger airbag indicator light displays "OFF".

### Powertrain

2021745 10 Dec 2021

Issue: On certain vehicles, a software problem in the transmission control unit (TCU) may cause the drive chain to slip or break. If this happens while the vehicle is in motion, there could be a loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the transmission chain guide and update the TCU. If necessary, the transmission assembly will be replaced.

### Fuel system

2021466 29 Jul 2021

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

### Visual system

2020607 10 Dec 2020

Issue: On certain vehicles, a software update could cause the Centre Information Display ("CID") to go blank. When this happens, the cockpit control module ("CCM") will continuously reboot every three (3) minutes. As a result, the rearview camera image will disappear during the reboot process. Safety Risk: A rearview camera that turns off could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to update vehicle software. If the centre information display is not working properly, the cockpit control module will be replaced.

### Accessories

2019536 25 Oct 2019

Issue: Certain vehicles were shipped with the incorrect floor mat bracket. As a result, the floor mats may not be properly attached. A driver's floor mat that moves could interfere with the accelerator or brake pedals. Safety Risk: A floor mat that interferes with the accelerator and/or the brake pedal could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the floor mat bracket. If the wrong part is installed, it will be replaced. Subaru recommends that you remove the driver's floor mat until the recall repairs are performed.

> Listed for the model year, not checked against your VIN. Subaru confirms which apply.
> Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
> www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $28,888[5], $4,893 over the median of $23,995[4].




| | |
|---|---|
| Lowest ask | $17,495 |
| Middle half | $23,595 – $25,995 |
| Median ask | $23,995 |
| This car | $28,888 |

Same configuration · 9 live listings · as of 27 Oct 2026

### OTHER 2020 SUBARU OUTBACK LISTINGS [5]

| | |
|---|---|
| Boisbriand, QC · 46,282 km | $24,993 |
| Mississauga, ON · 105,858 km | $26,995 |
| Grande Prairie, AB · 135,832 km | $20,892 |
| Grande Prairie, AB · 135,832 km | $20,892 |
| Smiths Falls, ON · 66,916 km | $26,495 |
| Georgetown, ON · 153,988 km | $20,879 |

## §4 EVENTS

2020 Model year 2020[1]
Assembly plant Lafayette, Indiana, United States

| | |
|---|---|
| 25 Oct 2019 | Transport Canada recall 2019536[2]<br>Issued for the model year · Accessories |
| 10 Dec 2020 | Transport Canada recall 2020607[2]<br>Issued for the model year · Visual system |
| 29 Jul 2021 | Transport Canada recall 2021466[2]<br>Issued for the model year · Fuel system |
| 10 Dec 2021 | Transport Canada recall 2021745[2]<br>Issued for the model year · Powertrain |
| 22 Mar 2024 | Transport Canada recall 2024190[2]<br>Issued for the model year · Airbag |
| 15 Aug 2024 | Transport Canada recall 2024546[2]<br>Issued for the model year · Label |
| 19 Aug 2026 | Listed for sale, Burnaby, BC[5]<br>Morrey Volvo Cars Of Burnaby · asking $28,888 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $28,888 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 9 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.