Register entry, as of 27 October 2026 Listed for sale Record ID 065a2b2e5314

# 2025 Toyota Camry

2.5 L, 4 cylinders · 4WD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 4T1 | DBADK | 4 | S | U | 541041 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Toyota Motor Manufacturi… | Camry · 2.5 L | Verified | 2025 | Georgetown | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2025 | Engine | 2.5 L, 4 cylinders |
| Make | Toyota | Fuel | Gasoline |
| Model | Camry | Drive | 4WD |
| Trim | Not in the decode | Maker | TOYOTA MOTOR MANUFACTURING, KENTUCKY, INC. |
| Body | Sedan | Plant | Georgetown, Kentucky, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/camry/2025

5 recalls listed by Transport Canada for this model year

### Visual system

2026383 6 Aug 2026

Issue: On certain vehicles, a software problem could cause the combination meter in the instrument cluster not to display when the vehicle is started. As a result, the turn signals and hazard lights may not work. Additionally, you may not be able to see certain information about the vehicle, including warning lights, malfunction tell-tales and seat belt reminders. Note: This recall only affects vehicles equipped with a 7-inch display. Safety Risk: Turn signals that don't work may cause a person not to recognize when the driver intends to turn or change lanes and could increase the risk of a crash. Warnings, tell-tales and gauges that don't display could also increase the risk of a crash. A seat belt warning that doesn't work may not remind you to buckle your seat belt. Not wearing your seat belt can increase the risk of injury in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to update the combination meter software.

### High voltage

2025693 16 Dec 2025

Issue: On certain vehicles, a bolt in the inverter assembly for the hybrid system may not have been tightened properly. As a result, the vehicle could enter a reduced power mode or lose power to the wheels. Additionally, if the bolt becomes loose in the inverter assembly and the ignition is on, it could cause a short circuit. Safety Risk: A loss of power to the wheels could increase the risk of a crash. A short circuit can create the risk of a fire. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect the hybrid inverter assembly bolt. The dealer will tighten the bolt or, if necessary, replace the inverter assembly.

### Visual system

2025594 30 Oct 2025

Issue: Under certain conditions, a software problem could cause the rearview camera image to freeze or not to display. If this happens, the rearview image may not display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall only affects certain vehicles equipped with a panoramic view monitor system. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: The company will notify owners in writing and advise you to take your vehicle to a dealership to update the parking assist ECU software.

### Visual system

2025469 11 Sep 2025

Issue: On certain vehicles, a software problem could cause the combination meter in the instrument panel not to display when the vehicle is started. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, warning lights and malfunction tell-tales. Note: This recall only affects vehicles equipped with a 12.3-inch display. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to update the combination meter software. Alternatively, certain eligible vehicles will be sent a wireless over-the-air software update, which you can install yourself. For certain vehicles, the dealer will also inspect and, if necessary, replace the combination meter.

### Seats and restraints

2025050 6 Feb 2025

Issue: On certain vehicles, the second-row center seat belt may have been damaged during production. As a result, the seat belt could break in a crash. If this happens, the seat belt may not hold a person in place during the crash. Safety Risk: A seat belt that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: To reduce the safety risk, the company advises that you shouldn't transport a passenger in the second-row center seat until the recall repairs are completed. The company will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the second-row center seat belt assembly.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $40,000[5], $2,989 under the median of $42,989[4].




| | |
|---|---|
| Lowest ask | $34,229 |
| Middle half | $39,242 – $44,934 |
| Median ask | $42,989 |
| This car | $40,000 |

Same configuration · 39 live listings · as of 27 Oct 2026

### OTHER 2025 TOYOTA CAMRY LISTINGS [5]

| | |
|---|---|
| Essex, ON · 82,255 km | $32,488 |
| Essex, ON · 85,933 km | $31,988 |
| Toronto, ON · 85,933 km | $31,988 |
| Toronto, ON · 82,255 km | $32,488 |
| Woodbridge, ON · 29,486 km | $37,700 |

## §4 EVENTS

| | |
|---|---|
| 2025 | Model year 2025[1]<br>Assembly plant Georgetown, Kentucky, United States |
| 6 Feb 2025 | Transport Canada recall 2025050[2]<br>Issued for the model year · Seats and restraints |
| 11 Sep 2025 | Transport Canada recall 2025469[2]<br>Issued for the model year · Visual system |
| 30 Oct 2025 | Transport Canada recall 2025594[2]<br>Issued for the model year · Visual system |
| 16 Dec 2025 | Transport Canada recall 2025693[2]<br>Issued for the model year · High voltage |
| 6 Aug 2026 | Transport Canada recall 2026383[2]<br>Issued for the model year · Visual system |
| 26 Oct 2026 | Listed for sale, Windsor, ON[5]<br>Lexus of Windsor · asking $40,000 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $40,000 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 39 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.