Register entry, as of 28 October 2026 Listed for sale Record ID 9b6062b2610d

# 2019 Honda Odyssey EX/EX w/ RES

3.5 L, 6 cylinders · 4x2 · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5FN | RL6H4 | 6 | K | B | 500466 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| American Honda Motor Co... | Odyssey · 3.5 L | Verified | 2019 | Lincoln | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2019 | Engine | 3.5 L, 6 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | Odyssey | Drive | 4x2 |
| Trim | EX/EX w/ RES | Maker | AMERICAN HONDA MOTOR CO., INC. |
| Body | Minivan | Plant | Lincoln, Alabama, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/odyssey/2019

**19** recalls listed by Transport Canada for this model year

### Visual system

2026326 2 Jul 2026

Issue: On certain vehicles, the recall repairs completed by a Honda dealer during recall O38 (Transport Canada recall no. 2020-345) may not be effective. As a result, certain vehicles require a second repair. On certain vehicles, moisture could enter the rearview camera and cause it not to work properly. If this happens, the rearview image may be distorted or not display at all. Also, the camera image may not appear in certain bright light conditions. Note: This recall replaces recall O38 (Transport Canada recall no. 2020-345). Vehicles that were repaired under that recall also require this repair. Safety Risk: A rearview camera image that doesn't display properly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealer to replace the rearview camera.

### Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

### Seats and restraints

2026181 9 Apr 2026

Issue: On certain vehicles, under certain conditions, a software problem could cause the side airbag(s) and side curtain airbag(s) to inflate unexpectedly. Safety Risk: An airbag that deploys without a crash could create a risk of injury. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to reprogram or replace the supplemental restraint system (SRS) electronic control unit (ECU), as necessary.

### Visual system

2024761 13 Dec 2024

Issue: Under certain conditions, a software problem could cause the wrong view mode to display when the transmission is shifted into reverse. As a result, the rearview camera image may not appear correctly on the display screen. Canadian regulations allow only certain view modes to be displayed when the vehicle is reversing. Note: Vehicles that received a software update previously under a Honda product update, campaign no. P01 - 'Incorrect Rear View Camera View Mode', don't require this repair. Safety Risk: A rearview camera image that doesn't display the correct view mode could reduce a driver's field of view behind the vehicle. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and have sent a wireless over-the-air software update to eligible vehicles to update the vehicle software. Alternatively, you may schedule an appointment to have the update performed at a Honda dealership.

### Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

### Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

13 more on the model-year record, cardog.app/tools/recalls/honda/odyssey/2019

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 20 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $27,800[5], $400 over the median of $27,400[4].

| | |
|---|---|
| Lowest ask | $15,480 |
| Middle half | $24,555 – $29,997 |
| Median ask | $27,400 |
| This car | $27,800 |

Same configuration · 38 live listings · as of 28 Oct 2026

### OTHER 2019 HONDA ODYSSEY LISTINGS [5]

| | |
|---|---|
| Dunnville, ON · 125,026 km | $26,995 |
| Kitchener, ON · 143,114 km | $30,879 |
| Acton, ON · 190,778 km | $18,995 |
| London, ON · 143,114 km | $30,879 |
| Georgetown, ON · 143,114 km | $30,879 |
| London, ON · 143,114 km | $30,879 |

## §4 EVENTS

| | |
|---|---|
| 2019 | Model year 2019[1]<br>Assembly plant Lincoln, Alabama, United States |
| 1 Nov 2018 | Transport Canada recall 2018602[2]<br>Issued for the model year · Brakes |
| 11 Apr 2019 | Transport Canada recall 2019180[2]<br>Issued for the model year · Powertrain |
| 11 Apr 2019 | Transport Canada recall 2019179[2]<br>Issued for the model year · Engine |
| 6 Feb 2020 | Transport Canada recall 2020042[2]<br>Issued for the model year · Electrical |
| 28 Jul 2020 | Transport Canada recall 2020346[2]<br>Issued for the model year · Visual system |
| 28 Jul 2020 | Transport Canada recall 2020345[2]<br>Issued for the model year · Visual system |
| 28 Jul 2020 | Transport Canada recall 2020344[2]<br>Issued for the model year · Visual system |
| 29 Jul 2020 | Transport Canada recall 2020343[2]<br>Issued for the model year · Structure |
| 19 Jan 2021 | Transport Canada recall 2021012[2]<br>Issued for the model year · Fuel system |
| 26 Mar 2021 | Transport Canada recall 2021182[2]<br>Issued for the model year · Fuel system |
| 9 Mar 2023 | Transport Canada recall 2023127[2]<br>Issued for the model year · Seats and restraints |
| 15 Jun 2023 | Transport Canada recall 2023350[2]<br>Issued for the model year · Visual system |
| 8 Nov 2023 | Transport Canada recall 2023603[2]<br>Issued for the model year · Engine |
| 18 Dec 2023 | Transport Canada recall 2023679[2]<br>Issued for the model year · Fuel system |
| 6 May 2024 | Transport Canada recall 2024262[2]<br>Issued for the model year · Fuel system |
| 13 Dec 2024 | Transport Canada recall 2024761[2]<br>Issued for the model year · Visual system |
| 9 Apr 2026 | Transport Canada recall 2026181[2]<br>Issued for the model year · Seats and restraints |

| | |
|---|---|
| 21 May 2026 | Transport Canada recall 2026251[2]<br>Issued for the model year · Seats and restraints |
| 2 Jul 2026 | Transport Canada recall 2026326[2]<br>Issued for the model year · Visual system |
| 3 Oct 2026 | Listed for sale, Innisfil, ON[5]<br>AutoPark Barrie · asking $27,800 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $27,800 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 38 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.