Register entry, as of 29 November 2026 Listed for sale Record ID 0a24001425ac

2017 Honda Ridgeline SPORT

3.5 L, 6 cylinders · 2WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5FP	YK3F1	X	H	B	502842
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
American Honda Motor Co...	Ridgeline · 3.5 L	Verified	2017	Lincoln	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.5 L, 6 cylinders
Make	Honda	Fuel	Gasoline
Model	Ridgeline	Drive	2WD
Trim	SPORT	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Pickup	Plant	Lincoln, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/ridgeline/2017

6 recalls listed by Transport Canada for this model year

Structure — 2026275 — 4 Jun 2026

Issue: On certain vehicles, the suspension mounting points on the rear subframe could rust. As a result, rear suspension components could fail. This could lead to poor handling and a loss of vehicle control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and install a rear subframe reinforcement kit or replace the subframe, as necessary.

Visual system — 2022669 — 23 Nov 2022

Issue: On certain trucks, the tailgate wiring harness could become damaged over time. If this happens, the rearview camera image may not display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail. Due to a parts supply issue, Honda will advise you to take your truck to the dealership only if this failure occurs. When enough parts are available, Honda will re-notify owners and instruct you to take your truck to a dealership to replace the tailgate wiring harness.

Structure — 2021725 — 25 Nov 2021

Issue: On certain vehicles, the hood latch striker could separate from the hood. If this happens, the hood could open while driving. Note: A loose or vibrating hood may be a warning that the hood latch is failing. Safety Risk: A hood that opens suddenly while driving could block the driver's view and increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the hood latch striker. Depending on its condition, a striker support plate will be installed, or if necessary, the hood will be replaced.

Accessories

2020441 17 Sep 2020

Issue: This recall is for Honda Genuine Accessory tri-fold tonneau covers that were sold as an accessory by Honda dealers. There may be a problem with the bed-cover that could cause it to come loose while driving and detach from the truck. Safety Risk: A bed-cover cover that separates from a moving truck could create a hazard for other drivers and nearby people. Corrective Actions: Honda will notify owners by mail and instruct you to take your truck to a dealer for an inspection. If necessary, the dealer will install a tether between the center and rear panels of the tonneau cover to prevent them from separating. The dealer will also provide you with an updated accessory owner's manual and apply warning labels that remind you to properly secure the tonneau cover before driving. Note: Until the recall repairs are completed, you can prevent the tonneau cover from coming loose by removing and storing it.

Fuel system

2019035 25 Jan 2019

Issue: During a car wash, water can drain from the truck bed onto the top of the fuel pump. Certain car wash detergents containing sulfuric acid could cause damage to the fuel pump. This could cause the fuel pump to crack and create a fuel leak. Safety Risk: Fuel leakage, in the presence of an ignition source, could increase the risk of a fire. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer for an inspection of the fuel pump. If the fuel pump is cracked, it will be replaced. Dealers will also install a fuel pump cover. Note: Owners who smell a fuel odour or believe there is a fuel leak should contact a dealer immediately.

Electrical

2016612 8 Dec 2016

On certain vehicles, moisture could enter the rear wiring harness through a connection located underneath a drain hole in the truck bed and cause corrosion to form in some connection terminals. If corrosion of the rear wheel speed sensor terminals occurs, it could increase the electrical resistance and may be interpreted by the vehicle stability assist (VSA) as wheel slippage, resulting in a decrease of engine torque or brake application to the rear wheel(s). The unexpected and unnecessary application of brake assist while driving may increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the rear wiring harness and corresponding rear drivetrain components for moisture and/or corrosion. If present, the dealer will replace the rear wiring harness and corresponding components as necessary. If there is no moisture or corrosion, the dealer will repair the rear wiring harness to eliminate the potential for moisture intrusion.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $25,800[5], $2,856 over the median of $22,944[4].



Lowest ask	$17,850
Middle half	$21,984 – $24,714
Median ask	$22,944
This car	$25,800

Same configuration · 12 live listings · as of 29 Nov 2026

OTHER 2017 HONDA RIDGELINE LISTINGS [5]

Nanaimo, BC · 120,805 km	$28,805
New Hamburg, ON · 106,224 km	$25,995
Brantford, ON · 243,870 km	$12,000
Langley, BC · 99,576 km	$26,500
Burnaby, BC · 134,773 km	$27,800
Ottawa, ON · 208,708 km	$17,871

§4 EVENTS

2017	Model year 2017[1] Assembly plant Lincoln, Alabama, United States
8 Dec 2016	Transport Canada recall 2016612[2] Issued for the model year · Electrical
25 Jan 2019	Transport Canada recall 2019035[2] Issued for the model year · Fuel system
17 Sep 2020	Transport Canada recall 2020441[2] Issued for the model year · Accessories
25 Nov 2021	Transport Canada recall 2021725[2] Issued for the model year · Structure
23 Nov 2022	Transport Canada recall 2022669[2] Issued for the model year · Visual system
4 Jun 2026	Transport Canada recall 2026275[2] Issued for the model year · Structure
9 Nov 2026	Listed for sale, Boucherville, QC[5] Honda De Boucherville · asking $25,800
29 Nov 2026	Listing last updated[5] asking $25,800

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 12 live listings, as of 29 Nov 2026

[5] Live public dealer listings on Cardog, as of 29 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.