Register entry, as of 28 October 2026 Listed for sale Record ID 937305ea6d3f

2017 Acura MDX NAVI

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5FR	YD4H4	1	H	B	505532
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Acura · AMERICAN HONDA…	MDX · 3.5 L	Verified	2017	Lincoln	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.5 L, 6 cylinders
Make	Acura	Fuel	Gasoline
Model	MDX	Drive	4WD
Trim	NAVI	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sport Utility Vehicle	Plant	Lincoln, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/acura/mdx/2017

4 recalls listed by Transport Canada for this model year

Structure

2026275 4 Jun 2026

Issue: On certain vehicles, the suspension mounting points on the rear subframe could rust. As a result, rear suspension components could fail. This could lead to poor handling and a loss of vehicle control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and install a rear subframe reinforcement kit or replace the subframe, as necessary.

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Lights and instruments

2025212 17 Apr 2025

Issue: On certain vehicles, the recall repairs completed by a Honda or Acura dealer during recall AL65/AL66 (Transport Canada recall no. 2019-159) may not have been effective. As a result, a second repair is required. On certain vehicles, water could enter the tail lamps on the tailgate and cause a short circuit. As a result, the fuse could blow and cause a complete loss of rear lighting. Note: This recall replaces recall AL65/AL66 (Transport Canada recall no. 2019-159). Vehicles that previously had a fuse harness installed under that recall do not require this repair. Safety Risk: A loss of rear lighting could make the vehicle less visible and increase the risk of a crash. Corrective Actions: Acura will notify owners by mail and advise you to take your vehicle to a dealership to install a fuse harness. The dealer will also inspect and, if necessary, replace the tail lamps on the tailgate and repair the body dust sealer.

Lights and instruments

2019159 28 Mar 2019

This recall was replaced by Transport Canada recall no. 2025-212. Issue: On certain vehicles, water could enter the tail lamps located on the tailgate. This could cause the tail lamps not to work properly. This could also cause a fuse to blow, which could result in a complete loss of rear lighting. Safety Risk: A loss of rear lighting could make the vehicle less visible and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to inspect the tailgate lid lamps. If either lamp is not working, the dealer will replace both lamps and inspect/replace the fuse. If both tailgate lid lamps are working, the dealer will modify the lamps, and install updated gaskets and wiring.

Listed for the model year, not checked against your VIN. Acura confirms which apply.
Check your VIN with Acura Canada or call a Acura dealer with your VIN.
www.acura.ca/en/recalls

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $17,995[5], $4,701 under the median of $22,696[4].



Lowest ask	$12,999
Middle half	$18,937 – $29,124
Median ask	$22,696
This car	$17,995

Same configuration · 20 live listings · as of 28 Oct 2026

OTHER 2017 ACURA MDX LISTINGS [5]

Saint John, NB · 176,624 km	$18,995
Toronto, ON · 181,195 km	$18,995
Antigonish, NS · 176,624 km	$18,995
Sarnia, ON · 152,984 km	$20,599
Brampton, ON · 167,833 km	$19,990
Sarnia, ON · 152,984 km	$20,599

§4 EVENTS

2017	Model year 2017[1] Assembly plant Lincoln, Alabama, United States
28 Mar 2019	Transport Canada recall 2019159[2] Issued for the model year · Lights and instruments
17 Apr 2025	Transport Canada recall 2025212[2] Issued for the model year · Lights and instruments
21 May 2026	Transport Canada recall 2026251[2] Issued for the model year · Seats and restraints
4 Jun 2026	Transport Canada recall 2026275[2] Issued for the model year · Structure

24 Oct 2026 Listed for sale, Toronto, ON[5]
Ryder Auto Sales · asking $17,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 20 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.