Register entry, as of 29 November 2026 Listed for sale Record ID d0dd2fa2fcfd

2010 Buick Enclave CXL

3.6 L, 6 cylinders · FWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5GA	LRBED	6	A	J	198073
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Buick · GENERAL MOTORS…	Enclave · 3.6 L	Verified	2010	Lansing	Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	3.6 L, 6 cylinders
Make	Buick	Fuel	Gasoline
Model	Enclave	Drive	FWD
Trim	CXL	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Lansing, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/enclave/2010

4 recalls listed by Transport Canada for this model year

Structure

2015280 25 Jun 2015

On certain vehicles equipped with a power liftgate system, the gas-filled struts (which help to raise and support the liftgate) may prematurely wear. These vehicles have a Prop Rod Recovery system intended to accomplish a controlled, slow return of the liftgate to the closed position if the liftgate's gas struts are no longer capable of supporting the weight of the liftgate. The vehicle would provide audible warnings and flash the tail lamps to indicate there is a problem. However, the liftgate's Prop Rod Recovery system software may be unable to detect/stop a liftgate with prematurely worn gas struts from falling too quickly after the liftgate is opened. This could allow the liftgate to drop suddenly, placing anyone beneath or near the gate at risk of injury. Correction: Dealers will reprogram the power liftgate actuator motor ECU with a new software and will verify power liftgate operation following the reprogram.

Seats and restraints

2014181 21 May 2014

On certain vehicles, the flexible steel cable that connects the seat belt to the vehicle structure at the front outboard seating positions can fatigue over time and could separate, increasing the risk of injury in a crash. Correction: Dealers will inspect and repair or replace the lap pretensioner, as necessary.

Airbag

2014081 18 Mar 2014

On certain vehicles, side airbag wiring connections could develop high resistance, illuminating the airbag warning light. If the vehicle continues to be operated in this condition, resistance may continue to increase over time and eventually cause the seat side airbags and seat belt pretensioners to not deploy in the event of a crash, which could increase the risk of injury. Correction: Dealers will affect repairs.

Seats and restraints

2010276 16 Aug 2010

On certain vehicles, the second row seat side trim shield may restrict the upward rotation of the safety belt buckle when the seat back is returned to a seating position after being folded flat. If the buckle contacts the seat frame, additional effort is required to return the seat to a seating position. If sufficient force is applied, the buckle cover could be pushed down the strap, exposing and partially depressing the red release button. As a result, the release button will not travel as much as designed when depressed and will appear to be jammed. The buckle cover may have visible damage which may only be cosmetic, but in some cases, the buckle may not latch/unlatch, or may appear to latch when the latch mechanism is not fully engaged. If the latch mechanism is not fully engaged, the safety belt may not restrain the occupant as intended in a crash, which could result in personal injury or death. Correction: Dealers will modify the second row seat side trim shields, inspect the belt buckle and will replace it if damaged.

Listed for the model year, not checked against your VIN. Buick confirms which apply.
Check your VIN with Buick Canada or call a Buick dealer with your VIN.
www.buick.ca/en/ownercenter/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $4,900[5], $1,150 under the median of $6,050[4].



Lowest ask	$2,200
Middle half	$4,225 – $7,899
Median ask	$6,050
This car	$4,900

Same model year · 4 live listings · as of 29 Nov 2026

OTHER 2010 BUICK ENCLAVE LISTINGS [5]

Richmond, BC · 113,478 km	$7,200
Aylmer, ON · 375,000 km	$2,200
High Level, AB · 249,558 km	$9,995

§4 EVENTS

2010	Model year 2010[1] Assembly plant Lansing, Michigan, United States
16 Aug 2010	Transport Canada recall 2010276[2] Issued for the model year · Seats and restraints
18 Mar 2014	Transport Canada recall 2014081[2] Issued for the model year · Airbag
21 May 2014	Transport Canada recall 2014181[2] Issued for the model year · Seats and restraints
25 Jun 2015	Transport Canada recall 2015280[2] Issued for the model year · Structure

26 Nov 2026	Listed for sale, Whitby, ON[5] Whitby Oshawa Honda · asking $4,900
28 Nov 2026	Listing last updated[5] asking $4,900

§5 DOCUMENTS

Window sticker	This VIN reads as model year 1980 or 2010, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 4 live listings, as of 29 Nov 2026

[5] Live public dealer listings on Cardog, as of 29 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.